


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Antonia Leal Carneiro

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-JAIA-219622MbpsVSAT



Satellite (DVB) RX Configuration

Auto start : Enabled

Maria Branchi - MODGOD - 00 167

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

IdxPriSymbRate[Msps]Freq[GHz]ModePopIdSatIdPosSatNameName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176347 GHz
Symbol Rate : 4.883028 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 16.2 dB
Input Power : -33 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -15.7 dBm
ODU Output Power : 31.6 dBm
EIRP
                     : 44.9 dBW
Es/No
                     : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -264 us (281320 us)
Frequency correction: 110 Hz
System Information:
                        : SEE-JAIA-21962
    Name
    Location
                         : JANUARIA - MG
    Contact
    System Up time : 0 days, 00:17:28
CPU Load : 18%
System time(UTC) : 30 October 2017 18:47:39
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:49:f8
Satellite (DVB) : 00:20:0e:10:49:f8
NetAddr
           State MacAddr
    10.212.50.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.212.50.1 with 32 bytes of data:
Reply from 10.212.50.1: bytes=32 time=573ms TTL=56
Reply from 10.212.50.1: bytes=32 time=561ms TTL=56
Reply from 10.212.50.1: bytes=32 time=538ms TTL=56
Reply from 10.212.50.1: bytes=32 time=553ms TTL=56
Reply from 10.212.50.1: bytes=32 time=636ms TTL=56
Reply from 10.212.50.1: bytes=32 time=542ms TTL=56
Reply from 10.212.50.1: bytes=32 time=587ms TTL=56
Reply from 10.212.50.1: bytes=32 time=577ms TTL=56
Reply from 10.212.50.1: bytes=32 time=539ms TTL=56
Reply from 10.212.50.1: bytes=32 time=566ms TTL=56
Ping statistics for 10.212.50.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 538ms, Maximum = 636ms, Average = 567ms
```

Lista de sites acessados:
www.globo.com – ok www.hotmail.com – ok www.google.com – ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Antonia Leal Carneiro Função: Secretaria Identidade: MASP 9396938
Telefone: 38-3622-8087
Horário de funcionamento – 07hrs às 18hrs