

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

Operadora/Cliente Sergio Almeida

GRE/Prodemge: João Antinossi

Responsável/cliente Iverina Ferreira


Consórcio
VSAT-ID
Porta kbps
EMC/Vodanet

SEE-SAOES-22274

2Mbps

VSAT





dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable * 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176314 GHz Symbol Rate : 4.882903 Msps

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.2 dB Input Power : -36 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm

aODU Output Power : 429496720.8 dBm

EIRP : 4.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -14.8 dBm ODU Output Power : 35.0 dBm

EIRP : 48.3 dBW Es/No : 15.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -230 us (281267 us)

Frequency correction: 70 Hz

arp show

NetAddr State MacAddr If 10.213.73.2 Dynamic 00200E1054C2 1

device show

System Information:

Name : SEE-SAOES-22274

Location : S\overline{\text{S}\overline{\text{O}}\overline{\text{O}}\overline{\text{o}}\overline{\text{d}}\overline{\text{S}\overline{\text{C}}\overline{\text{O}}\ov

Contact :

System Up time : 0 days, 00:19:35

CPU Load : 12%

System time(UTC) : 31 October 2017 20:25:18

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:54:c2 Satellite (DVB) : 00:20:0e:10:54:c2

Pinging 10.213.73.1 with 32 bytes of data:

```
Reply from 10.213.73.1: bytes=32 time=557ms TTL=56 Reply from 10.213.73.1: bytes=32 time=570ms TTL=56 Reply from 10.213.73.1: bytes=32 time=537ms TTL=56 Reply from 10.213.73.1: bytes=32 time=563ms TTL=56 Reply from 10.213.73.1: bytes=32 time=551ms TTL=56 Reply from 10.213.73.1: bytes=32 time=524ms TTL=56 Reply from 10.213.73.1: bytes=32 time=546ms TTL=56 Reply from 10.213.73.1: bytes=32 time=583ms TTL=56 Reply from 10.213.73.1: bytes=32 time=582ms TTL=56 Reply from 10.213.73.1: bytes=32 time=582ms TTL=56 Reply from 10.213.73.1: bytes=32 time=549ms TTL=56
```

Ping statistics for 10.213.73.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 524ms, Maximum = 583ms, Average = 556ms www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

| Responsável | Iverina Ferreira |
|---------------|------------------|
| Cargo | Diretora |
| Identidade | 10080232 |
| Telefone | 038-9-9814-9668 |
| Funcionamento | 07:00 até 17:00 |