


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Adenisio Mendes Souza

> Porta kbps Consórcio **VSAT-ID** Plataforma EMC/Vodanet SEE-IBTU-22120 2Mbps **VSAT**



Satellite (DVB) RX Configuration \_\_\_\_\_

: Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176283 GHz : 4.882993 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.2 dB Input Power : -43 dBm

```
Satellite (DVB) TX Configuration
 _____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                     : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -6.4 dBm
ODU Output Power : 33.5 dBm
EIRP
                     : 46.8 dBW
Es/No
                     : 15.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -419 us (281330 us)
Frequency correction: 40 Hz
System Information:
    Name
                         : SEE-IBTU-22120
    Location
                         : IBIRACATU - MG
    Contact
    System Up time : 0 days, 00:23:03

CPU Load : 16%

System time(UTC) : 26 October 2017 12:42:39
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                         : 120033
                         : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:58:b7
Satellite (DVB) : 00:20:0e:10:58:b7
             State MacAddr
   10.212.173.2 Dynamic 64:1c:67:62:2e:12
Pinging 10.212.173.1 with 32 bytes of data:
Reply from 10.212.173.1: bytes=32 time=542ms TTL=56
Reply from 10.212.173.1: bytes=32 time=554ms TTL=56
Reply from 10.212.173.1: bytes=32 time=544ms TTL=56
Reply from 10.212.173.1: bytes=32 time=532ms TTL=56
Reply from 10.212.173.1: bytes=32 time=558ms TTL=56
Reply from 10.212.173.1: bytes=32 time=556ms TTL=56
Reply from 10.212.173.1: bytes=32 time=545ms TTL=56
Reply from 10.212.173.1: bytes=32 time=580ms TTL=56
Reply from 10.212.173.1: bytes=32 time=553ms TTL=56
Reply from 10.212.173.1: bytes=32 time=525ms TTL=56
Ping statistics for 10.212.173.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 580ms, Average = 548ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
<u>www.google.com</u> – ok
<u>www.educacao.mg.gov.br</u> – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Adenisio Mendes Souza Função: Gestor Identidade: MASP 1132530-5
Telefone:
Horário de funcionamento – 07hrs às 22hrs