

# TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

GRE/Prodemge: João Antinossi

Consórcio
EMC/Vodanet

Porta kbps
EMC/Vodanet

SEE-FRTE-22776

SEE-FRTE-22776


SOPERADOR JOÃO Gustavo

Responsável/cliente Rejiane Cristina Almeida

Porta kbps
SEE-FRTE-22776

Porta kbps
VSAT





#### SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

# dvb rx show

### $Satellite\ (DVB)\ RX\ Configuration$

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

#### Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176674 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

 $Roll \ off \qquad : 0.20$ 

**SNR** : 15.6 dB Input Power : -36 dBm

# dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm : 46.5 dBW

Default CW Frequency: 0.000000 GHz

: VC-Mux ATM mode Header Compression: UDP/IP

#### Satellite (DVB) Transmitter Status

: On (DVB-RCS2) State IDU Output Power : -20.6 dBm ODU Output Power : 33.3 dBm : 46.6 dBW **EIRP** Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -452 us (281581 us)

Frequency correction: 40 Hz

#### # arp show

State MacAddr NetAddr 10.214.84.2 Dynamic b4:99:ba:00:92:6b 1

# device show **System Information:** 

> : SEE-FRTE-22776 Name : Fruta de Leite - MG Location

Contact

System Up time : 0 days, 00:22:09 CPU Load : 16%

System time(UTC) : 13 November 2017 20:27:20

Broadcast Message : not set

#### HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.1

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:49:f0 Satellite (DVB) : 00:20:0e:10:49:f0

#### Pinging 10.214.84.1 with 32 bytes of data:

Reply from 10.214.84.1: bytes=32 time=537ms TTL=56 Reply from 10.214.84.1: bytes=32 time=537ms TTL=56 Reply from 10.214.84.1: bytes=32 time=545ms TTL=56 Reply from 10.214.84.1: bytes=32 time=560ms TTL=56 Reply from 10.214.84.1: bytes=32 time=590ms TTL=56 Reply from 10.214.84.1: bytes=32 time=506ms TTL=56 Reply from 10.214.84.1: bytes=32 time=563ms TTL=56 Reply from 10.214.84.1: bytes=32 time=530ms TTL=56 Reply from 10.214.84.1: bytes=32 time=538ms TTL=56 Reply from 10.214.84.1: bytes=32 time=524ms TTL=56

Ping statistics for 10.214.84.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 506ms, Maximum = 590ms, Average = 523ms

### www.yahoo.com.br

#### www.hotmail.com

## www.google.com

# www.prodemge.gov.br

Responsável	Rejiane Cristina Almeida
Cargo	Diretora
Identidade	636469-9
Telefone	038-9-9926-6643
Funcionamento	07:00-17:00