


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: João Gustavo

**GRE/Prodemge:** João Antinossi **Responsável/cliente:** Rosimarcia Pereira de Melo

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-IBTU-221212MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 24/10/2017 22:54:25

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176286 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20

```
: 15.8 dB
Input Power
                    : -28 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS2)
IDU Output Power : -22.7 dBm
ODU Output Power : 33.5 dBm
                    : 46.8 dBW
EIRP
                    : 14.0 dB
Es/No
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -425 us (281372 us)
Frequency correction: 80 Hz
# device show
System Information:
    Name
                        : SEE-IBTU-22121
    Location
                        : ibiracatu - MG
    Contact
    System Up time : 1 day, 13:40:11 CPU Load : 16%
    System time(UTC) : 01 November 2017 13:06:00 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:48:e9
Satellite (DVB) : 00:20:0e:10:48:e9
 Transec not Supported by this device !
# arp show
  NetAddr
                State MacAddr
    10.212.174.2 Dynamic e8:9a:8f:b7:bd:4a 1
#
Pinging 10.212.174.1 with 32 bytes of data:
Reply from 10.212.174.1: bytes=32 time=562ms TTL=56
Reply from 10.212.174.1: bytes=32 time=538ms TTL=56
Reply from 10.212.174.1: bytes=32 time=529ms TTL=56
Reply from 10.212.174.1: bytes=32 time=614ms TTL=56
Reply from 10.212.174.1: bytes=32 time=704ms TTL=56
Reply from 10.212.174.1: bytes=32 time=529ms TTL=56
Reply from 10.212.174.1: bytes=32 time=546ms TTL=56
Reply from 10.212.174.1: bytes=32 time=573ms TTL=56
```

```
Reply from 10.212.174.1: bytes=32 time=550ms TTL=56
Reply from 10.212.174.1: bytes=32 time=538ms TTL=56
Ping statistics for 10.212.174.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
   Minimum = 529ms, Maximum = 704ms, Average = 568ms
```

## Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok <u>www.google.com</u> – ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação: Nome: Rosimarcia Pereira de Melo

Função: Vice Diretora

Masp-107 45487