


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes **Operadora/Cliente: Ederson Martins**

GRE/Prodemge: João Antinossi Responsável/cliente: Jeane Ferreira de Sousa

> Consórcio **VSAT-ID** Porta kbps **Plataforma VSAT** EMC/Vodanet SEE-SACO-22225 2Mbps



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network

: 65281, Prodemge@Vodanet : 12.176145 GHz : 4.883151 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.9 dB SNR : -38 dBm Input Power

```
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                    : On (DVB-RCS2)
State
IDU Output Power : -12.6 dBm
ODU Output Power : 32.9 dBm
EIRP
                    : 46.2 dBW
Es/No
                     : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -172 us (281539 us)
Frequency correction: 110 Hz
# device show
System Information:
   Name
                        : SEE-SACO-22225
    Location
                        : S¦O FRANCISCO - MG
    Contact
    System Up time : 0 days, 00:42:03 CPU Load : 9%
    System time(UTC) : 28 October 2017 14:26:31
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4a:ce
Satellite (DVB) : 00:20:0e:10:4a:ce
# arp show
                State MacAddr
   NetAddr
    10.213.24.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.24.1 with 32 bytes of data:
Reply from 10.213.24.1: bytes=32 time=586ms TTL=56
Reply from 10.213.24.1: bytes=32 time=579ms TTL=56
Reply from 10.213.24.1: bytes=32 time=541ms TTL=56
Reply from 10.213.24.1: bytes=32 time=548ms TTL=56
Reply from 10.213.24.1: bytes=32 time=556ms TTL=56
Reply from 10.213.24.1: bytes=32 time=546ms TTL=56
Reply from 10.213.24.1: bytes=32 time=568ms TTL=56
Reply from 10.213.24.1: bytes=32 time=539ms TTL=56
Reply from 10.213.24.1: bytes=32 time=582ms TTL=56
Reply from 10.213.24.1: bytes=32 time=581ms TTL=56
Ping statistics for 10.213.24.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
```

Minimum = 539ms, Maximum = 586ms, Average = 562ms

Lista de sites acessados:

www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Jeane Ferreira de Sousa

Função: Diretora MASP: 11266038

Telefone: 38-99953-5354

Funcionamento: 07:00 às 22:30h