


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Eduardo Tadra

GRE/Prodemge: João Antinossi Responsável/cliente: Mary dos Santos Pereira

> Porta kbps Consórcio **VSAT-ID** Plataforma EMC/Vodanet SEE-FRAR-22817 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

0 0.0 E 16.667000 11.962753 DVB-S2 2 1 1

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

: 65281, Prodemge@Vodanet : 12.176356 GHz Network

Frequency : 4.883010 Msps Symbol Rate

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 21 16APSK-5/6

: On Pilot Frame length : Shor : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.3 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -14.8 dBm
ODU Output Power : 31.9 dBm
EIRP
                    : 45.2 dBW
Es/No
                    : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -298 us (280718 us)
Frequency correction: 90 Hz
System Information:
    Name
                       : SEE-FRAR-22817
    Location
                        : Frei Gaspar - MG
    Contact
    System Up time : 0 days, 00:39:28 CPU Load : 16%
    System time (UTC) : 13 November 2017 14:49:11
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:63:f4
Satellite (DVB) : 00:20:0e:10:63:f4
    Ethernet (LAN)
NetAddr
            State MacAddr
   10.215.110.2 Dynamic b8:70:f4:6e:b3:ab 1
Pinging 10.215.110.1 with 32 bytes of data:
Reply from 10.215.110.1: bytes=32 time=581ms TTL=56
Reply from 10.215.110.1: bytes=32 time=540ms TTL=56
Reply from 10.215.110.1: bytes=32 time=566ms TTL=56
Reply from 10.215.110.1: bytes=32 time=527ms TTL=56
Reply from 10.215.110.1: bytes=32 time=547ms TTL=56
Reply from 10.215.110.1: bytes=32 time=541ms TTL=56
Reply from 10.215.110.1: bytes=32 time=555ms TTL=56
Reply from 10.215.110.1: bytes=32 time=555ms TTL=56
Reply from 10.215.110.1: bytes=32 time=525ms TTL=56
Reply from 10.215.110.1: bytes=32 time=593ms TTL=56
Ping statistics for 10.215.110.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 593ms, Average = 553ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Mary dos Santos Pereira
Função: Diretora
MASP: 636469-9
Telefone: 33-3512-1131
Francis and a 07,00 \cdot 22,001
Funcionamento: 07:00 às 22:00h