


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

Responsável/cliente: Elvis Maicon Gonçalves Pereira GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-SACO-21971 **VSAT** 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 20/10/2017 13:19:58

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 * 0 0 0 0.0 E

Yes

1 0 0.0 E 16.667000 11.962753 DVB-S2 2 1

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.175980 GHz Frequency Symbol Rate : 4.883040 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.5 dB Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
-----
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -15.3 dBm

ODU Output Power : 33.7 dBm

EIRP
-----
Es/No
                    : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -514 us (281689 us)
Frequency correction: 10 Hz
System Information:
    Name
                        : SEE-SACO-21971
    Location
                        : SÃO FRANCISCO - MG
    Contact
    System Up time : 0 days, 00:19:32 CPU Load : 14%
    System time(UTC) : 20 October 2017 11:56:34
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Eumernet (LAN) : 00:20:0e:10:4a:d6
Satellite (DVB) : 00:20:0e:10:4a:d6
          State MacAddr
    10.212.59.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.212.59.1 with 32 bytes of data:
Reply from 10.212.59.1: bytes=32 time=542ms TTL=56
Reply from 10.212.59.1: bytes=32 time=535ms TTL=56
Reply from 10.212.59.1: bytes=32 time=560ms TTL=56
Reply from 10.212.59.1: bytes=32 time=554ms TTL=56
Reply from 10.212.59.1: bytes=32 time=566ms TTL=56
Reply from 10.212.59.1: bytes=32 time=593ms TTL=56
Reply from 10.212.59.1: bytes=32 time=565ms TTL=56
Reply from 10.212.59.1: bytes=32 time=568ms TTL=56
Reply from 10.212.59.1: bytes=32 time=566ms TTL=56
Reply from 10.212.59.1: bytes=32 time=624ms TTL=56
Ping statistics for 10.212.59.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 624ms, Average = 567ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com - ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Elvis Maicon Gonçalves Pereira Função: Vice-Diretor Identidade: MG 15.836.363
Telefone: 38-99945-8544
Horário de funcionamento – 07hrs às 22:30hrs