


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Cunha Operadora/Cliente: Ederson Martins

Responsável/cliente: Soraya Jamel GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-GOES-22806 2048/1024 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 17/11/2017 22:48:26

# dvb rx show

Satellite (DVB) RX Configuration : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 \* 0 0 0 0.0 E Yes 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Symbol Rate : 4.882011 : 4.882011

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
SNR
                   : 16.5 dB
Input Power
                   : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS2)
IDU Output Power : -15.2 dBm
ODU Output Power : 33.0 dBm
EIRP
                    : 46.3 dBW
Es/No
                    : 11.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -144 us (281125 us)
Frequency correction: 50 Hz
# device show
System Information:
              : SEE-GOES-22806
   Name
                        : GOVERNADOR VALADARES
    Location
    Contact
                       :
   System Up time : 0 days, 00:43:58 CPU Load : 30%
    System time (UTC) : 17 November 2017 21:47:20
    Broadcast Message : not set
HW:
                       : SatLink 2000
   Model
    HW ID
                       : 120033
                       : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4f:7f
Satellite (DVB) : 00:20:0e:10:4f:7f
# arp show
             State MacAddr
                                            Ιf
   10.214.220.2 Dynamic b8:70:f4:6e:b3:ab 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -n 15 10.214.220.1
Pinging 10.214.220.1 with 32 bytes of data:
Reply from 10.214.220.1: bytes=32 time=531ms TTL=56
Reply from 10.214.220.1: bytes=32 time=528ms TTL=56
Reply from 10.214.220.1: bytes=32 time=526ms TTL=56
Reply from 10.214.220.1: bytes=32 time=568ms TTL=56
Reply from 10.214.220.1: bytes=32 time=581ms TTL=56
Reply from 10.214.220.1: bytes=32 time=530ms TTL=56
Reply from 10.214.220.1: bytes=32 time=528ms TTL=56
Reply from 10.214.220.1: bytes=32 time=545ms TTL=56
```

```
Reply from 10.214.220.1: bytes=32 time=531ms TTL=56
Reply from 10.214.220.1: bytes=32 time=565ms TTL=56
Reply from 10.214.220.1: bytes=32 time=555ms TTL=56
Reply from 10.214.220.1: bytes=32 time=805ms TTL=56
Reply from 10.214.220.1: bytes=32 time=561ms TTL=56
Reply from 10.214.220.1: bytes=32 time=570ms TTL=56
Reply from 10.214.220.1: bytes=32 time=570ms TTL=56
Reply from 10.214.220.1: bytes=32 time=557ms TTL=56

Ping statistics for 10.214.220.1:
    Packets: Sent = 15, Received = 15, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 526ms, Maximum = 805ms, Average = 565ms
```

## Lista de sites acessados:

www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
www.prodemge.gov.br - ok

Nome do responvavel : helena aparecida camargo

telefone: (33) 32772662

cargo: diretora MASP: 886691-5 tecnico: Eduardo Tadra telefone: (11) 9 98331162