

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

Responsável/cliente: JOSÉ DE JESUS MOTA DOS GRE/Prodemge: João Antinossi

SANTOS

Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-TENI-22982 2Mbps **VSAT**



Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 16.667000 11.962753 DVB-S2 2 0 0.0 E 1

Yes

Satellite (DVB) Receiver Status _____

Rx State

DVB State

Network

: On : Forward link up : 65281, Prodemge@Vodanet : 12.176617 GHz : 4.883017 ** Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

: On Pilot Frame length : Short
DVB S2 Mode : ACM DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB : -29 dBm Input Power

```
Satellite (DVB) TX Configuration
_____
Auto start
                  : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                   : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-I
IDU Output Power : -13.8 dBm
ODU Output Power : 34.8 dBm
                   : On (DVB-RCS2)
State
EIRP
                   : 48.1 dBW
Es/No
                   : 12.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -225 us (280632 us)
Frequency correction: 130 Hz
System Information:
                      : SEE-TENI-22982
   Name
    Location
                       : TE¦FILO OTONI - MG
    Contact
   System Up time : 0 days, 00:22:39 CPU Load : 8%
                      : 18 November 2017 17:28:48
    System time(UTC)
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
                       : 120033
    HW ID
    Main board ID
                      : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5e:61
Satellite (DVB) : 00:20:0e:10:5e:61
NetAddr
          State MacAddr
   10.215.182.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.215.182.1 with 32 bytes of data:
Reply from 10.215.182.1: bytes=32 time=596ms TTL=56
Reply from 10.215.182.1: bytes=32 time=556ms TTL=56
Reply from 10.215.182.1: bytes=32 time=584ms TTL=56
Reply from 10.215.182.1: bytes=32 time=601ms TTL=56
Reply from 10.215.182.1: bytes=32 time=553ms TTL=56
Reply from 10.215.182.1: bytes=32 time=570ms TTL=56
Reply from 10.215.182.1: bytes=32 time=590ms TTL=56
Reply from 10.215.182.1: bytes=32 time=555ms TTL=56
Reply from 10.215.182.1: bytes=32 time=553ms TTL=56
Reply from 10.215.182.1: bytes=32 time=591ms TTL=56
Ping statistics for 10.215.182.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 553ms, Maximum = 601ms, Average = 574ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok

www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok

Responsável pelo teste de navegação:

Nome: JOSÉ DE JESUS MOTA DOS SANTOS

Função: Professor MASP: 862761-4

Telefone: 33- 9 9804-4089

Funcionamento: 07:00 as 17:00