
prodemge TERMO DE ACEITE TÉCNICO Solicitante: PRODEMGE / SEE NOC/Operadora: Ermínio Junior Operadora/Cliente Jean Polini GRE/Prodemge: João Antinossi Responsável/cliente Rosimar Rocha Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet SEE-PIIS-22199

2Mbps

VSAT



SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable Name

* 0 0 4.883300 12.176420 DVB-S2 104 0.0E

Yes

16.667000 11.962753 DVB-S2 2 0.0E1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176482 GHz Symbol Rate : 4.883011 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 17.3 dB Input Power : -31 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -24.0 dBm ODU Output Power : 33.5 dBm

EIRP : 46.8 dBW Es/No : 13.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -468 us (281810 us)

Frequency correction: 70 Hz

arp show

NetAddr State MacAddr If 10.212.252.2 Dynamic 64:1c:67:62:2e:12 1

device show

System Information:

Name : SEE-PIIS-22199 Location : PINT POLIS - MG

Contact :

System Up time : 0 days, 00:06:50

CPU Load : 23%

System time(UTC) : 07 November 2017 13:22:32

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:54:47 Satellite (DVB) : 00:20:0e:10:54:47

#

Pinging 10.212.252.1 with 32 bytes of data:

Reply from 10.212.252.1: bytes=32 time=528ms TTL=56 Reply from 10.212.252.1: bytes=32 time=524ms TTL=56 Reply from 10.212.252.1: bytes=32 time=547ms TTL=56 Reply from 10.212.252.1: bytes=32 time=542ms TTL=56 Reply from 10.212.252.1: bytes=32 time=541ms TTL=56 Reply from 10.212.252.1: bytes=32 time=544ms TTL=56 Reply from 10.212.252.1: bytes=32 time=532ms TTL=56 Reply from 10.212.252.1: bytes=32 time=531ms TTL=56 Reply from 10.212.252.1: bytes=32 time=572ms TTL=56 Reply from 10.212.252.1: bytes=32 time=572ms TTL=56 Reply from 10.212.252.1: bytes=32 time=584ms TTL=56

Ping statistics for 10.212.252.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds:

Minimum = 524ms, Maximum = 584ms, Average = 564ms

www.globo.com

www.yahoo.com.br

www.hotmail.com www.google.com

www.prodemge.gov.br

Responsável	Rosimar Rocha
Cargo	Diretora
Identidade	976917-5
Telefone	038-9-9959-9240
Funcionamento	07:00 `as 17:00