


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

GRE/Prodemge: João Antinossi Responsável/cliente: Cilene Araujo Santos Gomes

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet **VSAT SEE-SAES-22259** 2Mbps



Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet : 12.176085 GHz : 4.883081 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.1 dB Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                   : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-I
IDU Output Power : -13.7 dBm
ODU Output Power : 34.5 dBm
                    : On (DVB-RCS2)
State
EIRP
                    : 47.5 dBW
Es/No
                    : 15.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -333 us (281240 us)
Frequency correction: 150 Hz
System Information:
                   : SEE-SAES-22259
   Name
    Location
                        : SÃO JOÃO DAS MISSÕES - MG
    Contact
   System Up time : 0 days, 00:24:10 CPU Load : 23%
    System time (UTC) : 26 October 2017 17:04:33
    Broadcast Message : not set
HW:
                       : SatLink 2000
    Model
                       : 120033
    HW ID
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4a:6e
Satellite (DVB) : 00:20:0e:10:4a:6e
NetAddr
          State MacAddr
    10.213.58.2 Dynamic e8:9a:8f:b7:bd:4a
Pinging 10.213.58.1 with 32 bytes of data:
Reply from 10.213.58.1: bytes=32 time=540ms TTL=56
Reply from 10.213.58.1: bytes=32 time=533ms TTL=56
Reply from 10.213.58.1: bytes=32 time=541ms TTL=56
Reply from 10.213.58.1: bytes=32 time=544ms TTL=56
Reply from 10.213.58.1: bytes=32 time=585ms TTL=56
Reply from 10.213.58.1: bytes=32 time=550ms TTL=56
Reply from 10.213.58.1: bytes=32 time=569ms TTL=56
Reply from 10.213.58.1: bytes=32 time=571ms TTL=56
Reply from 10.213.58.1: bytes=32 time=539ms TTL=56
Reply from 10.213.58.1: bytes=32 time=557ms TTL=56
Ping statistics for 10.213.58.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 533ms, Maximum = 585ms, Average = 552ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok <u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Cilene Araujo Santos Gomes
Função: Vice-Diretora
Identidade:
Telefone: 31-99971-5746
Horário de funcionamento – 07:00 as 17:00