


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Carlos

GRE/Prodemge: João Antinossi Responsável/cliente: Admilson Alves Pereira

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-ICAS-22129 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 24/10/2017 14:55:55

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176025 GHz Frequency Symbol Rate : 4.883020 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.8 dB Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
 _____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.4 dBm
EIRP
                    : 46.4 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -13.0 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.1 dBW
Es/No
                    : 12.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -418 us (281763 us)
Frequency correction: 100 Hz
System Information:
   Name
                        : SEE-ICAS-22129
                        : ICARAÍ DE MINAS - MG
    Location
    Contact
    System Up time : 0 days, 00:23:57 CPU Load : 19%
    System time (UTC) : 24 October 2017 13:59:45
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
                        : 120026 R6.1
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:48:cf
Satellite (DVB) : 00:20:0e:10:48:cf
             State MacAddr
   10.212.182.2 Dynamic 54:04:a6:8e:d3:f6
Pinging 10.212.182.1 with 32 bytes of data:
Reply from 10.212.182.1: bytes=32 time=607ms TTL=56
Reply from 10.212.182.1: bytes=32 time=528ms TTL=56
Reply from 10.212.182.1: bytes=32 time=543ms TTL=56
Reply from 10.212.182.1: bytes=32 time=540ms TTL=56
Reply from 10.212.182.1: bytes=32 time=545ms TTL=56
Reply from 10.212.182.1: bytes=32 time=545ms TTL=56
Reply from 10.212.182.1: bytes=32 time=543ms TTL=56
Reply from 10.212.182.1: bytes=32 time=542ms TTL=56
Reply from 10.212.182.1: bytes=32 time=527ms TTL=56
Reply from 10.212.182.1: bytes=32 time=534ms TTL=56
Ping statistics for 10.212.182.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 527ms, Maximum = 607ms, Average = 545ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
<u>www.educacao.mg.gov.br</u> – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação: Nome: Admilson Alves Pereira Função: Diretor Identidade: MASP 1136769.5
Telefone: 38-3634-5090
Horário de funcionamento – 07hrs às 22:30hrs