

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Gilvan P de Brito Júnior

Responsável/cliente: GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-SAES-22252 2Mbps VSAT





PRTG Traffic Grapher V6.2.0.907 - 11/2/2017 1:00:32 PM

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdoo

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

30.000000 11.512253 DVB-S2 2 0 0.0 E 1 1

No

Satellite (DVB) Receiver Status \_\_\_\_\_

: On Rx State

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176323 GHz Symbol Rate : 4.882936 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS DVB S2 Stream:

Roll off : 0.20
: 16.1 dB

```
Input Power
                  : -35 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -16.6 dBm
ODU Output Power : 33.1 dBm
EIRP
EIRP
                     : 46.1 dBW
                     : 12.0 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -441 us (281196 us)
Frequency correction: 60 Hz
# device show
System Information:
                    : SEE-SAES-22252
    Name
    Location
                         : S O JO O DAS MISS ES
    Contact
    System Up time : 0 days, 00:04:16 CPU Load : 9%
    System time(UTC) : 02 November 2017 12:48:14 Broadcast Message : not set
HW:
   Model
                        : SatLink 2000
    HW ID
                         : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:8c
Satellite (DVB) : 00:20:0e:10:4c:8c
# arp show
  NetAddr
                State MacAddr
    10.213.51.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.213.51.1 with 32 bytes of data:
Reply from 10.213.51.1: bytes=32 time=561ms TTL=56
Reply from 10.213.51.1: bytes=32 time=548ms TTL=56
Reply from 10.213.51.1: bytes=32 time=541ms TTL=56
Reply from 10.213.51.1: bytes=32 time=832ms TTL=56
Reply from 10.213.51.1: bytes=32 time=559ms TTL=56
Reply from 10.213.51.1: bytes=32 time=564ms TTL=56
Reply from 10.213.51.1: bytes=32 time=521ms TTL=56
Reply from 10.213.51.1: bytes=32 time=529ms TTL=56
Reply from 10.213.51.1: bytes=32 time=573ms TTL=56
Reply from 10.213.51.1: bytes=32 time=550ms TTL=56
Reply from 10.213.51.1: bytes=32 time=560ms TTL=56
Ping statistics for 10.213.51.1:
    Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
```

Minimum = 521ms,	Maximum = 832ms,	Average = 576ms	
		<del>-</del>	

## Lista de sites acessados:

www.globo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação: Nome: VANILDE GONÇALVES DE DEUS ARAUJO

Função: VICE DIRETORA

Masp: 450498-1

Telefone: 38 -9 9826-3840 Funcionamento: 08:00 às 12:00h