

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gustavo de Oliveira

GRE/Prodemge: João Antinossi Responsável/cliente: Ermelindo Pedro da Silva

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-COCI-23185 2Mbps VSAT

Port eth0 on SEE-COCI-23185 (10.214.205.1)



Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

______ Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet

: 65281, 1133 : 12.176373 GHz : 4.882850 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.1 dB Input Power : -41 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -17 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -16.9 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -275 us (281116 us)
Frequency correction: 160 Hz
System Information:
   Name
                        : SEE-COCI-23185
    Location
                         : Coroaci - MG
    Contact
    System Up time : 0 days, 00:36:05 CPU Load : 13%
    System time(UTC) : 04 December 2017 16:00:44
Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:c5
Satellite (DVB) : 00:20:0e:10:4c:c5
NetAddr
             State MacAddr
   10.214.205.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.214.205.1 with 32 bytes of data:
Reply from 10.214.205.1: bytes=32 time=608ms TTL=56
Reply from 10.214.205.1: bytes=32 time=527ms TTL=56
Reply from 10.214.205.1: bytes=32 time=525ms TTL=56
Reply from 10.214.205.1: bytes=32 time=546ms TTL=56
Reply from 10.214.205.1: bytes=32 time=582ms TTL=56
Reply from 10.214.205.1: bytes=32 time=554ms TTL=56
Reply from 10.214.205.1: bytes=32 time=548ms TTL=56
Reply from 10.214.205.1: bytes=32 time=639ms TTL=56
Reply from 10.214.205.1: bytes=32 time=558ms TTL=56
Reply from 10.214.205.1: bytes=32 time=629ms TTL=56
Ping statistics for 10.214.205.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 639ms, Average = 571ms
```

Lista de sites acessados:		
www.globo.com – ok		
www.yahoo.com – ok		
www.hotmail.com - ok		
www.google.com – ok		
www.educacao.mg.gov.br – ok		
<u>www.prodemge.gov.br</u> – ok		
Responsável pelo teste de navegação:		
Nome: Ermelindo Pedro da Silva		
Função: Supervisor		
MASP: 882674-5		
Telefone: 33-98897-8517		
Funcionamento: 07:00h às 14:25h		