

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE


NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Guilherme Barbosa Pereira

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-SACO-22222 2Mbps

> > Port eth0 on SEE-SACO-22222 (10.213.21.1)





PRTG Traffic Grapher V6.2.0.907 - 19/10/2017 14:40:55

Satellite (DVB) RX Configuration ______

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 * 0 0 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

: On Rx State

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176476 GHz Frequency Symbol Rate : 4.882988 Msps

S2 ModCod

- receiving : 14 8PSK-3/4 16APSK-5/6 - current max : 21

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS : 0.20 Roll off SNR : 16.9 dB Input Power : -28 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -20.9 dBm
ODU Output Power : 34.6 dBm
EIRP
                     : 47.9 dBW
Es/No
                     : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -428 us (281685 us)
Frequency correction: 20 Hz
System Information:
    Name
                        : SEE-SACO-22222
    Location
                         : SÃO FRANCISCO
    Contact
    System Up time : 0 days, 00:03:37
CPU Load : 15%
System time(UTC) : 19 October 2017 12:49:58
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:59:35
Satellite (DVB) : 00:20:0e:10:59:35
NetAddr
           State MacAddr
    10.213.21.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.21.1 with 32 bytes of data:
Reply from 10.213.21.1: bytes=32 time=536ms TTL=56
Reply from 10.213.21.1: bytes=32 time=527ms TTL=56
Reply from 10.213.21.1: bytes=32 time=566ms TTL=56
Reply from 10.213.21.1: bytes=32 time=566ms TTL=56
Reply from 10.213.21.1: bytes=32 time=569ms TTL=56
Reply from 10.213.21.1: bytes=32 time=570ms TTL=56
Reply from 10.213.21.1: bytes=32 time=553ms TTL=56
Reply from 10.213.21.1: bytes=32 time=569ms TTL=56
Reply from 10.213.21.1: bytes=32 time=537ms TTL=56
Reply from 10.213.21.1: bytes=32 time=553ms TTL=56
Ping statistics for 10.213.21.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 527ms, Maximum = 570ms, Average = 554ms
```

Lista de sites acessados:
www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Guilherme Barbosa Pereira Função: Diretor Identidade: M5713632
Telefone: 38-99920-4679
Horário de funcionamento – 07hrs às 18hrs