



TERMO DE ACEITE TÉCNICO





dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm

ODU Output Power : max

EIRP : max

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -15.7 dBm ODU Output Power : 35.1 dBm

EIRP : 48.4 dBW Es/No : 15.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -356 us (280706 us)

Frequency correction: 90 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176205 GHz Symbol Rate : 4.883001 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.2 dB Input Power : -36 dBm

arp show

NetAddr State MacAddr If 10.212.80.1 Dynamic 00200E1048C7 1

device show

System Information:

Name : SEE-CAHA-22008 Location : CAPELINHA - MG

Contact :

System Up time : 0 days, 18:15:41

CPU Load : 9%

System time(UTC) : 20 October 2017 14:35:08

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.1

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:48:c7

Satellite (DVB) : 00:20:0e:10:48:c7

Transec not Supported by this device!

Pinging 10.212.80.1 with 32 bytes of data:

```
Reply from 10.212.80.1: bytes=32 time=563ms TTL=56 Reply from 10.212.80.1: bytes=32 time=553ms TTL=56 Reply from 10.212.80.1: bytes=32 time=546ms TTL=56 Reply from 10.212.80.1: bytes=32 time=591ms TTL=56 Reply from 10.212.80.1: bytes=32 time=556ms TTL=56 Reply from 10.212.80.1: bytes=32 time=556ms TTL=56 Reply from 10.212.80.1: bytes=32 time=562ms TTL=56 Reply from 10.212.80.1: bytes=32 time=561ms TTL=56 Reply from 10.212.80.1: bytes=32 time=567ms TTL=56 Reply from 10.212.80.1: bytes=32 time=567ms TTL=56 Reply from 10.212.80.1: bytes=32 time=575ms TTL=56
```

Ping statistics for 10.212.80.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 546ms, Maximum = 563ms, Average = 693ms

#

#

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável: Fernanda Nunes de Araujo

Cargo- Vice - Diretora

Identidade:1232695-5

Telefone: 033-3516-5806