

# TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

GRE/Prodemge: João Antinossi Responsável/cliente: Ednalva de Souza Ramos

> Porta kbps Consórcio **VSAT-ID** Plataforma EMC/Vodanet SEE-TAIM-23170 2Mbps **VSAT**

### Port eth0 on SEE-TAIM-23170 (10.214.176.1)



## Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

#### Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 65281, Prodei : 12.176475 GHz Frequency Symbol Rate : 4.883003 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.6 dB SNR Input Power : -30 dBm

```
Satellite (DVB) TX Configuration
 ______
Auto start
                                          : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                                          : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.1 dBm
ODU Output Power : 33.0 dBm
EIRP
                                           : 46.3 dBW
Es/No
                                           : 12.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -249 us (281240 us)
Frequency correction: 170 Hz
System Information:
        Name
                                                  : SEE-TAIM-23170
         Location
                                                    : Tarumirim - MG
         Contact
        System Up time : 0 days, 00:45:36 CPU Load : 15%
         System time(UTC) : 02 December 2017 17:29:28
         Broadcast Message : not set
HW:
        Model
                                                   : SatLink 2000
         HW ID
                                                   : 120033
         Main board ID
                                                  : 120026 R6.2
        converse convence converse converse converse converse converse converse convers
MAC addresses:
        Ethernet (LAN)
NetAddr
                           State MacAddr
       10.214.176.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.214.176.1 with 32 bytes of data:
Reply from 10.214.176.1: bytes=32 time=554ms TTL=56
Reply from 10.214.176.1: bytes=32 time=585ms TTL=56
Reply from 10.214.176.1: bytes=32 time=562ms TTL=56
Reply from 10.214.176.1: bytes=32 time=562ms TTL=56
Reply from 10.214.176.1: bytes=32 time=639ms TTL=56
Reply from 10.214.176.1: bytes=32 time=561ms TTL=56
Reply from 10.214.176.1: bytes=32 time=556ms TTL=56
Reply from 10.214.176.1: bytes=32 time=565ms TTL=56
Reply from 10.214.176.1: bytes=32 time=592ms TTL=56
Reply from 10.214.176.1: bytes=32 time=547ms TTL=56
Ping statistics for 10.214.176.1:
         Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
         Minimum = 547ms, Maximum = 639ms, Average = 572ms
```

# Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Ednalva de Souza Ramos Função: Diretora MASP: 556023-0 Telefone: 33-3233-2029 Funcionamento: 07:00h às 21:30h