


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: João Gustavo F M Sobrinho

GRE/Prodemge: João Antinossi Responsável/cliente: Edilson Francisco de souza

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-NOHA-21949 2Mbps



Satellite (DVB) RX Configuration -----Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency : 12.176287 GHz Symbol Rate : 4.882930 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.9 dB Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -16.1 dBm

ODU Output Power : 34.9 dBm

EIRP
_____
Es/No
                    : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -374 us (280953 us)
Frequency correction: -40 Hz
System Information:
   Name
                       : SEE-NOHA-21949
    Location
                       : NOVA PORTEIRINHA
    Contact
   System Up time : 0 days, 00:17:13 CPU Load : 11%
   System time (UTC) : 18 October 2017 10:28:15
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
                       : 120033
    HW ID
    Main board ID
                       : 120026 R6.2
   MAC addresses:
   Ethernet (LAN)
Pinging 10.212.37.1 with 32 bytes of data:
Reply from 10.212.37.1: bytes=32 time=561ms TTL=56
Reply from 10.212.37.1: bytes=32 time=565ms TTL=56
Reply from 10.212.37.1: bytes=32 time=569ms TTL=56
Reply from 10.212.37.1: bytes=32 time=577ms TTL=56
Reply from 10.212.37.1: bytes=32 time=543ms TTL=56
Reply from 10.212.37.1: bytes=32 time=565ms TTL=56
Reply from 10.212.37.1: bytes=32 time=573ms TTL=56
Reply from 10.212.37.1: bytes=32 time=573ms TTL=56
Reply from 10.212.37.1: bytes=32 time=577ms TTL=56
Reply from 10.212.37.1: bytes=32 time=630ms TTL=56
Ping statistics for 10.212.37.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
   Minimum = 543ms, Maximum = 630ms, Average = 573ms
          State
                    MacAddr
NetAddr
    10.212.37.2 Dynamic b4:99:ba:00:92:6b
```

ista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
Responsável pelo teste de navegação: Nome: Edilson Francisco de souza Função: Diretor MASP: 865196-0 Telefone: 38-99131-8656 Horário de funcionamento da escola: 7:00 as 21:30