



TERMO DE ACEITE TÉCNICO

NOC/Operadora: Ermínio Junior Operadora/Cliente João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente Edinalva Braga Britto

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-INRA-227782MbpsVSAT





SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled

IDU Output Power : -20 dBm

IDU Max Output Power: 0.0 dBm

ODU Output Power : max

EIRP : max

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux

Header Compression: UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)

IDU Output Power : -17.5 dBm

ODU Output Power : 35.1 dBm

EIRP : 48.4 dBW

Es/No : 12.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -319 us (280423 us)

Frequency correction: 130 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Name

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency: 12.176261 GHz

Symbol Rate : 4.882989 Msps

S2 ModCod

- receiving : 21 16APSK-5/6

- current max : 21 16APSK-5/6

Pilot : On

Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20

SNR : 16.1 dB

Input Power : -28 dBm

arp show

NetAddr State MacAddr If

10.214.86.2 Dynamic b4:99:ba:00:92:6b 1

device show

System Information:

Name : SEE-INRA-22778

Location : Indaiabira/MG

Contact :

System Up time : 0 days, 00:18:40

CPU Load : 15%

System time(UTC) : 21 November 2017 15:10:20

Broadcast Message : not set

HW:

Model : SatLink 2000

HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:54:7f

 $Satellite\ (DVB) \hspace{0.5cm} : 00{:}20{:}0e{:}10{:}54{:}7f$

#Pinging 10.214.86.1 with 32 bytes of data:

Reply from 10.214.86.1: bytes=32 time=523ms TTL=56

Reply from 10.214.86.1: bytes=32 time=602ms TTL=56

Reply from 10.214.86.1: bytes=32 time=538ms TTL=56

Reply from 10.214.86.1: bytes=32 time=521ms TTL=56

Reply from 10.214.86.1: bytes=32 time=540ms TTL=56

Reply from 10.214.86.1: bytes=32 time=755ms TTL=56

Reply from 10.214.86.1: bytes=32 time=520ms TTL=56

Reply from 10.214.86.1: bytes=32 time=550ms TTL=56

Reply from 10.214.86.1: bytes=32 time=543ms TTL=56

Reply from 10.214.86.1: bytes=32 time=541ms TTL=56

Ping statistics for 10.214.86.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 520ms, Maximum = 755ms, Average = 563ms

www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.yahoo.com.br

Responsável	Edinalva Braga Britto
Cargo	Vice-diretora
Identidade	556598-1
Telefone	038-9-9935-5292
Funcionamento	07:00-21:40
Onde ficou	Computador da diretoria