


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Eduardo Tadra

Responsável/cliente: Vanild Gonçalves de Deus Araujo GRE/Prodemge: João Antinossi

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet **VSAT** SEE-SACO-22592 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 2/11/2017 18:51:45

18:51

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Bandwidth Traffic IN Bandwidth Traffic OUT

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State

: On : Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency : 12.176409 GHz Symbol Rate : 4.883012 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On : Short : ACM Frame length DVB S2 Mode DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.3 dB SNR

```
Input Power
                  : -34 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.1 dBm
ODU Output Power : 33.2 dBm
EIRP
EIRP
                     : 46.5 dBW
                     : 13.0 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -224 us (281641 us)
Frequency correction: 150 Hz
# device show
System Information:
                    : SEE-SACO-22592
    Name
    Location
                         : Ant nio Dias - MG
    Contact
    System Up time : 0 days, 01:53:44 CPU Load : 4%
    System time(UTC) : 02 November 2017 17:56:00 Broadcast Message : not set
HW:
   Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5d:6c
Satellite (DVB) : 00:20:0e:10:5d:6c
# arp show
                 State MacAddr
                                              Ιf
   10.214.183.2 Dynamic b8:70:f4:6e:b3:ab 1
Pinging 10.214.183.1 with 32 bytes of data:
Reply from 10.214.183.1: bytes=32 time=549ms TTL=56
Reply from 10.214.183.1: bytes=32 time=765ms TTL=56
Reply from 10.214.183.1: bytes=32 time=573ms TTL=56
Reply from 10.214.183.1: bytes=32 time=587ms TTL=56
Reply from 10.214.183.1: bytes=32 time=575ms TTL=56
Reply from 10.214.183.1: bytes=32 time=571ms TTL=56
Reply from 10.214.183.1: bytes=32 time=622ms TTL=56
Reply from 10.214.183.1: bytes=32 time=581ms TTL=56
Reply from 10.214.183.1: bytes=32 time=567ms TTL=56
Reply from 10.214.183.1: bytes=32 time=571ms TTL=56
Ping statistics for 10.214.183.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
```

Minimum = 549ms, Maximum = 765ms, Average = 596ms
Lista de sites acessados:
www.globo.com – ok www.hotmail.com – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok <u>www.prodemge.mg.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Adilson Edson de Miranda Telefone: 31 9 95263127
Função: Diretor Masp: 5661798
Funcionamento: 07:00 às 11:20h