







Blue: MM Red: Tester

No Term
Both Term
USB to Neware
BTS4000 RS-485
Tester

Full Duplex 3MBaud Vo.1 2025



