

ConfigIQ Industrial Inspection Report

Unit ID: CV-102

Status: Corroded

Recommendation: Immediate replacement according to SOP-M-402.