Ly 8086 SIMUlator → MASM.

Dos based Simulation.

1. Install Dos environment for 32. bit.

→ DOSBOX

2. Files for MASM

Ly Extraor the GIE and Sove it on

Colline with the Polder name as 8006.

Ly How to wask with it?

- (1) Open DOSBOX application (Shortout on desktop).
- 2 mount C C:\8086
- 3 C:\
- (A) C:1> edit j.asm > This will open a window for writing Prog.

 (A) + Enter for for Screen

Waite and Save the plag.

- (b) C:1> masm j.asm

 keep 4

 if no ession are there there then.

 (c) C:1> link i.obi
- 6 C:17 link j.obj Reep L
- F C: 1> debug j. exe.

LAB 8086

- 1) Perogram to add two total 16-bit numbers.
- 2) Program to Subtract two 16-64 numbers.
- 3) Program to moraply two 8-bit numbers,
- (3) Mogram -0 D'ivi de.

File

-> be face writing the program you will write about assemble directive,

Masm - installation

Elebs for Ereaning processi.

-> Program win Gowenant.