

WARNING: Do not tamper with the wing nuts.



Do not attempt to tighten or loosen the iUP250 V3 wingnuts shown in the photo. Any changes to the wingnuts will trigger the device's pressure sensor and place the device in an unusable "Decommissioned" state. The device will then have to be returned to Ingenico for recommissioning at the user's expense.