To-Do List Report For Sumobot 2007.PRJPCB

Done	Action Item	Priority	Document	Owner	Category
False	Decouple HIP4081AIBZ VCC and 12V	Normal	•	•	
False	ARef require decoupling?	Normal	-	-	
False	Choose resistor values	Normal	•	-	
False	Sort out duplicated component names	Normal			
False	Add fuse for VBat and maybe 5V?	Normal		-	

March 22, 2007 10:26:19 PM Page 1 of 1