

Drill Number
01
02
03
04
05
06
07
08
09
10
11
12
13
14
15
16
17
18
19
20
0%
20%
40%
60%
80%
100%
Normalized Drilling Sequence (%)
Calibration (holes 1–5)
Transition (retrospective)
Normal — No Alert
Failure-aligned — Alert
Normal — Alert
Failure-aligned — No Alert