
























Sheet: /I2C Active Pullup2/ File: i2c.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.3	Id: 7/10	





Sheet: /Syringe Pump/
File: syrpump.kicad_sch

Title:

Size: A4


Date:

KiCad E.D.A. 10.0.3


Rev:

Id: 10/10

Level shift the calibration signal from 3.3V to 5V



Level shift the bubble detection signal from 5V to 3.3V



Sheet: /Bubble Sensors/
File: bubblesensors.kicad_sch

Title:

Size: A4

Date:

Rev:

KiCad E.D.A. 10.0.3

Id: 12/10

1	2	3	4	5	6
A					A
B					B
C					C
D					D
1	2	3	4	5	6

Subsheet for extra sensors. Add those sensors here, if needed.

Sheet: /Sensors/ File: sensors.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.3		Id: 13/10