










Sheet: /Selector Valves/
File: svalves.kicad_sch

Title:

Size: A4

Date:

KiCad E.D.A. 10.0.3

Rev:


Id: 4/11

1	2	3	4	5	6
A					A
B					B
C					C
D					D
1	2	3	4	5	6

Add extra components here, if needed.

Sheet: /Manual Control/ File: manualctrl.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.3		Id: 5/11


DNP – test signal integrity without the active pullups and populate them if necessary



Sheet: /I2C Active Pullup1/ File: i2c.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.3	Id: 6/11	

DNP – test signal integrity without the active pullups and populate them if necessary

I2C Active Driver
Drive higher capacitive loads
(more devices, longer connectors)
(can DNP IC and use smaller resistors)



Sheet: /I2C Active Pullup2/
File: i2c.kicad_sch

Title:

Size: A4

Date:


KiCad E.D.A. 10.0.3

Rev:

Id: 7/11

DNP – test signal integrity without the active pullups and populate them if necessary

I2C Active Driver
Drive higher capacitive loads
(more devices, longer connectors)
(can DNP IC and use smaller resistors)



Sheet: /I2C Active Pullup/
File: i2c.kicad_sch

Title:


Size: A4

Date:

KiCad E.D.A. 10.0.3

Rev:

Id: 9/11



Sheet: /Syringe Pump/
File: syrpump.kicad_sch

Title:

Size: A4


Date:

KiCad E.D.A. 10.0.3


Rev:

Id: 10/11

Level shift the calibration signal from 3.3V to 5V



Level shift the bubble detection signal from 5V to 3.3V



Sheet: /Bubble Sensors/
File: bubblesensors.kicad_sch

Title:

Size: A4

Date:

Rev:

KiCad E.D.A. 10.0.3

Id: 12/11

1	2	3	4	5	6
A					A
B					B
C					C
D					D
1	2	3	4	5	6

Subsheet for extra sensors. Add those sensors here, if needed.

Sheet: /Sensors/ File: sensors.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.3		Id: 13/11