1. Description


1.1. Project

Project Name	stm32l476-ili9341-example
Board Name	NUCLEO-L476RG
Generated with:	STM32CubeMX 5.3.0
Date	10/12/2019

1.2. MCU

MCU Series	STM32L4
MCU Line	STM32L4x6
MCU name	STM32L476RGTx
MCU Package	LQFP64
MCU Pin number	64

2. Pinout Configuration




3. Pins Configuration

Pin Number LQFP64	Pin Name (function after reset)	Pin Type	Alternate Function(s)	Label
1	VBAT	Power		
2	PC13	I/O	GPIO_EXTI13	B1 [Blue PushButton]
3	PC14-OSC32_IN (PC14)	I/O	RCC_OSC32_IN	
4	PC15-OSC32_OUT (PC15)	I/O	RCC_OSC32_OUT	
5	PH0-OSC_IN (PH0) *	I/O	RCC_OSC_IN	
6	PH1-OSC_OUT (PH1) *	I/O	RCC_OSC_OUT	
7	NRST	Reset		
12	VSSA/VREF-	Power		
13	VDDA/VREF+	Power		
16	PA2	I/O	USART2_TX	USART_TX
17	PA3	I/O	USART2_RX	USART_RX
18	VSS	Power		
19	VDD	Power		
21	PA5 **	I/O	GPIO_Output	LD2 [green Led]
29	PB10 **	I/O	GPIO_Output	LCD_CS
31	VSS	Power		
32	VDD	Power		
41	PA8 **	I/O	GPIO_Output	LCD_RST
46	PA13 (JTMS-SWDIO)	I/O	SYS_JTMS-SWDIO	
47	VSS	Power		
48	VDDUSB	Power		
49	PA14 (JTCK-SWCLK)	I/O	SYS_JTCK-SWCLK	
55	PB3 (JTDO-TRACESWO)	I/O	SPI3_SCK	
56	PB4 (NJTRST) **	I/O	GPIO_Output	LCD_DC
57	PB5	I/O	SPI3_MOSI	
60	воото	Boot		
63	VSS	Power		
64	VDD	Power		

^{**} The pin is affected with an I/O function

^{*} The pin is affected with a peripheral function but no peripheral mode is activated

4. Clock Tree Configuration



Page 4

5. Software Project

5.1. Project Settings

Name	Value		
Project Name	stm32l476-ili9341-example		
Project Folder	D:\projects\STM32-ILI9341\stm32I476-ili9341-example		
Toolchain / IDE	STM32CubeIDE		
Firmware Package Name and Version	STM32Cube FW_L4 V1.14.0		

5.2. Code Generation Settings

Name	Value
STM32Cube MCU packages and embedded software	Copy only the necessary library files
Generate peripheral initialization as a pair of '.c/.h' files	Yes
Backup previously generated files when re-generating	No
Delete previously generated files when not re-generated	Yes
Set all free pins as analog (to optimize the power	No
consumption)	

6. Power Consumption Calculator report

6.1. Microcontroller Selection

Series	STM32L4
Line	STM32L4x6
мси	STM32L476RGTx
Datasheet	025976_Rev4

6.2. Parameter Selection

Temperature	25
Vdd	3.0

7. IPs and Middleware Configuration 7.1. RCC

Low Speed Clock (LSE) : Crystal/Ceramic Resonator

7.1.1. Parameter Settings:

System Parameters:

VDD voltage (V) 3.3
Instruction Cache Enabled
Prefetch Buffer Enabled *
Data Cache Enabled

Flash Latency(WS) 4 WS (5 CPU cycle)

RCC Parameters:

HSI Calibration Value 16
MSI Calibration Value 0

MSI Auto Calibration Disabled
HSE Startup Timout Value (ms) 100
LSE Startup Timout Value (ms) 5000

Power Parameters:

Power Regulator Voltage Scale Power Regulator Voltage Scale 1

7.2. SPI3

Mode: Transmit Only Master 7.2.1. Parameter Settings:

Basic Parameters:

Frame Format Motorola

Data Size 8 Bits *

First Bit MSB First

Clock Parameters:

Prescaler (for Baud Rate) 2

Baud Rate 40.0 MBits/s *

Clock Polarity (CPOL) Low
Clock Phase (CPHA) 1 Edge

Advanced Parameters:

CRC Calculation Disabled

NSSP Mode Enabled

NSS Signal Type Software

7.3. SYS

Debug: Serial Wire

Timebase Source: SysTick

7.4. USART2

Mode: Asynchronous

7.4.1. Parameter Settings:

Basic Parameters:

Baud Rate 115200

Word Length 8 Bits (including Parity)

Parity None Stop Bits 1

Advanced Parameters:

Data Direction Receive and Transmit

Over Sampling 16 Samples
Single Sample Disable

Advanced Features:

Auto Baudrate Disable TX Pin Active Level Inversion Disable RX Pin Active Level Inversion Disable Data Inversion Disable Disable TX and RX Pins Swapping Enable Overrun DMA on RX Error Enable MSB First Disable

^{*} User modified value

8. System Configuration

8.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull down	Max Speed	User Label
RCC	PC14- OSC32_IN (PC14)	RCC_OSC32_IN	n/a	n/a	n/a	
	PC15- OSC32_OU T (PC15)	RCC_OSC32_O UT	n/a	n/a	n/a	
SPI3	PB3 (JTDO- TRACESWO	SPI3_SCK	Alternate Function Push Pull	No pull-up and no pull-down	Very High *	
	PB5	SPI3_MOSI	Alternate Function Push Pull	No pull-up and no pull-down	Very High	
SYS	PA13 (JTMS- SWDIO)	SYS_JTMS- SWDIO	n/a	n/a	n/a	
	PA14 (JTCK- SWCLK)	SYS_JTCK- SWCLK	n/a	n/a	n/a	
USART2	PA2	USART2_TX	Alternate Function Push Pull	No pull-up and no pull-down	Very High	USART_TX
	PA3	USART2_RX	Alternate Function Push Pull	No pull-up and no pull-down	Very High	USART_RX
Single Mapped Signals	PH0- OSC_IN (PH0)	RCC_OSC_IN	n/a	n/a	n/a	
	PH1- OSC_OUT (PH1)	RCC_OSC_OUT	n/a	n/a	n/a	
GPIO	PC13	GPIO_EXTI13	External Interrupt Mode with Falling edge trigger detection	No pull-up and no pull-down	n/a	B1 [Blue PushButton]
	PA5	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Very High	LD2 [green Led]
	PB10	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Very High	LCD_CS
	PA8	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Very High	LCD_RST
	PB4 (NJTRST)	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Very High	LCD_DC

8.2. DMA configuration

nothing configured in DMA service

8.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority	
Non maskable interrupt	true	0	0	
Hard fault interrupt	true	0	0	
Memory management fault	true	0	0	
Prefetch fault, memory access fault	true	0	0	
Undefined instruction or illegal state	true	0	0	
System service call via SWI instruction	true	0	0	
Debug monitor	true	0	0	
Pendable request for system service	true	0	0	
System tick timer	true	0	0	
PVD/PVM1/PVM2/PVM3/PVM4 interrupts through EXTI lines 16/35/36/37/38	unused			
Flash global interrupt	unused			
RCC global interrupt	unused			
USART2 global interrupt	unused			
EXTI line[15:10] interrupts	unused			
SPI3 global interrupt	unused			
FPU global interrupt	unused			

^{*} User modified value

9. Software Pack Report