

Aviation Investigation Final Report

Location: Placerville, California Accident Number: WPR22LA110

Date & Time: February 18, 2022, 17:00 Local Registration: N800SW

Aircraft: AMERICAN LEGEND AIRCRAFT CO
AL11C-100 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, he decided to perform a downwind landing because the setting sun was shining directly down the active runway. During the landing, the airplane veered off track and the main landing gear sustained damage after striking a culvert. The pilot applied engine power and performed a go-around, and during the second landing attempt, the airplane veered off the runway and collided with bushes in the runway drop off. The wings and fuselage were substantially damaged. The pilot reported no preaccidentct mechanical malfunctions or failures with the airframe or engine that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Loss of directional control during landing with a tailwind.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Environmental issues Tailwind - Effect on equipment

Page 2 of 6 WPR22LA110

Factual Information

History of Flight

| Landing-flare/touchdown | Loss of control on ground (Defining event) | |
|-------------------------|--|--|
| Landing-landing roll | Collision with terr/obj (non-CFIT) | |

Pilot Information

| Certificate: | Private | Age: | 84,Male |
|---------------------------|--|-----------------------------------|-------------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Front |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | Airplane | Second Pilot Present: | |
| Instructor Rating(s): | None | Toxicology Performed: | |
| Medical Certification: | Sport pilot None | Last FAA Medical Exam: | |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | November 12, 2020 |
| Flight Time: | 4400 hours (Total, all aircraft), 600 hours (Total, this make and model), 4400 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 0.3 hours (Last 24 hours, all aircraft) | | |

Page 3 of 6 WPR22LA110

Aircraft and Owner/Operator Information

| Aircraft Make: | AMERICAN LEGEND AIRCRAFT CO | Registration: | N800SW |
|-------------------------------|--------------------------------|-----------------------------------|-----------------|
| Model/Series: | AL11C-100 | Aircraft Category: | Airplane |
| Year of Manufacture: | 2005 | Amateur Built: | |
| Airworthiness Certificate: | Special light-sport (Special) | Serial Number: | AL-1013 |
| Landing Gear Type: | Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | June 9, 2021 Annual | Certified Max Gross Wt.: | 1320 lbs |
| Time Since Last Inspection: | 50 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 600 Hrs at time of accident | Engine Manufacturer: | Continental |
| ELT: | C91 installed, not activated | Engine Model/Series: | 0-200 |
| Registered Owner: | On file | Rated Power: | 100 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |
| | | | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | KPVF,2583 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 17:15 Local | Direction from Accident Site: | 160° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 3 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 290° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.23 inches Hg | Temperature/Dew Point: | 14°C / -2°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Placerville, CA | Type of Flight Plan Filed: | None |
| Destination: | Placerville, CA | Type of Clearance: | None |
| Departure Time: | | Type of Airspace: | Class G |

Page 4 of 6 WPR22LA110

Airport Information

| Airport: | PLACERVILLE PVF | Runway Surface Type: | Asphalt |
|----------------------|-----------------|----------------------------------|-----------|
| Airport Elevation: | 2585 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 5 | IFR Approach: | None |
| Runway Length/Width: | 3914 ft / 76 ft | VFR Approach/Landing: | Full stop |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|--------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 38.724227,-120.7533(est) |

Page 5 of 6 WPR22LA110

Administrative Information

| Investigator In Charge (IIC): | Simpson, Eliott |
|--------------------------------------|--|
| Additional Participating Persons: | Pierre T Makhoul; Federal Aviation Administration FSDO; Sacramento, CA |
| Original Publish Date: | July 13, 2022 |
| Last Revision Date: | |
| Investigation Class: | Class 4 |
| Note: | The NTSB did not travel to the scene of this accident. |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=104704 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR22LA110