

LiPo Battery Charging Guide

1. Connect the charger to the power socket. Connect the balancer cable and then the charger cable. Lastly, pack the LiPo into the **Safe Bag!**



2. Press **Enter** to select program.





4. Set the current to **5.0A** using the + and – buttons and confirm with **Enter**.



5. Set the voltage to **7.4V (2S)** using the **+** and **–** buttons and confirm with **Enter**.



6. Press and hold **Enter** to launch the program.



7. Confirm the setup and start the program with **Enter**.



8. The charging process is running.



9. When the LiPo battery is fully charged, a loud beep will sound.



