




$$m = \frac{137.75 - 104}{100 - 14} \frac{\Omega}{^\circ\text{C}} = 0.3324$$

$$m_{\text{ideal}} = \frac{142.75 - 100}{100 - 6} \frac{\Omega}{^\circ\text{C}} = 0.4548$$

$$\Delta m = m - m_{\text{ideal}} = 0.06 \frac{\Omega}{^\circ\text{C}}$$

$$\Rightarrow m = (0.39 \pm 0.06) \frac{\Omega}{^\circ\text{C}}$$