
1. A jet engine is traveling through the air with the forward velocity of 300 m/s. The exhaust gases leave the nozzle with an exit velocity of 800 m/s with respect to the nozzle. If the mass flow rate through the engine is $10~\rm kg/s$, determine the jet engine thrust. The exit plane static pressure is $80~\rm kPa$, inlet plane static pressure is $20~\rm kPa$, ambient pressure surrounding the engine is $20~\rm kPa$, and the exit plane area is $4.0~\rm m^2$.

Solution:

$$\begin{cases} V_{\infty} = 300 \frac{m}{s} \\ V_{e} = 800 \frac{m}{s} \\ P_{e} = 80 \text{kPa} \\ P_{\text{atm}} = 20 \text{kPa} \\ A_{e} = 4 \text{ m}^{2} \\ \dot{m} = 10 \frac{\text{kg}}{\text{s}} \end{cases}$$

$$\begin{split} \mathsf{T} &= \dot{\mathsf{m}} \mathsf{V}_{\varepsilon} - \dot{\mathsf{m}} \mathsf{V}_{\infty} + \mathsf{A}_{\varepsilon} (\mathsf{P}_{\varepsilon} - \mathsf{P}_{\mathsf{atm}}) \\ & \therefore \mathsf{T} = 245 \mathsf{kN} \end{split}$$

2. Describe the differences between Brayton Cycle and a Real Gas Turbine Cycle. Make diagrams to explain the losses associated with a real engine.



The first losses occur in the compressor from stage 1->2 due to the flow not being reversible. The combustion process is not completely isobaric. The process in the turbine is also not reversible.

3. Find all eigenvalues and eigenfunctions for the equation: $\phi'' + \lambda \phi = 0$ with $\phi(0) = 0$ and $\phi'(\pi) = 0$.

Solution:

4. Solve

$$\begin{cases} \frac{\partial^2}{\partial t^2} u = \frac{\partial^2}{\partial x^2} u \\ u(0,t) = u(\pi,t) = 0 \\ u(x,0) = f(x), \frac{\partial}{\partial t} u(x,0) = 0, \end{cases}$$

where f(x) is the "hat function": it's 0 and 0 and π and 1 and $\pi/2$ and linear in between.

Solution:

5. This is another perspective on the SOV method. Consider the problem

$$\begin{cases} \frac{\partial}{\partial t} u = \frac{\partial^2}{\partial x^2} u \\ u(0,t) = u(\pi,t) = 0 \\ u(x,0) = g(x) \end{cases}.$$

For each fixed x, assume that the solution can be written as $\sum_{k=1}^{\infty} B_k \sin(kx)$. Note that the B_k depend on t so a better way to write it is $\sum_{k=1}^{\infty} B_k(t) \sin(kx)$. Starting from this point, find the SOV solution. (Note: I had a typo that said $B_k(x)$ before; it should be $B_k(t)$ SORRY!!)

Solution: Plugging the function into the PDE we get:

$$\begin{split} \sum_{k=1}^{\infty} B_k'(t) \sin kx &= \sum_{k=1}^{\infty} B_k(t) \frac{d^2}{dx^2} \sin kx \\ &= \sum_{k=1}^{\infty} B_k(t) (-k^2 \sin kx) \\ &= -\sum_{k=1}^{\infty} B_k(t) k^2 \sin kx. \end{split}$$

Subtracting the left from the right:

$$0 = \sum_{k=1}^{\infty} (B_k'(t) + k^2 B_k(t)) \sin kx.$$

Since the $\sin kx$ functions are linearly independent, this implies that for all k, $B_k'(t) = -k^2B_k(t)$. So we get an ODE for B_k and the solution is $B_k(t) = B_k(0)e^{-k^2t}$. To find the values of the constants note that:

$$g(x)=u(x,0)=\sum_{k=1}^{\infty}B_k(0)\sin kx.$$

That is, as before, $B_k(0) = \frac{2}{\pi} \int_0^\pi g(y) \sin ky dy.$