AirBot FR-2 BOM and Assembly Instructions

Bill of Materials:

BOM Level	Part Name	Part Number	Quantity
1	3D Printed Arms	IDL#	4
2	3D Printed Bottom Plate	IDL#	1
3	3D Printed Top Plate	IDL#	1
4	3D Printed Landing Gear	IDL#	4
5	3D printed Hooks	IDL#	2
6	1/4 - 20 X 3 Nylon Bolt	IDL#	8
7	½ - 20 Nylon Nut	IDL#	8

Assembly Instructions:

- 1. Obtain all 3D printed parts
- 2. Clear supports from 3D printed parts
- 3. Obtain all materials from the bill of materials
- 4. Assemble bots....

AirBot FR-2 BOM and Assembly Instructions

Page 2 continued instructions......