Appendix G

Table of Control Chart Constants

n	d_2	d_3	C_4	\overline{X} and R Charts			\overline{X} and S Charts		
				$\overline{A_2}$	D_3	D_4	$\overline{A_3}$	B_3	B_4
2	1.128	0.8525	0.7979	1.880	_	3.267	2.659	_	3.267
3	1.693	0.8884	0.8862	1.023	_	2.574	1.954	_	2.568
4	2.059	0.8798	0.9213	0.729	_	2.282	1.628	_	2.266
5	2.326	0.8798	0.9400	0.577	_	2.114	1.427	_	2.089
6	2.534	0.8480	0.9515	0.483	_	2.004	1.287	0.030	1.970
7	2.704	0.8332	0.9594	0.419	0.076	1.924	1.182	0.118	1.882
8	2.847	0.8198	0.9650	0.373	0.136	1.864	1.099	0.185	1.815
9	2.970	0.8078	0.9693	0.337	0.184	1.816	1.032	0.239	1.761
10	3.078	0.7971	0.9727	0.308	0.223	1.777	0.975	0.284	1.716
11	3.173	0.7873	0.9754	0.285	0.256	1.744	0.927	0.321	1.679
12	3.258	0.7785	0.9776	0.266	0.283	1.717	0.886	0.354	1.646
13	3.336	0.7704	0.9794	0.249	0.307	1.693	0.850	0.382	1.618
14	3.407	0.7630	0.9810	0.235	0.328	1.672	0.817	0.406	1.594
15	3.472	0.7562	0.9823	0.223	0.347	1.653	0.789	0.428	1.572
16	3.532	0.7499	0.9835	0.212	0.363	1.637	0.763	0.448	1.552
17	3.588	0.7441	0.9845	0.203	0.378	1.662	0.739	0.466	1.534
18	3.640	0.7386	0.9854	0.194	0.391	1.607	0.718	0.482	1.518
19	3.689	0.7335	0.9862	0.187	0.403	1.597	0.698	0.497	1.503
20	3.735	0.7287	0.9869	0.180	0.415	1.585	0.680	0.510	1.490
21	3.778	0.7272	0.9876	0.173	0.425	1.575	0.663	0.523	1.477
22	3.819	0.7199	0.9882	0.167	0.434	1.566	0.647	0.534	1.466
23	3.858	0.1759	0.9887	0.162	0.443	1.557	0.633	0.545	1.455
24	3.895	0.7121	0.9892	0.157	0.451	1.548	0.619	0.555	1.445
25	3.931	0.7084	0.9896	0.153	0.459	1.541	0.606	0.565	1.435

Copyright ASTM International, used by permission.