












Production Detail											
Plant	At 0500AM (MBOD)	Average (MBOD)	H2S(PPM)	Stabilizer Bottom	API	WC%	Demulsifier (GPH)	Wash Water (GPM)	Salt (PTB)	BS&W%	RVP(PSIA)
GOSP -	350.00	336.70	26.30	200.00	25.00	16.70	3.00	100.00	3.00	0.05	3.00
GOSP -	335.00	334.60	17.10	201.00	25.00	16.70	4.00	120.00	2.30	0.05	3.00
GOSP -	345.00	346.40	20.70	200.00	25.20	16.70	3.00	120.00	1.90	0.05	3.00

Out of Service Equipments Initial Fault Plant Equipment Date Out of Srv Status **ETC Date** 2025-02-16T18:30:00.000Z 2025-03-03T18:30:00.000Z Abnormal Sound (Defected pully) on EMC-524C Lube Oil Coller of Propane Shut GAS PLANT EM-534C Down Compressor 2025-02-Shut 2025-02-GAS PLANT U-0553 Common Flare System for T&I Activity 08T18:30:00.000Z Down 19T18:30:00.000Z MACC-01 EM-2025-02-2025-03-Shut COGEN Gearbox Overheating 02T18:30:00.000Z 19T18:30:00.000Z 0808H Down 2024-11-30T18:30:00.000Z 2025-04-09T18:30:00.000Z Shut UTILITY/WIP D-981 Raw Water Tank for T&I Activity Down



Highlights

High Priority Items: Complete system upgrade for improved performance. Conduct training sessions for new software deployment. Finalize Q3 performance review and submit reports. Address client

feedback on recent project deliverables.

Safety. Conduct monthly fire drills and safety inspections.Ensure all employees complience training.Update safety protocols in line with new regulations.Install new signage

for emergency exits.

Implement energy-saving initiatives across all departments. Optimize HVAC systems to reduce power consumption. Track and analyze energy usage for cost-saving

opportunities.Upgrade lighting to energy-efficient LED fixtures.

Environment Launch a company-wide recycling program. Reduce paper usage by 30% by transitioning to digital documents. Organize a community clean-up event.