



IP ADDRESS

10.20.7.24

REGISTER

40014

CONTROL SOURCE

LOCAL · MANUAL

HARDWARE TELEMETRY

Connection Status

● ONLINE

Main Power

● OK

LHS Arrows

● FAIL_OPEN

RHS Arrows

● ON

Static Zone 1

● ON

Static Zone 2

● ON

Backup Battery

N/A · NOT FITTED

MANUAL OVERRIDE CONTROL

● LOCAL (MANUAL) — buttons live

commands ND-8104

COMMANDED

1 · LHS CHASE

ACTUALLY EXECUTING

1 · LHS CHASE

● IN SYNC

OPERATOR MODES

0
Arrows OFF

1
LHS Chase

2
RHS Chase

TECHNICIAN MODES · LATCH UNTIL CHANGED

3
Both Chase

4
Solid Left

5
Solid Right

6
Solid All

Per-LED Control



IP ADDRESS

10.20.7.24

REGISTER

40014

CONTROL SOURCE

LOCAL · MANUAL

HARDWARE TELEMETRY

Connection Status

ONLINE

Main Power

OK

LHS Arrows

FAIL_OPEN

RHS Arrows

ON

Static Zone 1

ON

Static Zone 2

ON

Backup Battery

N/A · NOT FITTED

MANUAL OVERRIDE CONTROL

LOCAL (MANUAL) — buttons live

commands ND-8104

COMMANDED

1 · LHS CHASE

ACTUALLY EXECUTING

1 · LHS CHASE

IN SYNC

OPERATOR MODES

0

Arrows OFF

1

LHS Chase

2

RHS Chase

TECHNICIAN MODES · LATCH UNTIL CHANGED

3

Both Chase

4

Solid Left

5

Solid Right

6

Solid All

Per-LED Control

B Azure

#3B9BFF



IP ADDRESS

10.20.7.24

REGISTER

40014

CONTROL SOURCE

LOCAL · MANUAL

HARDWARE TELEMETRY

Connection Status

● ONLINE

Main Power

● OK

LHS Arrows

● FAIL_OPEN

RHS Arrows

● ON

Static Zone 1

● ON

Static Zone 2

● ON

Backup Battery

N/A · NOT FITTED

MANUAL OVERRIDE CONTROL

● LOCAL (MANUAL) — buttons live

commands ND-8104

COMMANDED

1 · LHS CHASE

ACTUALLY EXECUTING

1 · LHS CHASE

● IN SYNC

OPERATOR MODES

0
Arrows OFF

1
LHS Chase

2
RHS Chase

TECHNICIAN MODES · LATCH UNTIL CHANGED

3
Both Chase

4
Solid Left

5
Solid Right

6
Solid All

Per-LED Control

HARDWARE TELEMETRY

Connection Status

ONLINE

Main Power

OK

LHS Arrows

FAIL_OPEN

RHS Arrows

ON

Static Zone 1

ON

Static Zone 2

ON

Backup Battery

N/A · NOT FITTED

MANUAL OVERRIDE CONTROL

LOCAL (MANUAL) — buttons live

commands ND-8104

COMMANDED

1 · LHS CHASE

ACTUALLY EXECUTING

1 · LHS CHASE

IN SYNC

OPERATOR MODES

0
Arrows OFF

1
LHS Chase

2
RHS Chase

TECHNICIAN MODES · LATCH UNTIL CHANGED

3
Both Chase

4
Solid Left

5
Solid Right

6
Solid All

Per-LED Control

D Steel · muted

#7F9BBF