

SOLIDWORKS API (.NET VBA C#) — Reference (89/337): IDrawingDoc (part 6 of 7)

SOLIDWORKS API Documentation (converted from CHM)

IDrawingDoc (part 6 of 7) (Type)

SOLIDWORKS API Help

[Send comments](#) on this topic.

IReorderSheets Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : IReorderSheets Method (IDrawingDoc)

Reorders the drawing sheets per their positions in the input array.

.NET Syntax

Visual Basic (Declaration)

```
Function IReorderSheets( _  
    ByVal SheetCount As System.Integer, _  
    ByRef NewSheetList As System.String _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim SheetCount As System.Integer  
Dim NewSheetList As System.String  
Dim value As System.Boolean
```

```
value = instance.IReorderSheets(SheetCount, NewSheetList)
```

C#

```
System.bool IReorderSheets(  
    System.int SheetCount,  
    ref System.string NewSheetList  
)
```

C++/CLI

```
System.bool IReorderSheets(  
& System.int SheetCount,  
& System.String^% NewSheetList  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

SheetCount

Number of sheets to reorder

NewSheetList

Array of the names of the sheets to reorder

Return Value

True if the sheets are reordered per their position in NewSheetList, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::IReorderSheets](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ReorderSheets Method](#)
[IDrawingDoc::ActivateSheet Method](#)
[IDrawingDoc::EditSheet Method](#)
[IDrawingDoc::GetCurrentSheet Method](#)
[IDrawingDoc::GetEditSheet Method](#)
[IDrawingDoc::GetSheetCount Method](#)
[IDrawingDoc::GetSheetNames Method](#)
[IDrawingDoc::IGetCurrentSheet Method](#)
[IDrawingDoc::IGetSheetNames Method](#)
[IDrawingDoc::SetupSheet4 Method](#)

[ISheet::GetName Method](#)
[ISheet::SetName Method](#)

Availability

SOLIDWORKS 2007 FCS, Revision Number 15.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

IsDetailingMode Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : IsDetailingMode Method (IDrawingDoc)

Gets whether this drawing is in detailing mode.

.NET Syntax

Visual Basic (Declaration)

```
Function IsDetailingMode() As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim value As System.Boolean  
  
value = instance.IsDetailingMode()
```

C#

```
System.bool IsDetailingMode()
```

C++/CLI

```
System.bool IsDetailingMode();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Return Value

True if drawing is in detailing mode, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::IsDetailingMode](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

Availability

SOLIDWORKS 2020 FCS, Revision Number 28.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

IsolateChangedDimensions Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : IsolateChangedDimensions Method (IDrawingDoc)

Isolates changed dimensions.

.NET Syntax

Visual Basic (Declaration)

```
Sub IsolateChangedDimensions()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
  
instance.IsolateChangedDimensions()
```

C#

```
void IsolateChangedDimensions()
```

C++/CLI

```
void IsolateChangedDimensions();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::IsolateChangedDimensions](#).

Example

[Isolate Changed Dimension \(C#\)](#)
[Isolate Changed Dimension \(VB.NET\)](#)
[Isolate Changed Dimension \(VBA\)](#)

Remarks

This method only works with drawings saved in SOLIDWORKS 2012 and later.

To isolate changed dimensions:

1. Call [ISldWorks::SetUserPreferenceToggle](#) and set its UserPreferenceValue argument to swUserPreferenceToggle_e.swUseChangedDimensions and its OnFlag argument to true.
2. Call [IDrawingDoc::IsolateChangedDimensions](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

Availability

SOLIDWORKS 2012 FCS, Revision 20.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

LoadLineStyle Method (IDrawingDoc)

See Also [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : LoadLineStyle Method (IDrawingDoc)

Loads the specified line styles into the current drawing.

.NET Syntax

Visual Basic (Declaration)

```
Function LoadLineStyle( _  
    ByVal StyleFiles As System.String, _  
    ByVal StyleNameList As System.Object, _  
    ByVal ReplaceExisting As System.Boolean _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim StyleFiles As System.String  
Dim StyleNameList As System.Object  
Dim ReplaceExisting As System.Boolean  
Dim value As System.Boolean
```

```
value = instance.LoadLineStyles(StyleFiles, StyleNameList, ReplaceExisting)
```

C#

```
System.bool LoadLineStyles(  
    System.string StyleFiles,  
    System.object StyleNameList,  
    System.bool ReplaceExisting  
)
```

C++/CLI

```
System.bool LoadLineStyles(  
& System.String^ StyleFiles,  
& System.Object^ StyleNameList,  
& System.bool ReplaceExisting  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

StyleFiles

Full pathname of file containing line styles to import

StyleNameList

Array of strings containing style names

ReplaceExisting

True to replace existing styles, false to not

Return Value

True if successful, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::LoadLineStyles](#).

Example

[Manage Drawing Document Line Styles \(C#\)](#)
[Manage Drawing Document Line Styles \(VB.NET\)](#)
[Manage Drawing Document Line Styles \(VBA\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::AddLineStyle Method](#)
[IDrawingDoc::DeleteLineStyle Method](#)
[IDrawingDoc::GetLineStyles Method](#)
[IDrawingDoc::SaveLineStyles Method](#)
[ISldWorks::GetLineStyles Method](#)

Availability

SOLIDWORKS 2011 FCS, Revision Number 19.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

MakeBlockDefinition Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : [MakeBlockDefinition Method \(IDrawingDoc\)](#)

Obsolete. Superseded by [ISketchManager::MakeSketchBlockFromFile](#), [ISketchManager::MakeSketchBlockSelected](#), and [ISketchManager::MakeSketchBlockFromSketch](#).

.NET Syntax

Visual Basic (Declaration)

```
Function MakeBlockDefinition( _  
    ByVal Name As System.String, _  
    ByVal XRefFileName As System.String, _
```

```
ByVal Instance As System.Boolean _  
) As BlockDefinition
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim XRefFileName As System.String  
Dim Instance As System.Boolean  
Dim value As BlockDefinition  
  
value = instance.MakeBlockDefinition(Name, XRefFileName, Instance)
```

C#

```
BlockDefinition MakeBlockDefinition(  
    System.string Name,  
    System.string XRefFileName,  
    System.bool Instance  
)
```

C++/CLI

```
BlockDefinition^ MakeBlockDefinition(  
& System.String^ Name,  
& System.String^ XRefFileName,  
& System.bool Instance  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

XRefFileName

Instance

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::MakeBlockDefinition](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

MakeCustomSymbol Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : MakeCustomSymbol Method (IDrawingDoc)

Obsolete. Superseded by [ISketchManager::MakeSketchBlockFromFile](#), [ISketchManager::MakeSketchBlockSelected](#), and [ISketchManager::MakeSketchBlockFromSketch](#).

.NET Syntax

Visual Basic (Declaration)

```
Sub MakeCustomSymbol()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
  
instance.MakeCustomSymbol()
```

C#

```
void MakeCustomSymbol()
```

C++/CLI

```
void MakeCustomSymbol();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::MakeCustomSymbol](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

MakeCustomSymbol2 Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : MakeCustomSymbol2 Method (IDrawingDoc)

Obsolete. Superseded by [ISketchManager::MakeSketchBlockFromFile](#), [ISketchManager::MakeSketchBlockSelected](#), and [ISketchManager::MakeSketchBlockFromSketch](#).

.NET Syntax

Visual Basic (Declaration)

```
Function MakeCustomSymbol2() As System.Object
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim value As System.Object  
  
value = instance.MakeCustomSymbol2()
```

C#

```
System.object MakeCustomSymbol2()
```

C++/CLI

```
System.Object^ MakeCustomSymbol2();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::MakeCustomSymbol2](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

MakeSectionLine Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : MakeSectionLine Method (IDrawingDoc)

Makes a section line from a set of connected sketch lines.

.NET Syntax

```
Sub MakeSectionLine()
```



```
Dim instance As IDrawingDoc  
instance.MakeSectionLine()
```

```
void MakeSectionLine()
```

```
void MakeSectionLine();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::MakeSectionLine](#).

Remarks

You must create the sketch lines in the drawing view, not on the drawing sheet.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::CreateSectionView Method](#)
[IDrawingDoc::CreateSectionViewAt4 Method](#)
[IDrawingDoc::FlipSectionLine Method](#)
[IDrawingDoc::!CreateSectionViewAt4 Method](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

ModifySurfaceFinishSymbol Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ModifySurfaceFinishSymbol Method (IDrawingDoc)

Modifies the selected surface finish symbol.

.NET Syntax

```
Function ModifySurfaceFinishSymbol( _  
    ByVal SymType As System.Integer, _  
    ByVal LeaderType As System.Integer, _  
    ByVal LocX As System.Double, _  
    ByVal LocY As System.Double, _  
    ByVal LocZ As System.Double, _  
    ByVal LaySymbol As System.Integer, _  
    ByVal ArrowType As System.Integer, _  
    ByVal MachAllowance As System.String, _  
    ByVal OtherVals As System.String, _  
    ByVal ProdMethod As System.String, _  
    ByVal SampleLen As System.String, _  
    ByVal MaxRoughness As System.String, _  
    ByVal MinRoughness As System.String, _  
    ByVal RoughnessSpacing As System.String _  
) As System.Boolean
```



```

Dim instance As IDrawingDoc
Dim SymType As System.Integer
Dim LeaderType As System.Integer
Dim LocX As System.Double
Dim LocY As System.Double
Dim LocZ As System.Double
Dim LaySymbol As System.Integer
Dim ArrowType As System.Integer
Dim MachAllowance As System.String
Dim OtherVals As System.String
Dim ProdMethod As System.String
Dim SampleLen As System.String
Dim MaxRoughness As System.String
Dim MinRoughness As System.String
Dim RoughnessSpacing As System.String
Dim value As System.Boolean

```

```

value = instance.ModifySurfaceFinishSymbol(SymType, LeaderType, LocX, LocY, LocZ, LaySymbol,
ArrowType, MachAllowance, OtherVals, ProdMethod, SampleLen, MaxRoughness, MinRoughness,
RoughnessSpacing)

```

C#

```

System.bool ModifySurfaceFinishSymbol(
    System.int SymType,
    System.int LeaderType,
    System.double LocX,
    System.double LocY,
    System.double LocZ,
    System.int LaySymbol,
    System.int ArrowType,
    System.string MachAllowance,
    System.string OtherVals,
    System.string ProdMethod,
    System.string SampleLen,
    System.string MaxRoughness,
    System.string MinRoughness,
    System.string RoughnessSpacing
)

```

C++/CLI

```

System.bool ModifySurfaceFinishSymbol(
    & System.int SymType,
    & System.int LeaderType,
    & System.double LocX,
    & System.double LocY,
    & System.double LocZ,
    & System.int LaySymbol,
    & System.int ArrowType,
    & System.String^ MachAllowance,
    & System.String^ OtherVals,
    & System.String^ ProdMethod,
    & System.String^ SampleLen,
    & System.String^ MaxRoughness,
    & System.String^ MinRoughness,
    & System.String^ RoughnessSpacing
)

```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

SymType

Symbol type as defined in [swSFSymType_e](#)

LeaderType

Leader type as defined in [swLeaderStyle_e](#)

LocX

X location for symbol

LocY

Y location for symbol

LocZ

Z location for symbol

LaySymbol

Direction of lay as defined in [swSFLaySym_e](#)

ArrowType

Arrowhead type as defined in [swArrowStyle_e](#)

MachAllowance

Material removal allowance

OtherVals

Other roughness values

ProdMethod

Production method/treatment

SampleLen

Sampling length

MaxRoughness

Maximum roughness

MinRoughness

Minimum roughness

RoughnessSpacing

Roughness spacing

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ModifySurfaceFinishSymbol](#).

See Also

[IDrawingDoc Interface](#)

[IDrawingDoc Members](#)

[IModelDocExtension::InsertSurfaceFinishSymbol3 Method](#)

[ISFSymbol Interface](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

NewGtol Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : NewGtol Method (IDrawingDoc)

Creates a new GTol object and returns the pointer to that object.

.NET Syntax

Visual Basic (Declaration)

```
Function NewGtol() As System.Object
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim value As System.Object
```

```
value = instance.NewGtol()
```

C#

```
System.object NewGtol()
```

C++/CLI

```
System.Object^ NewGtol();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Return Value

Newly created GTol

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::NewGtol](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::INewGtol Method](#)

SOLIDWORKS API Help

[Send comments on this topic.](#)

NewNote Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : NewNote Method (IDrawingDoc)

Creates a new note at the selected location.

.NET Syntax

Visual Basic (Declaration)

```
Sub NewNote( _  
    ByVal Text As System.String, _  
    ByVal Height As System.Double _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Text As System.String  
Dim Height As System.Double  
  
instance.NewNote(Text, Height)
```

C#

```
void NewNote(  
    System.string Text,  
    System.double Height  
)
```

C++/CLI

```
void NewNote(  
& System.String^ Text,  
& System.double Height  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Text
Text string for the note
Height
Height of the note in meters

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::NewNote](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::CreateText2 Method](#)
[IDrawingDoc::ICreateText2 Method](#)
[IDrawingDoc::InsertNewNote2 Method](#)
[IDrawingDoc::InsertRevisionSymbol Method](#)
[IDrawingDoc::ICreateCompoundNote Method](#)
[IDrawingDoc::CreateCompoundNote Method](#)

SOLIDWORKS API Help

[Send comments on this topic.](#)

NewSheet Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : NewSheet Method (IDrawingDoc)

Obsolete. Superseded by [IDrawingDoc::NewSheet3](#).

.NET Syntax

Visual Basic (Declaration)

```
Sub NewSheet( _  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Short, _  
    ByVal TemplateIn As System.Short, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Short  
Dim TemplateIn As System.Short  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
  
instance.NewSheet(Name, PaperSize, TemplateIn, Scale1, Scale2)
```

C#

```
void NewSheet(  
    System.string Name,  
    System.short PaperSize,  
    System.short TemplateIn,  
    System.double Scale1,  
    System.double Scale2  
)
```

C++/CLI

```
void NewSheet(  
& System.String^ Name,  
& System.short PaperSize,  
& System.short TemplateIn,  
& System.double Scale1,  
& System.double Scale2  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

PaperSize

TemplateIn

Scale1

Scale2

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::NewSheet](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

NewSheet2 Method (IDrawingDoc)

[See Also](#)[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : NewSheet2 Method (IDrawingDoc)**Obsolete.** Superseded by [IDrawingDoc::NewSheet3](#). .NET Syntax

Visual Basic (Declaration)

```

Function NewSheet2( _
    ByVal Name As System.String, _
    ByVal PaperSize As System.Integer, _
    ByVal TemplateIn As System.Integer, _
    ByVal Scale1 As System.Double, _
    ByVal Scale2 As System.Double, _
    ByVal FirstAngle As System.Boolean, _
    ByVal TemplateName As System.String, _
    ByVal Width As System.Double, _
    ByVal Height As System.Double _
) As System.Boolean

```

Visual Basic (Usage)



```

Dim instance As IDrawingDoc
Dim Name As System.String
Dim PaperSize As System.Integer
Dim TemplateIn As System.Integer
Dim Scale1 As System.Double
Dim Scale2 As System.Double
Dim FirstAngle As System.Boolean
Dim TemplateName As System.String
Dim Width As System.Double
Dim Height As System.Double
Dim value As System.Boolean

```

```

value = instance.NewSheet2(Name, PaperSize, TemplateIn, Scale1, Scale2, FirstAngle, TemplateName,
Width, Height)

```

C#

```

System.bool NewSheet2(
    System.string Name,
    System.int PaperSize,
    System.int TemplateIn,
    System.double Scale1,
    System.double Scale2,
    System.bool FirstAngle,
    System.string TemplateName,
    System.double Width,
    System.double Height
)

```

C++/CLI

```

System.bool NewSheet2(
    & System.String^ Name,
    & System.int PaperSize,
    & System.int TemplateIn,
    & System.double Scale1,
    & System.double Scale2,
    & System.bool FirstAngle,
    & System.String^ TemplateName,
    & System.double Width,
    & System.double Height
)

```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

PaperSize

TemplateIn

Scale1

Scale2

FirstAngle

TemplateName

Width

Height

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::NewSheet2](#).

See Also

[IDrawingDoc Interface](#)

[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments on this topic.](#)

NewSheet3 Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : NewSheet3 Method (IDrawingDoc)

Obsolete. Superseded by [IDrawingDoc::NewSheet4](#).

.NET Syntax

Visual Basic (Declaration)

```
Function NewSheet3( _  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Integer, _  
    ByVal TemplateIn As System.Integer, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double, _  
    ByVal FirstAngle As System.Boolean, _  
    ByVal TemplateName As System.String, _  
    ByVal Width As System.Double, _  
    ByVal Height As System.Double, _  
    ByVal PropertyViewName As System.String _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Integer  
Dim TemplateIn As System.Integer  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
Dim FirstAngle As System.Boolean  
Dim TemplateName As System.String  
Dim Width As System.Double  
Dim Height As System.Double  
Dim PropertyViewName As System.String  
Dim value As System.Boolean
```

```
value = instance.NewSheet3(Name, PaperSize, TemplateIn, Scale1, Scale2, FirstAngle, TemplateName,  
Width, Height, PropertyViewName)
```

C#

```

System.bool NewSheet3(
    System.string Name,
    System.int PaperSize,
    System.int TemplateIn,
    System.double Scale1,
    System.double Scale2,
    System.bool FirstAngle,
    System.string TemplateName,
    System.double Width,
    System.double Height,
    System.string PropertyViewName
)

```

C++/CLI

```

System.bool NewSheet3(
    & System.String^ Name,
    & System.int PaperSize,
    & System.int TemplateIn,
    & System.double Scale1,
    & System.double Scale2,
    & System.bool FirstAngle,
    & System.String^ TemplateName,
    & System.double Width,
    & System.double Height,
    & System.String^ PropertyViewName
)

```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name
Name to be given to the new drawing sheet

PaperSize
Size of paper if using swDwgTemplateNone as defined in [swDwgPaperSizes_e](#)

TemplateIn
Template as defined in [swDwgTemplates_e](#)

Scale1
Scale numerator

Scale2
Scale denominator

FirstAngle
True for first angle projection, false otherwise

TemplateName
Name of custom template with full directory path if TemplateIn is set to swDwgTemplateCustom

Width
Paper width if TemplateIn is set to swDwgTemplateNone or swDwgPapersUserDefined

Height
Paper height if TemplateIn is set to swDwgTemplateNone or swDwgPapersUserDefined

PropertyViewName
Name of the drawing view containing the model custom property values

Return Value

True if drawing sheet creation was successful, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::NewSheet3](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ActivateSheet Method](#)
[IDrawingDoc::EditSheet Method](#)
[IDrawingDoc::GetCurrentSheet Method](#)
[IDrawingDoc::GetSheetCount Method](#)
[IDrawingDoc::GetSheetNames Method](#)
[IDrawingDoc::IGetCurrentSheet Method](#)
[IDrawingDoc::IGetSheetNames Method](#)
[IDrawingDoc::IReorderSheets Method](#)
[IDrawingDoc::ReorderSheets Method](#)
[IDrawingDoc::SetupSheet4 Method](#)
[IDrawingDoc::SheetNext Method](#)
[IDrawingDoc::SheetPrevious Method](#)
[ISheet Interface](#)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : NewSheet4 Method (IDrawingDoc)

Creates a new drawing sheet in this drawing document.

.NET Syntax

Visual Basic (Declaration)

```
Function NewSheet4( _  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Integer, _  
    ByVal TemplateIn As System.Integer, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double, _  
    ByVal FirstAngle As System.Boolean, _  
    ByVal TemplateName As System.String, _  
    ByVal Width As System.Double, _  
    ByVal Height As System.Double, _  
    ByVal PropertyViewName As System.String, _  
    ByVal ZoneLeftMargin As System.Double, _  
    ByVal ZoneRightMargin As System.Double, _  
    ByVal ZoneTopMargin As System.Double, _  
    ByVal ZoneBottomMargin As System.Double, _  
    ByVal ZoneRow As System.Integer, _  
    ByVal ZoneCol As System.Integer _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Integer  
Dim TemplateIn As System.Integer  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
Dim FirstAngle As System.Boolean  
Dim TemplateName As System.String  
Dim Width As System.Double  
Dim Height As System.Double  
Dim PropertyViewName As System.String  
Dim ZoneLeftMargin As System.Double  
Dim ZoneRightMargin As System.Double  
Dim ZoneTopMargin As System.Double  
Dim ZoneBottomMargin As System.Double  
Dim ZoneRow As System.Integer  
Dim ZoneCol As System.Integer  
Dim value As System.Boolean  
  
value = instance.NewSheet4(Name, PaperSize, TemplateIn, Scale1, Scale2, FirstAngle, TemplateName,  
Width, Height, PropertyViewName, ZoneLeftMargin, ZoneRightMargin, ZoneTopMargin, ZoneBottomMargin,  
ZoneRow, ZoneCol)
```

C#

```
System.bool NewSheet4(  
    System.string Name,  
    System.int PaperSize,  
    System.int TemplateIn,  
    System.double Scale1,  
    System.double Scale2,  
    System.bool FirstAngle,  
    System.string TemplateName,  
    System.double Width,  
    System.double Height,  
    System.string PropertyViewName,  
    System.double ZoneLeftMargin,  
    System.double ZoneRightMargin,  
    System.double ZoneTopMargin,
```

```

        System.double ZoneBottomMargin,
        System.int ZoneRow,
        System.int ZoneCol
    )

```

C++/CLI

```

System.bool NewSheet4(
& System.String^ Name,
& System.int PaperSize,
& System.int TemplateIn,
& System.double Scale1,
& System.double Scale2,
& System.bool FirstAngle,
& System.String^ TemplateName,
& System.double Width,
& System.double Height,
& System.String^ PropertyViewName,
& System.double ZoneLeftMargin,
& System.double ZoneRightMargin,
& System.double ZoneTopMargin,
& System.double ZoneBottomMargin,
& System.int ZoneRow,
& System.int ZoneCol
)

```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

Name to be given to the new drawing sheet

PaperSize

Size of paper as defined in [swDwgPaperSizes_e](#); valid only if TemplateIn is swDwgTemplates_e.swDwgTemplateNone

TemplateIn

Template as defined in [swDwgTemplates_e](#)

Scale1

Scale numerator

Scale2

Scale denominator

FirstAngle

True for first angle projection, false for third angle projection

TemplateName

Name of custom template with full directory path; valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateCustom

Width

Paper width; valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateNone or PaperSize is set to swDwgPaperSizes_e.swDwgPapersUserDefined

Height

Paper height; valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateNone or PaperSize is set to swDwgPaperSizes_e.swDwgPapersUserDefined

PropertyViewName

Name of view containing the model from which to get custom property values

ZoneLeftMargin

Zone area left margin; distance from drawing sheet's left edge

ZoneRightMargin

Zone area right margin; distance from drawing sheet's right edge

ZoneTopMargin

Zone area top margin; distance from drawing sheet's top edge

ZoneBottomMargin

Zone area bottom margin; distance from drawing sheet's bottom edge

ZoneRow

Number of zone rows in the zone area of this sheet (see **Remarks**)

ZoneCol

Number of zone columns in the zone area of this sheet (see **Remarks**)

Return Value

True if drawing sheet creation was successful, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::NewSheet4](#).

Example

[Create Drawing Sheet Zones \(VBA\)](#)
[Create Drawing Sheet Zones \(VB.NET\)](#)
[Create Drawing Sheet Zones \(C#\)](#)

Remarks

The drawing sheet can be created with zones that annotations in other views can reference. Each zone is referenced by an alphanumeric label that is defined using the Zone Editor. See the SOLIDWORKS Help for more information about drawing sheet zones.

(ZoneRow x ZoneCol) is the total number of zones in the zone area of this drawing sheet. The zone area is specified by ZoneLeftMargin, ZoneRightMargin, ZoneTopMargin, and ZoneBottomMargin.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ActivateSheet Method \(\)](#)
[IDrawingDoc::EditSheet Method \(\)](#)
[IDrawingDoc::GetCurrentSheet Method \(\)](#)
[IDrawingDoc::GetSheetCount Method \(\)](#)
[IDrawingDoc::GetSheetNames Method \(\)](#)
[IDrawingDoc::ReorderSheets Method \(\)](#)
[IDrawingDoc::SetupSheet6 Method \(\)](#)
[IDrawingDoc::SheetNext Method \(\)](#)
[IDrawingDoc::SheetPrevious Method \(\)](#)
[ISheet Interface](#)
[IDrawingDoc::PasteSheet Method \(\)](#)
[ISheet::GetDrawingZone Method \(\)](#)

Availability

SOLIDWORKS 2015 FCS, Revision Number 23.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

OnComponentProperties Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : OnComponentProperties Method (IDrawingDoc)

Displays the **Component Properties** dialog for the selected view.

.NET Syntax

Visual Basic (Declaration)

```
Sub OnComponentProperties()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
  
instance.OnComponentProperties()
```

C#

```
void OnComponentProperties()
```

C++/CLI

```
void OnComponentProperties();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::OnComponentProperties](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ResolveOutOfDateLightWeightComponents Method](#)
[IDrawingDoc::ChangeComponentLayer Method](#)
[IComponent2 Interface](#)

SOLIDWORKS API Help

[Send comments on this topic.](#)

PasteSheet Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : PasteSheet Method (IDrawingDoc)

Copies and pastes a drawing sheet to the specified location of the drawing document, optionally renaming whenever duplicate names occur.

.NET Syntax

Visual Basic (Declaration)

```
Function PasteSheet( _  
    ByVal InsertOption As System.Integer, _  
    ByVal RenameOption As System.Integer _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim InsertOption As System.Integer  
Dim RenameOption As System.Integer  
Dim value As System.Boolean  
  
value = instance.PasteSheet(InsertOption, RenameOption)
```

C#

```
System.bool PasteSheet(  
    System.int InsertOption,  
    System.int RenameOption  
)
```

C++/CLI

```
System.bool PasteSheet(  
& System.int InsertOption,  
& System.int RenameOption  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

InsertOption

Option as defined in [swInsertOptions_e](#)

RenameOption

Option as defined in [swRenameOptions_e](#); 1 to rename duplicate section, detail or auxiliary view names; 2 to not rename

Return Value

True if successful, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::PasteSheet](#).

Example

[Copy and Paste Drawing Sheet \(C#\)](#)
[Copy and Paste Drawing Sheet \(VB.NET\)](#)
[Copy and Paste Drawing Sheet \(VBA\)](#)

Remarks

Before calling this method, you must:

1. Select a sheet.
2. Call [IModelDoc2::EditCopy](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[ISheet Interface](#)
[IDrawingDoc::ActivateSheet Method](#)
[IDrawingDoc::EditSheet Method](#)
[IDrawingDoc::GetEditSheet Method](#)
[IDrawingDoc::GetSheetCount Method](#)
[IDrawingDoc::GetSheetNames Method](#)
[IDrawingDoc::GetCurrentSheet Method](#)
[IDrawingDoc::IReorderSheets Method](#)
[IDrawingDoc::NewSheet3 Method](#)

[IDrawingDoc::ReorderSheets Method](#)
[IDrawingDoc::SetupSheet5 Method](#)
[IDrawingDoc::SheetNext Method](#)
[IDrawingDoc::SheetPrevious Method](#)
[IDrawingDoc::Sheet Property](#)

Availability

SOLIDWORKS 2011 FCS, Revision Number 19.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

ReorderSheets Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ReorderSheets Method (IDrawingDoc)

Reorders the drawing sheets per their positions in the input array.

.NET Syntax

Visual Basic (Declaration)

```
Function ReorderSheets( _  
    ByVal NewSheetList As System.Object _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim NewSheetList As System.Object  
Dim value As System.Boolean  
  
value = instance.ReorderSheets(NewSheetList)
```

C#

```
System.bool ReorderSheets(  
    System.object NewSheetList  
)
```

C++/CLI

```
System.bool ReorderSheets(  
    & System.Object^ NewSheetList  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

NewSheetList

Array of the names of the sheets to reorder

Return Value

True if the sheets are reordered per their position in NewSheetList, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ReorderSheets](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ReorderSheets Method](#)
[IDrawingDoc::ActivateSheet Method](#)
[IDrawingDoc::EditSheet Method](#)
[IDrawingDoc::GetCurrentSheet Method](#)
[IDrawingDoc::GetEditSheet Method](#)
[IDrawingDoc::GetSheetCount Method](#)
[IDrawingDoc::GetSheetNames Method](#)
[IDrawingDoc::GetCurrentSheet Method](#)
[IDrawingDoc::NewSheet3 Method](#)
[IDrawingDoc::SetupSheet4 Method](#)
[IDrawingDoc::SheetNext Method](#)

Availability

SOLIDWORKS 2007 FCS, Revision Number 15.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

ReplaceViewModel Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ReplaceViewModel Method (IDrawingDoc)

Replaces the specified instances of a model in the specified drawing views.

.NET Syntax

Visual Basic (Declaration)

```
Function ReplaceViewModel( _  
    ByVal NewModelPathName As System.String, _  
    ByVal Views As System.Object, _  
    ByVal Instances As System.Object _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim NewModelPathName As System.String  
Dim Views As System.Object  
Dim Instances As System.Object  
Dim value As System.Boolean  
  
value = instance.ReplaceViewModel(NewModelPathName, Views, Instances)
```

C#

```
System.bool ReplaceViewModel(  
    System.string NewModelPathName,  
    System.object Views,  
    System.object Instances  
)
```

C++/CLI

```
System.bool ReplaceViewModel(  
& System.String^ NewModelPathName,  
& System.Object^ Views,  
& System.Object^ Instances  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

NewModelPathName

Full path and filename of the replacement model

Views

Array of [IViews](#) in which to replace the model

Instances

Array of [IComponent2](#)s that are specific instances of the model to replace in the drawing

Return Value

True if the model is replaced, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ReplaceViewModel](#).

Example

[Replace View Model \(C#\)](#)
[Replace View Model \(VB.NET\)](#)
[Replace View Model \(VBA\)](#)

Remarks

This method corresponds to **Tools > Replace Model**.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::InsertModelInPredefinedView Method \(\)](#)

Availability

SOLIDWORKS 2014 FCS, Revision Number 22.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

ResolveOutOfDateLightWeightComponents Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ResolveOutOfDateLightWeightComponents Method (IDrawingDoc)

Resolves out-of-date lightweight components in the selected drawing view or drawing sheet.

.NET Syntax

Visual Basic (Declaration)

```
Function ResolveOutOfDateLightWeightComponents() As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim value As System.Boolean
```

```
value = instance.ResolveOutOfDateLightWeightComponents()
```

C#

```
System.bool ResolveOutOfDateLightWeightComponents()
```

C++/CLI

```
System.bool ResolveOutOfDateLightWeightComponents();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Return Value

True if out-of-date lightweight components are resolved, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ResolveOutOfDateLightWeightComponents](#).

Remarks

This method also resolves a selected out-of-date lightweight component and any out-of-date lightweight sub-components, in a drawing document.

You must select a drawing view, drawing sheet, or an out-of-date lightweight component before using this method.

If...	Then...
Drawing view is selected	All out-of-date lightweight components in that drawing view are resolved
Drawing sheet is selected	All-out-of-date lightweight components in that drawing sheet are resolved

Out-of-date lightweight component is selected	It and any out-of-date lightweight sub-components are resolved
Your selection is invalid	This method returns false

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IAssemblyDoc::ResolveOutOfDateLightWeightComponents Method](#)
[IComponent2 Interface](#)
[IDrawingDoc::ChangeComponentLayer Method](#)
[IDrawingDoc::OnComponentProperties Method](#)

Availability

SOLIDWORKS 2006 FCS, Revision Number 14.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

RestoreRotation Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : RestoreRotation Method (IDrawingDoc)

Restores rotation for the selected drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Sub RestoreRotation()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
instance.RestoreRotation()
```

C#

```
void RestoreRotation()
```

C++/CLI

```
void RestoreRotation();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::RestoreRotation](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::AlignHorz Method](#)
[IDrawingDoc::AlignVert Method](#)
[IDrawingDoc::DrawingViewRotate Method](#)
[IView Interface](#)

Availability

SOLIDWORKS 99, datecode 1999207

SOLIDWORKS API Help

[Send comments](#) on this topic.

SaveBlock Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SaveBlock Method (IDrawingDoc)

Obsolete. Superseded by [ISketchBlockDefinition::Save](#).

.NET Syntax

Visual Basic (Declaration)

```
Function SaveBlock( _  
    ByVal FileName As System.String _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim FileName As System.String  
Dim value As System.Boolean  
  
value = instance.SaveBlock(FileName)
```

C#

```
System.bool SaveBlock(  
    System.string FileName  
)
```

C++/CLI

```
System.bool SaveBlock(  
& System.String^ FileName  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

FileName

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SaveBlock](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SaveLineStyle Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SaveLineStyle Method (IDrawingDoc)

Exports to a file the specified line styles in the current drawing.

.NET Syntax

Visual Basic (Declaration)

```
Function SaveLineStyle( _  
    ByVal StyleFiles As System.String, _  
    ByVal StyleNameList As System.Object, _  
    ByVal ReplaceExisting As System.Boolean _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim StyleFiles As System.String  
Dim StyleNameList As System.Object
```

```
Dim ReplaceExisting As System.Boolean
Dim value As System.Boolean
```

```
value = instance.SaveLineStyles(StyleFiles, StyleNameList, ReplaceExisting)
```

C#

```
System.bool SaveLineStyles(
    System.string StyleFiles,
    System.object StyleNameList,
    System.bool ReplaceExisting
)
```

C++/CLI

```
System.bool SaveLineStyles(
    & System.String^ StyleFiles,
    & System.Object^ StyleNameList,
    & System.bool ReplaceExisting
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

StyleFiles

Full pathname of file to save line styles to

StyleNameList

Array of strings containing line style names to save

ReplaceExisting

True to replace existing styles in the file, false to not

Return Value

True if successful, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SaveLineStyles](#).

Example

[Manage Drawing Document Line Styles \(C#\)](#)
[Manage Drawing Document Line Styles \(VB.NET\)](#)
[Manage Drawing Document Line Styles \(VBA\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::AddLineStyle Method](#)
[IDrawingDoc::DeleteLineStyle Method](#)
[IDrawingDoc::GetLineStyles Method](#)
[IDrawingDoc::LoadLineStyles Method](#)
[ISldWorks::GetLineStyles Method](#)

Availability

SOLIDWORKS 2011 FCS, Revision Number 19.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetCurrentLayer Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetCurrentLayer Method (IDrawingDoc)

Sets the current layer used by this document.

.NET Syntax

Visual Basic (Declaration)

```
Function SetCurrentLayer( _
    ByVal Layername As System.String _
```

) As System.Boolean

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
Dim Layername As System.String
Dim value As System.Boolean

value = instance.SetCurrentLayer(Layername)
```

C#

```
System.bool SetCurrentLayer(
    System.string Layername
)
```

C++/CLI

```
System.bool SetCurrentLayer(
    & System.String^ Layername
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Layername
Name of the layer

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetCurrentLayer](#).

Remarks

SOLIDWORKS creates subsequent items on the specified layer.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ChangeComponentLayer Method](#)
[IDrawingDoc::CreateLayer Method](#)
[ILayer Interface](#)
[ILayerMgr Interface](#)

Availability

SOLIDWORKS 99, datecode 1999207

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetLineColor Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetLineColor Method (IDrawingDoc)

Sets the line color for a selected edge or sketch entity.

.NET Syntax

Visual Basic (Declaration)

```
Sub SetLineColor( _
    ByVal color As System.Integer _
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
Dim Color As System.Integer

instance.SetLineColor(Color)
```

C#

```
void SetLineColor(
    System.int Color
)
```

C++/CLI

```
void SetLineColor(
    & System.int Color
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Color
Color definition as a COLORREF

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetLineColor](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::GetLineFontCount2 Method](#)
[IDrawingDoc::GetLineFontId Method](#)
[IDrawingDoc::GetLineFontInfo2 Method](#)
[IDrawingDoc::GetLineFontName2 Method](#)
[IDrawingDoc::SetLineWidth Method](#)
[IDrawingDoc::SetLineStyle Method](#)
[IDrawingDoc::SetLineWidthCustom Method](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetLineStyle Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetLineStyle Method (IDrawingDoc)

Sets the style or font for the line for a selected edge or sketch entity.

.NET Syntax

Visual Basic (Declaration)

```
Sub SetLineStyle( _
    ByVal StyleName As System.String _
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
Dim StyleName As System.String

instance.SetLineStyle(StyleName)
```

C#

```
void SetLineStyle(
    System.string StyleName
)
```

C++/CLI

```
void SetLineStyle(  
& System.String^ StyleName  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

StyleName

Style or font for the selected edge or sketch entity as defined in [swLineStyles_e](#)

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetLineStyle](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::GetLineFontCount2 Method](#)
[IDrawingDoc::GetLineFontId Method](#)
[IDrawingDoc::GetLineFontInfo2 Method](#)
[IDrawingDoc::GetLineFontName2 Method](#)
[IDrawingDoc::SetLineColor Method](#)
[IDrawingDoc::SetLineWidth Method](#)
[IDrawingDoc::SetLineWidthCustom Method](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetLineWidth Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetLineWidth Method (IDrawingDoc)

Sets the line thickness for a selected edge or sketch entity to a SOLIDWORKS-supplied weight (width).

.NET Syntax

Visual Basic (Declaration)

```
Sub SetLineWidth(  
    ByVal Width As System.Integer _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Width As System.Integer  
  
instance.SetLineWidth(Width)
```

C#

```
void SetLineWidth(  
    System.int Width  
)
```

C++/CLI

```
void SetLineWidth(  
& System.int Width  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Width

Weight for the line as defined in [swLineWeights_e](#)

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetLineWidth](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::SetLineColor Method](#)
[IDrawingDoc::SetLineStyle Method](#)
[IDrawingDoc::GetLineFontCount2 Method](#)
[IDrawingDoc::GetLineFontId Method](#)
[IDrawingDoc::GetLineFontInfo2 Method](#)
[IDrawingDoc::GetLineFontName2 Method](#)
[IDrawingDoc::SetLineWidthCustom Method](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetLineWidthCustom Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetLineWidthCustom Method (IDrawingDoc)

Sets the line thickness to the specified custom width for a selected edge or sketch entity.

.NET Syntax

Visual Basic (Declaration)

```
Sub SetLineWidthCustom( _  
    ByVal Width As System.Double _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Width As System.Double  
  
instance.SetLineWidthCustom(Width)
```

C#

```
void SetLineWidthCustom(  
    System.double Width  
)
```

C++/CLI

```
void SetLineWidthCustom(  
& System.double Width  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Width
Custom width for the line in meters

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetLineWidthCustom](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::SetLineStyle Method](#)
[IDrawingDoc::SetLineWidth Method](#)
[IDrawingDoc::SetLineColor Method](#)

Availability

SOLIDWORKS 2009 FCS, Revision Number 17.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetSheetsSelected Method (IDrawingDoc)

[See Also](#) [Example](#)



Sets the specified drawing sheets whose setups to modify.

VB.NET Syntax

Visual Basic (Declaration)

```
Sub SetSheetsSelected( _  
    ByVal NewSheetList As System.Object _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim NewSheetList As System.Object  
  
instance.SetSheetsSelected(NewSheetList)
```

C#

```
void SetSheetsSelected(  
    System.object NewSheetList  
)
```

C++/CLI

```
void SetSheetsSelected(  
& System.Object^ NewSheetList  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

NewSheetList
Names of the drawing sheets whose setups to modify (see **Remarks**)

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetSheetsSelected](#).

Example

[Modify Multiple Drawing Sheets Setups \(C#\)](#)
[Modify Multiple Drawing Sheets Setups \(VB.NET\)](#)
[Modify Multiple Drawing Sheets Setups \(VBA\)](#)

Remarks

The first drawing sheet in the drawing is automatically included in NewSheetList and need not be specified.

After calling this method, call [IDrawingDoc::SetupSheet6](#) to specify how to modify the setups of the specified drawing sheets.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

Availability

SOLIDWORKS 2017 FCS, Revision Number 25.0



.NET Syntax

Visual Basic (Declaration)

```
Sub SetupSheet( _  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Short, _  
    ByVal TemplateIn As System.Short, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Short  
Dim TemplateIn As System.Short  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
  
instance.SetupSheet(Name, PaperSize, TemplateIn, Scale1, Scale2)
```

C#

```
void SetupSheet(  
    System.string Name,  
    System.short PaperSize,  
    System.short TemplateIn,  
    System.double Scale1,  
    System.double Scale2  
)
```

C++/CLI

```
void SetupSheet(  
& System.String^ Name,  
& System.short PaperSize,  
& System.short TemplateIn,  
& System.double Scale1,  
& System.double Scale2  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

PaperSize

TemplateIn

Scale1

Scale2

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetupSheet](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)



Obsolete. Superseded by [IDrawingDoc::SetupSheet4](#).

.NET Syntax

Visual Basic (Declaration)

```
Sub SetupSheet2(  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Short, _  
    ByVal TemplateIn As System.Short, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double, _  
    ByVal SkPointsFlag As System.Integer _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Short  
Dim TemplateIn As System.Short  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
Dim SkPointsFlag As System.Integer  
  
instance.SetupSheet2(Name, PaperSize, TemplateIn, Scale1, Scale2, SkPointsFlag)
```

C#

```
void SetupSheet2(  
    System.string Name,  
    System.short PaperSize,  
    System.short TemplateIn,  
    System.double Scale1,  
    System.double Scale2,  
    System.int SkPointsFlag  
)
```

C++/CLI

```
void SetupSheet2(  
& System.String^ Name,  
& System.short PaperSize,  
& System.short TemplateIn,  
& System.double Scale1,  
& System.double Scale2,  
& System.int SkPointsFlag  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

PaperSize

TemplateIn

Scale1

Scale2

SkPointsFlag

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetupSheet2](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetupSheet3 Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetupSheet3 Method (IDrawingDoc)

Obsolete. Superseded by [IDrawingDoc::SetupSheet4](#).

.NET Syntax

Visual Basic (Declaration)

```
Function SetupSheet3( _  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Integer, _  
    ByVal TemplateIn As System.Integer, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double, _  
    ByVal FirstAngle As System.Boolean, _  
    ByVal TemplateName As System.String, _  
    ByVal Width As System.Double, _  
    ByVal Height As System.Double _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Integer  
Dim TemplateIn As System.Integer  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
Dim FirstAngle As System.Boolean  
Dim TemplateName As System.String  
Dim Width As System.Double  
Dim Height As System.Double  
Dim value As System.Boolean
```

```
value = instance.SetupSheet3(Name, PaperSize, TemplateIn, Scale1, Scale2, FirstAngle,  
TemplateName, Width, Height)
```

C#

```
System.bool SetupSheet3(  
    System.string Name,  
    System.int PaperSize,  
    System.int TemplateIn,  
    System.double Scale1,  
    System.double Scale2,  
    System.bool FirstAngle,  
    System.string TemplateName,  
    System.double Width,  
    System.double Height  
)
```

C++/CLI

```
System.bool SetupSheet3(  
& System.String^ Name,  
& System.int PaperSize,  
& System.int TemplateIn,  
& System.double Scale1,  
& System.double Scale2,  
& System.bool FirstAngle,  
& System.String^ TemplateName,
```

```
& System.double Width,  
& System.double Height  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

PaperSize

TemplateIn

Scale1

Scale2

FirstAngle

TemplateName

Width

Height

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetupSheet3](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetupSheet4 Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetupSheet4 Method (IDrawingDoc)

Obsolete. Superseded by [IDrawingDoc::SetupSheet5](#).

.NET Syntax

Visual Basic (Declaration)

```
Function SetupSheet4( _  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Integer, _  
    ByVal TemplateIn As System.Integer, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double, _  
    ByVal FirstAngle As System.Boolean, _  
    ByVal TemplateName As System.String, _  
    ByVal Width As System.Double, _  
    ByVal Height As System.Double, _  
    ByVal PropertyViewName As System.String _  
) As System.Boolean
```

Visual Basic (Usage)

```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Integer  
Dim TemplateIn As System.Integer  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
Dim FirstAngle As System.Boolean  
Dim TemplateName As System.String  
Dim Width As System.Double  
Dim Height As System.Double  
Dim PropertyViewName As System.String  
Dim value As System.Boolean
```



```
value = instance.SetupSheet4(Name, PaperSize, TemplateIn, Scale1, Scale2, FirstAngle, TemplateName, Width, Height, PropertyViewName)
```

C#

```
System.bool SetupSheet4(  
    System.string Name,  
    System.int PaperSize,  
    System.int TemplateIn,  
    System.double Scale1,  
    System.double Scale2,  
    System.bool FirstAngle,  
    System.string TemplateName,  
    System.double Width,  
    System.double Height,  
    System.string PropertyViewName  
)
```

C++/CLI

```
System.bool SetupSheet4(  
& System.String^ Name,  
& System.int PaperSize,  
& System.int TemplateIn,  
& System.double Scale1,  
& System.double Scale2,  
& System.bool FirstAngle,  
& System.String^ TemplateName,  
& System.double Width,  
& System.double Height,  
& System.String^ PropertyViewName  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

Name for the sheet

PaperSize

Size of paper if using swDwgTemplateNone as defined in [swDwgPaperSizes_e](#)

TemplateIn

Template as defined in [swDwgTemplates_e](#)

Scale1

Scale numerator

Scale2

Scale denominator

FirstAngle

True for first angle projection, false otherwise

TemplateName

Name of custom template with full directory path if using swDwgTemplateCustom

Width

Paper width if TemplateIn is set to swDwgTemplateNone or swDwgPapersUserDefined

Height

Paper height if TemplateIn is set to swDwgTemplateNone or swDwgPapersUserDefined

PropertyViewName

Name of view containing the model from which to get custom property values

Return Value

True if set successfully, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetupSheet4](#).

Example

[Change Setup of Drawing Sheet \(VBA\)](#)

Remarks

Call [IModelDoc2::ForceRebuild3](#) after calling IDrawingDoc::SetupSheet4 to update any changes to first angle/third angle projections in the drawing views.

If you specify a different filename for TemplateName than what is currently being used by SOLIDWORKS, then SOLIDWORKS updates the sheet format.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SetupSheet5 Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetupSheet5 Method (IDrawingDoc)

Obsolete. Superseded by [IDrawingDoc::SetupSheet6](#).

.NET Syntax

Visual Basic (Declaration)

```
Function SetupSheet5( _  
    ByVal Name As System.String, _  
    ByVal PaperSize As System.Integer, _  
    ByVal TemplateIn As System.Integer, _  
    ByVal Scale1 As System.Double, _  
    ByVal Scale2 As System.Double, _  
    ByVal FirstAngle As System.Boolean, _  
    ByVal TemplateName As System.String, _  
    ByVal Width As System.Double, _  
    ByVal Height As System.Double, _  
    ByVal PropertyViewName As System.String, _  
    ByVal RemoveModifiedNotes As System.Boolean _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim PaperSize As System.Integer  
Dim TemplateIn As System.Integer  
Dim Scale1 As System.Double  
Dim Scale2 As System.Double  
Dim FirstAngle As System.Boolean  
Dim TemplateName As System.String  
Dim Width As System.Double  
Dim Height As System.Double  
Dim PropertyViewName As System.String  
Dim RemoveModifiedNotes As System.Boolean  
Dim value As System.Boolean
```

```
value = instance.SetupSheet5(Name, PaperSize, TemplateIn, Scale1, Scale2, FirstAngle,  
TemplateName, Width, Height, PropertyViewName, RemoveModifiedNotes)
```

C#

```
System.bool SetupSheet5(  
    System.string Name,  
    System.int PaperSize,  
    System.int TemplateIn,  
    System.double Scale1,  
    System.double Scale2,  
    System.bool FirstAngle,  
    System.string TemplateName,  
    System.double Width,  
    System.double Height,  
    System.string PropertyViewName,  
    System.bool RemoveModifiedNotes  
)
```

C++/CLI

```
System.bool SetupSheet5(  
& System.String^ Name,
```

```

& System.int PaperSize,
& System.int TemplateIn,
& System.double Scale1,
& System.double Scale2,
& System.bool FirstAngle,
& System.String^ TemplateName,
& System.double Width,
& System.double Height,
& System.String^ PropertyViewName,
& System.bool RemoveModifiedNotes
)

```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

Name for the sheet

PaperSize

Size of paper if using swDwgTemplateNone as defined in [swDwgPaperSizes_e](#)

TemplateIn

Template as defined in [swDwgTemplates_e](#)

Scale1

Scale numerator

Scale2

Scale denominator

FirstAngle

True for first angle projection, false otherwise

TemplateName

Name of custom template with full directory path if using swDwgTemplateCustom

Width

Paper width; valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateNone or PaperSize is set to swDwgPaperSizes_e.swDwgPapersUserDefined

Height

Paper height if TemplateIn is set to swDwgTemplateNone or swDwgPapersUserDefined

PropertyViewName

Name of view containing the model from which to get custom property values

RemoveModifiedNotes

True to delete modified notes, false to not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SetupSheet5](#).

Remarks

Call [IModelDoc2::ForceRebuild3](#) after calling IDrawingDoc::SetupSheet5 to update any changes to first angle/third angle projections in the drawing views.

If you specify a different filename for TemplateName than what is currently being used by SOLIDWORKS, then SOLIDWORKS updates the sheet format.

See Also

[IDrawingDoc Interface](#)

[IDrawingDoc Members](#)

[IDrawingDoc::ActivateSheet Method](#)

[IDrawingDoc::EditSheet Method](#)

[IDrawingDoc::GetEditSheet Method](#)

[IDrawingDoc::GetSheetCount Method](#)

[IDrawingDoc::GetSheetNames Method](#)

[IDrawingDoc::GetCurrentSheet Method](#)

[IDrawingDoc::IGetSheetNames Method](#)

[IDrawingDoc::IReorderSheets Method](#)

[IDrawingDoc::NewSheet3 Method](#)

[IDrawingDoc::SheetNext Method](#)

[IDrawingDoc::SheetPrevious Method](#)

[IDrawingDoc::ReorderSheets](#)

[ISheet Interface](#)

Availability

SOLIDWORKS 2009 FCS, Revision Number 17.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

SetupSheet6 Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SetupSheet6 Method (IDrawingDoc)

Sets up the specified drawing sheet.

Visual Basic (Declaration)

```
Function SetupSheet6( _
    ByVal Name As System.String, _
    ByVal PaperSize As System.Integer, _
    ByVal TemplateIn As System.Integer, _
    ByVal Scale1 As System.Double, _
    ByVal Scale2 As System.Double, _
    ByVal FirstAngle As System.Boolean, _
    ByVal TemplateName As System.String, _
    ByVal Width As System.Double, _
    ByVal Height As System.Double, _
    ByVal PropertyViewName As System.String, _
    ByVal RemoveModifiedNotes As System.Boolean, _
    ByVal ZoneLeftMargin As System.Double, _
    ByVal ZoneRightMargin As System.Double, _
    ByVal ZoneTopMargin As System.Double, _
    ByVal ZoneBottomMargin As System.Double, _
    ByVal ZoneRow As System.Integer, _
    ByVal ZoneCol As System.Integer _
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
Dim Name As System.String
Dim PaperSize As System.Integer
Dim TemplateIn As System.Integer
Dim Scale1 As System.Double
Dim Scale2 As System.Double
Dim FirstAngle As System.Boolean
Dim TemplateName As System.String
Dim Width As System.Double
Dim Height As System.Double
Dim PropertyViewName As System.String
Dim RemoveModifiedNotes As System.Boolean
Dim ZoneLeftMargin As System.Double
Dim ZoneRightMargin As System.Double
Dim ZoneTopMargin As System.Double
Dim ZoneBottomMargin As System.Double
Dim ZoneRow As System.Integer
Dim ZoneCol As System.Integer
Dim value As System.Boolean
```

```
value = instance.SetupSheet6(Name, PaperSize, TemplateIn, Scale1, Scale2, FirstAngle,
TemplateName, Width, Height, PropertyViewName, RemoveModifiedNotes, ZoneLeftMargin,
ZoneRightMargin, ZoneTopMargin, ZoneBottomMargin, ZoneRow, ZoneCol)
```

C#

```
System.bool SetupSheet6(
    System.string Name,
    System.int PaperSize,
    System.int TemplateIn,
    System.double Scale1,
    System.double Scale2,
    System.bool FirstAngle,
    System.string TemplateName,
    System.double Width,
    System.double Height,
    System.string PropertyViewName,
    System.bool RemoveModifiedNotes,
    System.double ZoneLeftMargin,
    System.double ZoneRightMargin,
    System.double ZoneTopMargin,
    System.double ZoneBottomMargin,
    System.int ZoneRow,
```

```
System.int ZoneCol  
)
```

C++/CLI

```
System.bool SetupSheet6(  
& System.String^ Name,  
& System.int PaperSize,  
& System.int TemplateIn,  
& System.double Scale1,  
& System.double Scale2,  
& System.bool FirstAngle,  
& System.String^ TemplateName,  
& System.double Width,  
& System.double Height,  
& System.String^ PropertyViewName,  
& System.bool RemoveModifiedNotes,  
& System.double ZoneLeftMargin,  
& System.double ZoneRightMargin,  
& System.double ZoneTopMargin,  
& System.double ZoneBottomMargin,  
& System.int ZoneRow,  
& System.int ZoneCol  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name

Name of the sheet to set up

PaperSize

Size of paper as defined in [swDwgPaperSizes_e](#); valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateNone

TemplateIn

Template as defined in [swDwgTemplates_e](#)

Scale1

Scale numerator

Scale2

Scale denominator

FirstAngle

True for first angle projection, false for third angle projection

TemplateName

Name of custom template with full directory path; valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateCustom

Width

Paper width; valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateNone or PaperSize is set to swDwgPaperSizes_e.swDwgPapersUserDefined

Height

Paper height; valid only if TemplateIn is set to swDwgTemplates_e.swDwgTemplateNone or PaperSize is set to swDwgPaperSizes_e.swDwgPapersUserDefined

PropertyViewName

Name of view containing the model from which to get custom property values

RemoveModifiedNotes

True to delete modified notes, false to not

ZoneLeftMargin

Zone area left margin; distance from drawing sheet's left edge

ZoneRightMargin

Zone area right margin; distance from drawing sheet's right edge

ZoneTopMargin

Zone area top margin; distance from drawing sheet's top edge

ZoneBottomMargin

Zone area bottom margin; distance from drawing sheet's bottom edge

ZoneRow

Number of zone rows in the zone area of this sheet (see **Remarks**)

ZoneCol

Number of zone columns in the zone area of this sheet (see **Remarks**)

Return Value

True if drawing sheet setup is successful, false if not

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc2::SetupSheet6](#).

Example

[Create Drawing Sheet Zones \(VBA\)](#)

[Create Drawing Sheet Zones \(VB.NET\)](#)

[Create Drawing Sheet Zones \(C#\)](#)

[Modify Multiple Drawing Sheets Setups \(C#\)](#)

[Modify Multiple Drawing Sheets Setups \(VB.NET\)](#)

[Modify Multiple Drawing Sheets Setups \(VBA\)](#)

Remarks

After calling this method, call [IModelDoc2::ForceRebuild3](#) to update any changes to first angle/third angle projections in the drawing views.

If you specify a different filename for TemplateName than what is currently being used by SOLIDWORKS, then SOLIDWORKS updates the sheet format.

The drawing sheet can be set up with zones that annotations in other views can reference. Each zone is referenced by an alphanumeric label that is defined using the Zone Editor. See the SOLIDWORKS Help for more information about drawing sheet zones.

Multiplying ZoneRow by ZoneCol equals the total number of zones in the zone area of this drawing sheet. The zone area is specified by ZoneLeftMargin, ZoneRightMargin, ZoneTopMargin, and ZoneBottomMargin.

To modify the setups of multiple drawing sheets with just one call to IDrawingDoc::SetupSheet6, call [IDrawingDoc::SetSelectedSheets](#) before calling IDrawingDoc::SetupSheet6.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ActivateSheet Method \(\)](#)
[IDrawingDoc::EditSheet Method \(\)](#)
[IDrawingDoc::GetEditSheet Method \(\)](#)
[IDrawingDoc::GetSheetCount Method \(\)](#)
[IDrawingDoc::GetSheetNames Method \(\)](#)
[IDrawingDoc::NewSheet4 Method \(\)](#)
[IDrawingDoc::PasteSheet Method \(\)](#)
[IDrawingDoc::SheetNext Method \(\)](#)
[IDrawingDoc::SheetPrevious Method \(\)](#)
[IDrawingDoc::ReorderSheets Method \(\)](#)
[ISheet::GetDrawingZone Method \(\)](#)
[ISheet Interface](#)

Availability

SOLIDWORKS 2015 FCS, Revision Number 23.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

Sheet Property (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : Sheet Property (IDrawingDoc)

Gets the specified sheet.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property Sheet( _  
    ByVal Name As System.String _  
) As Sheet
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim Name As System.String  
Dim value As Sheet  
  
value = instance.Sheet(Name)
```

C#

```
Sheet Sheet(  
    System.string Name  
) {get;}
```

C++/CLI

```
property Sheet^ Sheet {  
    Sheet^ get(System.String^ Name);  
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

Name
Name of sheet

Property Value

[Sheet](#)

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::Sheet](#).

Example

[Get Sheet in Multi-sheet Drawing \(C#\)](#)
[Get Sheet in Multi-Sheet Drawing \(VB.NET\)](#)
[Get Sheet in Multi-sheet Drawing \(VBA\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

Availability

SOLIDWORKS 2010 FCS, Revision Number 18.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

SheetNext Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SheetNext Method (IDrawingDoc)

Moves to the next sheet in the drawing.

.NET Syntax

Visual Basic (Declaration)

```
Sub SheetNext()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
  
instance.SheetNext()
```

C#

```
void SheetNext()
```

C++/CLI

```
void SheetNext();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SheetNext](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[ISheet Interface](#)
[IDrawingDoc::ActivateSheet Method](#)
[IDrawingDoc::SEditSheet Method](#)
[IDrawingDoc::SGetEditSheet Method](#)
[IDrawingDoc::SGetSheetCount Method](#)
[IDrawingDoc::SGetSheetNames Method](#)
[IDrawingDoc::SGetCurrentSheet Method](#)
[IDrawingDoc::SGetSheetNames Method](#)
[IDrawingDoc::SReorderSheets Method](#)
[IDrawingDoc::SNewSheet3 Method](#)
[IDrawingDoc::SReorderSheets Method](#)
[IDrawingDoc::SSetupSheet4 Method](#)
[IDrawingDoc::SheetPrevious Method](#)
[ISheet Interface](#)

SheetPrevious Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SheetPrevious Method (IDrawingDoc)

Returns to the previous sheet in a drawing.

.NET Syntax

Visual Basic (Declaration)

```
Sub SheetPrevious()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
```

```
instance.SheetPrevious()
```

C#

```
void SheetPrevious()
```

C++/CLI

```
void SheetPrevious();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SheetPrevious](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::SheetNext Method](#)
[IDrawingDoc::ActivateSheet Method](#)
[IDrawingDoc::EditSheet Method](#)
[IDrawingDoc::GetEditSheet Method](#)
[IDrawingDoc::GetSheetCount Method](#)
[IDrawingDoc::GetSheetNames Method](#)
[IDrawingDoc::GetCurrentSheet Method](#)
[IDrawingDoc::IGetCurrentSheet Method](#)
[IDrawingDoc::IGetSheetNames Method](#)
[IDrawingDoc::NewSheet3 Method](#)
[IDrawingDoc::SetupSheet4 Method](#)
[ISheet Interface](#)

ShowEdge Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ShowEdge Method (IDrawingDoc)

Shows the selected hidden edges in a drawing document.

.NET Syntax

Visual Basic (Declaration)

```
Sub ShowEdge()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
```

```
instance.ShowEdge()
```

C#

```
void ShowEdge()
```

C++/CLI

```
void ShowEdge();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ShowEdge](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::HideEdge Method](#)
[IDrawingDoc::ViewModelEdges Method](#)
[IDrawingDoc::ViewTangentEdges Method](#)
[IView::HiddenEdges Property](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SketchDim Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SketchDim Method (IDrawingDoc)

Inserts a sketch dimension in this drawing.

.NET Syntax

Visual Basic (Declaration)

```
Sub SketchDim()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
```

```
instance.SketchDim()
```

C#

```
void SketchDim()
```

C++/CLI

```
void SketchDim();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SketchDim](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::AddChamferDim Method](#)
[IDrawingDoc::AddOrdinateDimension2 Method](#)
[IDrawingDoc::AttachDimensions Method](#)
[IDrawingDoc::AutoDimension Method](#)
[IDrawingDoc::Create3rdAngleViews2 Method](#)
[IDrawingDoc::CreateAngDim4 Method](#)
[IDrawingDoc::CreateDiamDim4 Method](#)
[IDrawingDoc::CreateLinearDim4 Method](#)
[IDrawingDoc::CreateOrdinateDim4 Method](#)
[IDrawingDoc::Dimensions Method](#)
[IDrawingDoc::DragModelDimension Method](#)
[IDrawingDoc::HideShowDimensions Method](#)
[IDrawingDoc::!AddChamferDim Method](#)
[IDrawingDoc::!CreateAngDim4 Method](#)
[IDrawingDoc::!CreateDiamDim4 Method](#)

[IDrawingDoc::ICreateLinearDim4 Method](#)
[IDrawingDoc::ICreateOrdinateDim4 Method](#)
[IDrawingDoc::InsertBaseDim Method](#)
[IDrawingDoc::InsertModelAnnotations3 Method](#)
[IDrawingDoc::InsertModelDimensions Method](#)
[IDrawingDoc::InsertOrdinate Method](#)
[IDrawingDoc::InsertRefDim Method](#)
[IDrawingDoc::InsertVerticalOrdinate Method](#)
[IDimension Interface](#)
[ISketch Interface](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

StartDrawing Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : StartDrawing Method (IDrawingDoc)

Provides faster creation of entities within a drawing.

.NET Syntax

Visual Basic (Declaration)

```
Sub StartDrawing()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
instance.StartDrawing()
```

C#

```
void StartDrawing()
```

C++/CLI

```
void StartDrawing();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::StartDrawing](#).

Remarks

This method automatically disables inferencing to provide faster geometry creation. Use this method and [IDrawingDoc::EndDrawing](#) to bound your entity creation statements.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

SuppressView Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : SuppressView Method (IDrawingDoc)

Hides the selected drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Sub SuppressView()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
```

```
instance.SuppressView()
```

C#

```
void SuppressView()
```

C++/CLI

```
void SuppressView();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::SuppressView](#).

Example

[Automatically Insert Center Marks \(C#\)](#)
[Automatically Insert Center Marks \(VB.NET\)](#)
[Automatically Insert Center Marks \(VBA\)](#)

Remarks

Dependent views are not suppressed.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ActivateView Method](#)
[IDrawingDoc::GetFirstView Method](#)
[IDrawingDoc::HideShowDrawingViews Method](#)
[IDrawingDoc::IGetFirstView Method](#)
[IDrawingDoc::UnsuppressView Method](#)
[IDrawingDoc::ActiveDrawingView Property](#)
[IDrawingDoc::AutomaticViewUpdate Property](#)
[IDrawingDoc::HiddenViewsVisible Property](#)
[IDrawingDoc::IDrawingDoc::IActiveDrawingView Property](#)
[IView::IGetNextView Method](#)
[IView::GetNextView Method](#)

Availability

SOLIDWORKS 2001Plus FCS, Revision Number 10.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

ToggleGrid Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : [ToggleGrid Method \(IDrawingDoc\)](#)

Obsolete. Superseded by [IModelDocExtension::GetUserPreferenceToggle](#) and [IModelDocExtension::SetUserPreferenceToggle](#) and [swUserPreferenceToggle_e.swGridDisplay](#).

.NET Syntax

Visual Basic (Declaration)

```
Sub ToggleGrid()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc
```

```
instance.ToggleGrid()
```

C#

```
void ToggleGrid()
```

C++/CLI

```
void ToggleGrid();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ToggleGrid](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

SOLIDWORKS API Help

[Send comments on this topic.](#)

TranslateDrawing Method (IDrawingDoc)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : TranslateDrawing Method (IDrawingDoc)

Translates the entire drawing.

.NET Syntax

Visual Basic (Declaration)

```
Sub TranslateDrawing( _  
    ByVal DeltaX As System.Double, _  
    ByVal DeltaY As System.Double _  
)
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
Dim DeltaX As System.Double  
Dim DeltaY As System.Double  
  
instance.TranslateDrawing(DeltaX, DeltaY)
```

C#

```
void TranslateDrawing(  
    System.double DeltaX,  
    System.double DeltaY  
)
```

C++/CLI

```
void TranslateDrawing(  
& System.double DeltaX,  
& System.double DeltaY  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

DeltaX

Delta X value for the translation operation

DeltaY

Delta Y value for the translation operation

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::TranslateDrawing](#).

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)

Availability

SOLIDWORKS 99, datecode 1999207

SOLIDWORKS API Help

[Send comments](#) on this topic.

UnBreakView Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : UnBreakView Method (IDrawingDoc)

Removes a break in the selected drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Sub UnBreakView()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
instance.UnBreakView()
```

C#

```
void UnBreakView()
```

C++/CLI

```
void UnBreakView();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::UnBreakView](#).

Example

[Create Break View \(C#\)](#)
[Create Break View \(VB.NET\)](#)
[Create Break View \(VBA\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc.BreakView Method](#)
[IDrawingDoc.InsertBreakHorizontal Method](#)
[IDrawingDoc.InsertBreakVertical Method](#)

SOLIDWORKS API Help

[Send comments](#) on this topic.

UnsuppressView Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : UnsuppressView Method (IDrawingDoc)

Hides the selected drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Sub UnsuppressView()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
  
instance.UnsuppressView()
```

C#

```
void UnsuppressView()
```

C++/CLI

```
void UnsuppressView();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::UnsuppressView](#).

Example

[Automatically Insert Center Marks \(C#\)](#)
[Automatically Insert Center Marks \(VB.NET\)](#)
[Automatically Insert Center Marks \(VBA\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ActivateView Method](#)
[IDrawingDoc::GetFirstView Method](#)
[IDrawingDoc::HideShowDrawingViews Method](#)
[IDrawingDoc::IGetFirstView Method](#)
[IDrawingDoc::SuppressView Method](#)
[IDrawingDoc::ActiveDrawingView Property](#)
[IDrawingDoc::AutomaticViewUpdate Property](#)
[IDrawingDoc::HiddenViewsVisible Property](#)
[IDrawingDoc::IActiveDrawingView Property](#)
[IView::GetNextView Method](#)
[IView::IGetNextView Method](#)

Availability

SOLIDWORKS 2001Plus FCS, Revision Number 10.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

ViewDisplayHidden Method (IDrawingDoc)

See Also [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ViewDisplayHidden Method (IDrawingDoc)

Sets the current display mode to **Hidden Lines Removed**.

.NET Syntax

Visual Basic (Declaration)

```
Sub ViewDisplayHidden()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
  
instance.ViewDisplayHidden()
```

C#

```
void ViewDisplayHidden()
```

C++/CLI

```
void ViewDisplayHidden();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ViewDisplayHidden](#).

Example

[Display Hidden Lines in Drawing \(VBA\)](#)
[Display Hidden Lines in Drawing \(VB.NET\)](#)
[Display Hidden Lines in Drawing \(C#\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ViewDisplayHiddengreyed Method](#)
[IDrawingDoc::ViewDisplayShaded Method](#)
[IDrawingDoc::ViewDisplayWireframe Method](#)
[IDrawingDoc::ViewHirQuality Method](#)
[IDrawingDoc::ViewFullPage Method](#)
[IDrawingDoc::ViewModelEdges Method](#)
[IDrawingDoc::ViewTangentEdges Method](#)

Availability

SOLIDWORKS 2001Plus FCS, Revision Number 10.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

ViewDisplayHiddengreyed Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ViewDisplayHiddengreyed Method (IDrawingDoc)

Sets the current display mode to **Hidden Lines Visible**.

.NET Syntax

Visual Basic (Declaration)

```
Sub ViewDisplayHiddengreyed()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
instance.ViewDisplayHiddengreyed()
```

C#

```
void ViewDisplayHiddengreyed()
```

C++/CLI

```
void ViewDisplayHiddengreyed();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ViewDisplayHiddengreyed](#).

Example

[Display Hidden Lines in Drawing \(VBA\)](#)
[Display Hidden Lines in Drawing \(VB.NET\)](#)
[Display Hidden Lines in Drawing \(C#\)](#)

Remarks

The hidden lines are shown in grey.

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ViewDisplayHidden Method](#)
[IDrawingDoc::ViewDisplayShaded Method](#)
[IDrawingDoc::ViewDisplayWireframe Method](#)
[IDrawingDoc::ViewHlrQuality Method](#)
[IDrawingDoc::ViewFullPage Method](#)
[IDrawingDoc::ViewModelEdges Method](#)
[IDrawingDoc::ViewTangentEdges Method](#)

Availability

SOLIDWORKS 2001Plus FCS, Revision Number 10.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

ViewDisplayShaded Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ViewDisplayShaded Method (IDrawingDoc)

Sets the current display mode to **Shaded**.

.NET Syntax

Visual Basic (Declaration)

```
Sub ViewDisplayShaded()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
instance.ViewDisplayShaded()
```

C#

```
void ViewDisplayShaded()
```

C++/CLI

```
void ViewDisplayShaded();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ViewDisplayShaded](#).

Example

[Display Hidden Lines in Drawing \(VBA\)](#)
[Display Hidden Lines in Drawing \(VB.NET\)](#)
[Display Hidden Lines in Drawing \(C#\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ViewDisplayHidden Method](#)
[IDrawingDoc::ViewDisplayHiddengreyed Method](#)
[IDrawingDoc::ViewDisplayWireframe Method](#)
[IDrawingDoc::ViewFullPage Method](#)
[IDrawingDoc::ViewHlrQuality Method](#)
[IDrawingDoc::ViewModelEdges Method](#)
[IDrawingDoc::ViewTangentEdges Method](#)

Availability

SOLIDWORKS 2001Plus FCS, Revision Number 10.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

ViewDisplayWireframe Method (IDrawingDoc)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IDrawingDoc Interface](#) : ViewDisplayWireframe Method (IDrawingDoc)

Sets the current display mode to **Wireframe**.

.NET Syntax

Visual Basic (Declaration)

```
Sub ViewDisplayWireframe()
```

Visual Basic (Usage)



```
Dim instance As IDrawingDoc  
instance.ViewDisplayWireframe()
```

C#

```
void ViewDisplayWireframe()
```

C++/CLI

```
void ViewDisplayWireframe();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [DrawingDoc::ViewDisplayWireframe](#).

Example

[Display Hidden Lines in Drawing \(VBA\)](#)
[Display Hidden Lines in Drawing \(VB.NET\)](#)
[Display Hidden Lines in Drawing \(C#\)](#)

See Also

[IDrawingDoc Interface](#)
[IDrawingDoc Members](#)
[IDrawingDoc::ViewDisplayHidden Method](#)
[IDrawingDoc::ViewDisplayHiddengreyed Method](#)
[IDrawingDoc::ViewDisplayShaded Method](#)
[IDrawingDoc::ViewFullPage Method](#)
[IDrawingDoc::ViewHirQuality Method](#)
[IDrawingDoc::ViewModelEdges Method](#)
[IDrawingDoc::ViewTangentEdges Method](#)

Availability

SOLIDWORKS 2001Plus FCS, Revision Number 10.0