

SOLIDWORKS API (VB6 COM) — Reference (31/102): FeatureManager (part 1 of 3)

SOLIDWORKS API Documentation (converted from CHM)

FeatureManager (part 1 of 3) (Type)

SOLIDWORKS Type Library

FeatureManager Object

 Object Model

FeatureManager

- AdvancedHole (Feature)
- AdvancedHole2 (Feature)
- ConvertLoftOrSweepToNetBlend (Feature)
- CreateCoordinateSystem (Feature)
- CreateCoordinateSystemUsingNumericalValues (Feature)
- CreateCustomBendAllowance (CustomBendAllowance)
- CreateFeature (Feature)
- CreateFormTool (Feature)
- CreateFormTool2 (Feature)
- CreateStructuralMemberGroup (StructuralMemberGroup)
- Document (ModelDoc2)
- DraftXpertChange (Feature)
- DraftXpertRemove (Feature)
- EndVariablePitchHelix (Feature)
- FeatureAdvancedTableDrivenPattern (Feature)
- FeatureBossThicken (Feature)
- FeatureChainPattern (Feature)
- FeatureCircularPattern (Feature)
- FeatureCircularPattern2 (Feature)
- FeatureCircularPattern3 (Feature)
- FeatureCircularPattern4 (Feature)
- FeatureCircularPattern5 (Feature)
- FeatureCut (Feature)
- FeatureCut2 (Feature)
- FeatureCut3 (Feature)
- FeatureCut4 (Feature)
- FeatureCutThicken (Feature)
- FeatureCutThin (Feature)
- FeatureCutThin2 (Feature)
- FeatureDimensionPattern (Feature)

- FeatureExtrusion (Feature)
- FeatureExtrusion2 (Feature)
- FeatureExtrusion3 (Feature)
- FeatureExtrusionThin (Feature)
- FeatureExtrusionThin2 (Feature)
- FeatureFillPattern (Feature)
- FeatureFolderLocation (Feature)
- FeatureLinearPattern (Feature)
- FeatureLinearPattern2 (Feature)
- FeatureLinearPattern3 (Feature)
- FeatureLinearPattern4 (Feature)
- FeatureLinearPattern5 (Feature)
- FeatureLocalCurveDrivenPattern (Feature)
- FeatureLocalSketchDrivenPattern (Feature)
- FeatureRevolve (Feature)
- FeatureRevolve2 (Feature)
- FeatureRevolveCut (Feature)
- FeatureRevolveCut2 (Feature)
- FeatureRevolveThin (Feature)
- FeatureRevolveThinCut (Feature)
- FeatureSketchDrivenPattern (Feature)
- FeatureStatistics
- FiletXpertChange (Feature)
- FiletXpertMakeCorner (Feature)
- FiletXpertRemove (Feature)
- FinishCornerRelief (Feature)
- GetFeatureTreeRootItem (TreeControlItem)
- GetFeatureTreeRootItem2 (TreeControlItem)
- GetFreezeLocation (Feature)
- HoleWizard (Feature)
- HoleWizard2 (Feature)
- HoleWizard3 (Feature)

	HoleWizard3 (Feature)
	HoleWizard4 (Feature)
	HoleWizard5 (Feature)
	IFeatureFilet (Feature)
	IFeatureFilet2 (Feature)
	IGetFeatures (Feature)
	IInsertCombineFeature (Feature)
	IInsertMacroFeature (Feature)
	IInsertMacroFeature2 (Feature)
	IInsertMacroFeature3 (Feature)
	IInsertMoveFace2 (Feature)
	IInsertReferencePoint (Feature)
	IInsertSheetMetalEdgeFlange2 (Feature)
	IInsertTableDrivenPattern (Feature)
	InsertCenterOfMass (Feature)
	InsertCenterOfMassReferencePoint (Feature)
	InsertCombineFeature (Feature)
	InsertCoordinateSystem (Feature)
	InsertCosmeticThread2 (Feature)
	InsertCosmeticThread3 (Feature)
	InsertCosmeticWeldBead (Feature)
	InsertCrossBreak (Feature)
	InsertCutBlend (Feature)
	InsertCutSurface (Feature)
	InsertCutSwept (Feature)
	InsertCutSwept2 (Feature)
	InsertCutSwept3 (Feature)
	InsertCutSwept4 (Feature)
	InsertCutSwept5 (Feature)
	InsertDeleteBody (Feature)
	InsertDeleteBody2 (Feature)
	InsertDeleteHoleForSurface (Feature)

InsertDerivedPattern (Feature)	
InsertDerivedPattern2 (Feature)	
InsertDwgOrDxfFile (Feature)	
InsertDwgOrDxfFile2 (Feature)	
InsertEdgeMerge (Feature)	
InsertEndCapFeature (Feature)	
InsertEndCapFeature2 (Feature)	
InsertEndCapFeature3 (Feature)	
InsertFeatureChamfer (Feature)	
InsertFeatureLock (Feature)	
InsertFeatureTreeFolder2 (Feature)	
InsertFiletBeadFeature (Feature)	
InsertFiletBeadFeature2 (Feature)	
InsertFiletBeadFeature3 (Feature)	
InsertFilSurface (Feature)	
InsertFilSurface2 (Feature)	
InsertFlattenSurface (Feature)	
InsertFlattenSurface2 (Feature)	
InsertFlexFeature (Feature)	
InsertFormToolFeature (Feature)	
InsertFreeform (Feature)	
InsertFreeform2 (Feature)	
InsertGridFeature (Feature)	
InsertGroundPlane (Feature)	
InsertGussetFeature (Feature)	
InsertGussetFeature2 (Feature)	
InsertGussetFeature3 (Feature)	
InsertIndent (Feature)	
InsertLiveSectionPlane (Feature)	
InsertMacroFeature (Feature)	
InsertMacroFeature2 (Feature)	

- InsertMacroFeature3 (Feature)
- InsertMateReference (Feature)
- InsertMateReference2 (Feature)
- InsertMirrorFeature (Feature)
- InsertMirrorFeature2 (Feature)
- InsertMoldCoreCavitySolids (Feature)
- InsertMoldPartingLine (Feature)
- InsertMoldPartingSurface (Feature)
- InsertMoldShutOffSurface (Feature)
- InsertMoveCopyBody (Feature)
- InsertMoveCopyBody2 (Feature)
- InsertMoveFace (Feature)
- InsertMoveFace2 (Feature)
- InsertMoveFace3 (Feature)
- InsertMultiFaceDraft (Feature)
- InsertNetBlend (Feature)
- InsertNetBlend2 (Feature)
- InsertProtrusionBlend (Feature)
- InsertProtrusionBlend2 (Feature)
- InsertProtrusionSwept (Feature)
- InsertProtrusionSwept2 (Feature)
- InsertProtrusionSwept3 (Feature)
- InsertProtrusionSwept4 (Feature)
- InsertRevolvedRefSurface (Feature)
- InsertRuledSurfaceFromEdge (Feature)
- InsertRuledSurfaceFromEdge2 (Feature)
- InsertScale (Feature)
- InsertSecurityNote (Note)
- InsertSewRefSurface (Feature)
- InsertSheetMetal3dBend (Feature)
- InsertSheetMetalBaseFlange (Feature)

InsertSheetMetalBaseFlange2 (Feature)
InsertSheetMetalCornerTrim (Feature)
InsertSheetMetalEdgeFlange (Feature)
InsertSheetMetalEdgeFlange2 (Feature)
InsertSheetMetalGussetFeature (Feature)
InsertSheetMetalGussetFeature2 (Feature)
InsertSheetMetalGussetFeature3 (Feature)
InsertSheetMetalHem (Feature)
InsertSheetMetalHem2 (Feature)
InsertSheetMetalLoftedBend (Feature)
InsertSheetMetalLoftedBend2 (Feature)
InsertSheetMetalMiterFlange (Feature)
InsertSplitLineIntersect (Feature)
InsertStructuralWeldment (Feature)
InsertStructuralWeldment2 (Feature)
InsertStructuralWeldment3 (Feature)
InsertStructuralWeldment4 (Feature)
InsertStructuralWeldment5 (Feature)
InsertSubFolder (Feature)
InsertSubWeldFolder (Feature)
InsertSubWeldFolder2 (Feature)
InsertSweepSurface (Feature)
InsertSweepSurface2 (Feature)
InsertSweepSurface3 (Feature)
InsertTableDrivenPattern (Feature)
InsertTableDrivenPattern2 (Feature)
InsertUntrimSurface (Feature)
InsertUntrimSurface2 (Feature)
InsertWeldmentCutList (Feature)
InsertWeldmentCutList2 (Feature)
InsertWeldmentFeature (Feature)

- InsertWeldmentTrimFeature (Feature)
- InsertWeldmentTrimFeature2 (Feature)
- InsertWrapFeature (Feature)
- InsertWrapFeature2 (Feature)
- PostIntersect (Feature)
- PostSplitBody (Feature)
- PostTrimSurface (Feature)
- SetNetBlendCenterlineData (Feature)
- SetNetBlendCurveData (Feature)
- SetNetBlendDirectionData (Feature)
- SimpleFeatureBossExtrude (Feature)
- SimpleHole (Feature)
- SimpleHole2 (Feature)

SOLIDWORKS Type Library

FeatureManager Object Members

Public Methods

- [AddCornerReliefCorner](#)
- [AddCornerReliefType](#)
- [AddSMNormalCut](#)
- [AddSMNormalCutType](#)
- [AddVariablePitchHelixFirstPitchAndDiameter](#)
- [AddVariablePitchHelixSegment](#)
- [AdvancedHole](#)
- [AdvancedHole2](#)
- [ConvertLoftOrSweepToNetBlend](#)
- [CreateCoordinateSystem](#)
- [CreateCoordinateSystemUsingNumericalValues](#)
- [CreateCustomBendAllowance](#)
- [CreateDefinition](#)
- [CreateFeature](#)
- [CreateFormTool](#)
- [CreateFormTool2](#)
- [CreateSaveBodyFeature](#)
- [CreateStructuralMemberGroup](#)
- [CutListFolderLocation](#)
- [DraftXpertChange](#)
- [DraftXpertRemove](#)

	EditDeleteFace
	EditFreeze
	EditFreeze2
	EditReferencePoint
	EditRollback
	EndVariablePitchHelix
	ExpandFeature
	FeatureAdvancedTableDrivenPattern
	FeatureBossThicken
	FeatureChainPattern
	FeatureCircularPattern
	FeatureCircularPattern2
	FeatureCircularPattern3
	FeatureCircularPattern4
	FeatureCircularPattern5
	FeatureCut
	FeatureCut2
	FeatureCut3
	FeatureCut4
	FeatureCutThicken
	FeatureCutThin
	FeatureCutThin2
	FeatureDimensionPattern
	FeatureExtruRefSurface
	FeatureExtruRefSurface2
	FeatureExtruRefSurface3
	FeatureExtrusion
	FeatureExtrusion2
	FeatureExtrusion3
	FeatureExtrusionThin
	FeatureExtrusionThin2
	FeatureFillet
	FeatureFillet2
	FeatureFillet3
	FeatureFillPattern
	FeatureFolderLocation
	FeatureLinearPattern
	FeatureLinearPattern2
	FeatureLinearPattern3
	FeatureLinearPattern4
	FeatureLinearPattern5
	FeatureLocalCurveDrivenPattern
	FeatureLocalSketchDrivenPattern

	FeatureRevolve
	FeatureRevolve2
	FeatureRevolveCut
	FeatureRevolveCut2
	FeatureRevolveThin
	FeatureRevolveThinCut
	FeatureSketchDrivenPattern
	FilletXpertChange
	FilletXpertMakeCorner
	FilletXpertRemove
	FinishCornerRelief
	FinishSMNormalCut
	GetCornerManagementFolders
	GetCreateFeatureErrors
	GetFeatureCount
	GetFeatures
	GetFeatureTreeRootItem
	GetFeatureTreeRootItem2
	GetFlatPatternFolder
	GetFreezeLocation
	GetPlasticsShellType
	GetPreTrimmedBodies
	GetSelectionSetFolder
	GetSheetMetalFolder
	GetSlicingData
	GetStructureSystemFolders
	HideBodies
	HoleWizard
	HoleWizard2
	HoleWizard3
	HoleWizard4
	HoleWizard5
	IFeatureFillet
	IFeatureFillet2
	IGetFeatures
	InsertCombineFeature
	InsertMacroFeature
	InsertMacroFeature2
	InsertMacroFeature3
	InsertMoveFace2
	InsertReferencePoint
	InsertSheetMetalEdgeFlange2
	InsertTableDrivenPattern

	<u>InsertCenterOfMass</u>
	<u>InsertCenterOfMassReferencePoint</u>
	<u>InsertCombineFeature</u>
	<u>InsertConnectionPoint</u>
	<u>InsertConvertToSheetMetal</u>
	<u>InsertConvertToSheetMetal2</u>
	<u>InsertCoordinateSystem</u>
	<u>InsertCosmeticThread</u>
	<u>InsertCosmeticThread2</u>
	<u>InsertCosmeticThread3</u>
	<u>InsertCosmeticWeldBead</u>
	<u>InsertCosmeticWeldBead2</u>
	<u>InsertCrossBreak</u>
	<u>InsertCutBlend</u>
	<u>InsertCutSurface</u>
	<u>InsertCutSweep</u>
	<u>InsertCutSweep2</u>
	<u>InsertCutSweep3</u>
	<u>InsertCutSweep4</u>
	<u>InsertCutSweep5</u>
	<u>InsertDeleteBody</u>
	<u>InsertDeleteBody2</u>
	<u>InsertDeleteHoleForSurface</u>
	<u>InsertDerivedPattern</u>
	<u>InsertDerivedPattern2</u>
	<u>InsertDwgOrDxfFile</u>
	<u>InsertDwgOrDxfFile2</u>
	<u>InsertEdgeMerge</u>
	<u>InsertEndCapFeature</u>
	<u>InsertEndCapFeature2</u>
	<u>InsertEndCapFeature3</u>
	<u>InsertFeatureChamfer</u>
	<u>InsertFeatureLock</u>
	<u>InsertFeatureTreeFolder</u>
	<u>InsertFeatureTreeFolder2</u>
	<u>InsertFilletBeadFeature</u>
	<u>InsertFilletBeadFeature2</u>
	<u>InsertFilletBeadFeature3</u>
	<u>InsertFillSurface</u>
	<u>InsertFillSurface2</u>
	<u>InsertFlattenSurface</u>
	<u>InsertFlattenSurface2</u>
	<u>InsertFlexFeature</u>

	InsertFormToolFeature
	InsertFreeform
	InsertFreeform2
	InsertGlobalBoundingBox
	InsertGlobalBoundingBox2
	InsertGridFeature
	InsertGroundPlane
	InsertGussetFeature
	InsertGussetFeature2
	InsertGussetFeature3
	InsertIndent
	InsertLiveSectionPlane
	InsertMacroFeature
	InsertMacroFeature2
	InsertMacroFeature3
	InsertMateReference
	InsertMateReference2
	InsertMidSurface
	InsertMirrorFeature
	InsertMirrorFeature2
	InsertMoldCoreCavitySolids
	InsertMoldPartingLine
	InsertMoldPartingSurface
	InsertMoldShutOffSurface
	InsertMoveCopyBody
	InsertMoveCopyBody2
	InsertMoveFace
	InsertMoveFace2
	InsertMoveFace3
	InsertMultiFaceDraft
	InsertNetBlend
	InsertNetBlend2
	InsertProtrusionBlend
	InsertProtrusionBlend2
	InsertProtrusionSweep
	InsertProtrusionSweep2
	InsertProtrusionSweep3
	InsertProtrusionSweep4
	InsertReferencePoint
	InsertRefPlane
	InsertRevolvedRefSurface
	InsertRib
	InsertRuledSurfaceFromEdge

	<u>InsertRuledSurfaceFromEdge2</u>
	<u>InsertSaveOutBodies</u>
	<u>InsertScale</u>
	<u>InsertSecurityNote</u>
	<u>InsertSewRefSurface</u>
	<u>InsertSheetMetal3dBend</u>
	<u>InsertSheetMetalBaseFlange</u>
	<u>InsertSheetMetalBaseFlange2</u>
	<u>InsertSheetMetalCornerTrim</u>
	<u>InsertSheetMetalEdgeFlange</u>
	<u>InsertSheetMetalEdgeFlange2</u>
	<u>InsertSheetMetalGussetFeature</u>
	<u>InsertSheetMetalGussetFeature2</u>
	<u>InsertSheetMetalGussetFeature3</u>
	<u>InsertSheetMetalIem</u>
	<u>InsertSheetMetalIem2</u>
	<u>InsertSheetMetalIofdBend</u>
	<u>InsertSheetMetalIofdBend2</u>
	<u>InsertSheetMetalMiterFlange</u>
	<u>InsertSlicing</u>
	<u>InsertSplitLineIntersect</u>
	<u>InsertStructuralWeldment</u>
	<u>InsertStructuralWeldment2</u>
	<u>InsertStructuralWeldment3</u>
	<u>InsertStructuralWeldment4</u>
	<u>InsertStructuralWeldment5</u>
	<u>InsertSubFolder</u>
	<u>InsertSubWeldFolder</u>
	<u>InsertSubWeldFolder2</u>
	<u>InsertSweepSurface</u>
	<u>InsertSweepSurface2</u>
	<u>InsertSweepSurface3</u>
	<u>InsertTableDrivenPattern</u>
	<u>InsertTableDrivenPattern2</u>
	<u>InsertUntrimSurface</u>
	<u>InsertUntrimSurface2</u>
	<u>InsertVariablePitchHelix</u>
	<u>InsertVaryInstanceIncrement</u>
	<u>InsertVaryInstanceOverride</u>
	<u>InsertWeldmentCutList</u>
	<u>InsertWeldmentCutList2</u>
	<u>InsertWeldmentFeature</u>
	<u>InsertWeldmentTrimFeature</u>

	InsertWeldmentTrimFeature2
	InsertWrapFeature
	InsertWrapFeature2
	IsNameUsed
	MakeStyledCurves
	MakeStyledCurves2
	MoldUndercutDetect
	MoldUndercutDetect2
	MoveRotateLiveSectionPlane
	MoveToFolder
	PostIntersect
	PostSplitBody
	PostSplitBody2
	PostTrimSurface
	PreIntersect
	PreIntersect2
	PreSplitBody
	PreSplitBody2
	PreTrimSurface
	SetComponentIdentifiers
	SetFreeformBoundaryContinuity
	SetFreeformCurveData
	SetFreeformPointData
	SetNetBlendCenterlineData
	SetNetBlendCurveData
	SetNetBlendDirectionData
	ShowBodies
	SimpleFeatureBossExtrude
	SimpleHole
	SimpleHole2
	UpdateFeatureTree

Public Properties

	ComponentPrimaryIdentifier
	ComponentSecondaryIdentifier
	ComponentTertiaryIdentifier
	Document
	EnableFeatureTree
	EnableFeatureTreeWindow
	FeatureName
	FeatureStatistics
	GroupComponentInstances
	HideComponentSingleConfigurationOrDisplayStateNames

 MoveSizeFeatures
 ShowComponentConfigurationDescriptions
 ShowComponentConfigurationNames
 ShowComponentDescriptions
 ShowComponentNames
 ShowDisplayStateNames
 ShowFeatureDescription
 ShowFeatureDetails
 ShowFeatureName
 ShowHierarchyOnly
 SolidForTrim
 ViewDependencies
 ViewFeatures

SOLIDWORKS Type Library

AddCornerReliefCorner Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function AddCornerReliefCorner() As Long
```

SOLIDWORKS Type Library

AddCornerReliefType Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function AddCornerReliefType( _
    ByVal CornerIndex As Long, _
    ByVal ReliefType As Long, _
    ByVal Length1 As Double, _
    ByVal Length2 As Double, _
    ByVal Length3 As Double, _
    ByVal CenterOnBendLines As Boolean, _
    ByVal RatioToThickness As Boolean, _
    ByVal TangentToBend As Boolean, _
    ByVal AddFillettedCorners As Boolean, _
    ByVal NarrowCorner As Boolean _
) As Boolean
```

SOLIDWORKS Type Library

AddSMNormalCut Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function AddSMNormalCut() As Long
```

SOLIDWORKS Type Library

AddSMNormalCutType Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub AddSMNormalCutType( _  
    ByVal AutoPropagation As Boolean, _  
    ByVal Optimize As Boolean, _  
    ByVal BExtent As Boolean _  
)
```

SOLIDWORKS Type Library

AddVariablePitchHelixFirstPitchAndDiameter Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function AddVariablePitchHelixFirstPitchAndDiameter( _  
    ByVal FirstPitch As Double, _  
    ByVal FirstDiameter As Double _  
) As Boolean
```

SOLIDWORKS Type Library

AddVariablePitchHelixSegment Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function AddVariablePitchHelixSegment( _  
    ByVal Height As Double, _  
    ByVal Diameter As Double, _  
    ByVal Pitch As Double _  
) As Boolean
```

SOLIDWORKS Type Library

AdvancedHole Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function AdvancedHole( _  
    ByVal AdvancedHoleNearElementArray As Variant, _  
    ByVal AdvancedHoleFarElementArray As Variant, _  
    ByVal UseBaselineDimensions As Boolean, _  
    ByVal IsCustomCallout As Boolean, _  
    ByRef ResultArray As Variant _  
) As Feature
```

SOLIDWORKS Type Library

AdvancedHole2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function AdvancedHole2( _  
    ByVal AdvancedHoleNearElementArray As Variant, _  
    ByVal AdvancedHoleFarElementArray As Variant, _  
    ByVal UseBaselineDimensions As Boolean, _  
    ByVal IsCustomCallout As Boolean, _  
    ByVal IsDepthUptoTip As Boolean, _  
    ByRef ResultArray As Variant _  
) As Feature
```

SOLIDWORKS Type Library

ComponentPrimaryIdentifier Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property ComponentPrimaryIdentifier As Long
```

SOLIDWORKS Type Library

ComponentSecondaryIdentifier Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property ComponentSecondaryIdentifier As Long
```

SOLIDWORKS Type Library

ComponentTertiaryIdentifier Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property ComponentTertiaryIdentifier As Long
```

SOLIDWORKS Type Library

ConvertLoftOrSweepToNetBlend Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function ConvertLoftOrSweepToNetBlend() As Feature
```

SOLIDWORKS Type Library

CreateCoordinateSystem Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateCoordinateSystem( _  
    ByVal OriginPointEntity As Object, _  
    ByVal XAxisEntities As Variant, _  
    ByVal YAxisEntities As Variant, _  
    ByVal ZAxisEntities As Variant _  
) As Feature
```

SOLIDWORKS Type Library

CreateCoordinateSystemUsingNumericalValues Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateCoordinateSystemUsingNumericalValues( _  
    ByVal UseLocation As Boolean, _  
    ByVal DeltaX As Double, _  
    ByVal DeltaY As Double, _  
    ByVal DeltaZ As Double, _  
    ByVal UseRotation As Boolean, _  
    ByVal AngleX As Double, _  
    ByVal AngleY As Double, _  
    ByVal AngleZ As Double _  
) As Feature
```

SOLIDWORKS Type Library

CreateCustomBendAllowance Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateCustomBendAllowance() As CustomBendAllowance
```

SOLIDWORKS Type Library

CreateDefinition Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateDefinition( _  
    ByVal Type As Long _  
) As Object
```

SOLIDWORKS Type Library

CreateFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateFeature( _  
    ByVal FeatureData As Object _  
) As Feature
```

SOLIDWORKS Type Library

CreateFormTool Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateFormTool() As Feature
```

SOLIDWORKS Type Library

CreateFormTool2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateFormTool2( _  
    ByVal OriginX As Double, _  
    ByVal OriginY As Double _  
) As Feature
```

SOLIDWORKS Type Library

CreateSaveBodyFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateSaveBodyFeature( _  
    ByVal Bodies As Variant, _  
    ByVal FilePaths As Variant, _  
    ByVal AssemName As String, _  
    ByVal ConsumeBody As Boolean, _  
    ByVal CopyCustomProperty As Boolean _  
) As Object
```

SOLIDWORKS Type Library

CreateStructuralMemberGroup Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CreateStructuralMemberGroup() As StructuralMemberGroup
```

SOLIDWORKS Type Library

CutListFolderLocation Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function CutListFolderLocation( _  
    ByVal QueryObj As Object _  
) As Object
```

Document Property (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Property Document As ModelDoc2
```

DraftXpertChange Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function DraftXpertChange( _  
    ByVal Angle As Double, _  
    ByVal FlipDir As Boolean, _  
    ByVal EdgeDraft As Boolean, _  
    ByVal PropType As Long, _  
    ByVal IsStepDraft As Boolean, _  
    ByVal IsBodyDraft As Boolean _  
) As Feature
```

DraftXpertRemove Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function DraftXpertRemove() As Feature
```

EditDeleteFace Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function EditDeleteFace( _  
    ByVal Refill As Long _  
) As Boolean
```

EditFreeze Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function EditFreeze( _  
    ByVal Location As Long, _  
    ByVal FeatureName As String, _  
    ByVal UpdateAllConfigs As Boolean _  
) As Long
```

EditFreeze2 Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function EditFreeze2( _  
    ByVal Location As Long, _  
    ByVal FeatureName As String, _  
    ByVal UpdateAllConfigs As Boolean, _  
    ByVal UnlockConfigs As Boolean _  
) As Long
```

EditReferencePoint Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function EditReferencePoint( _  
    ByVal NRefPointType As Long, _  
    ByVal NRefPointAlongCurveType As Long, _  
    ByVal DDistance_or_Percent As Double, _  
    ByVal NumberOfRefPoints As Long _  
    ) As Boolean
```

EditRollback Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function EditRollback( _  
    ByVal Location As Long, _  
    ByVal Feature As String _  
    ) As Boolean
```

EnableFeatureTree Property (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Property EnableFeatureTree As Boolean
```

EnableFeatureTreeWindow Property (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Property EnableFeatureTreeWindow As Boolean
```

EndVariablePitchHelix Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function EndVariablePitchHelix() As Feature
```

ExpandFeature Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function ExpandFeature( _  
    ByVal Component As Object, _  
    ByVal FeatureName As String, _  
    ByVal WhichPane As Long _  
    ) As Boolean
```

FeatureAdvancedTableDrivenPattern Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

Public Function FeatureAdvancedTableDrivenPattern() As [Feature](#)

SOLIDWORKS Type Library

FeatureBossThicken Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureBossThicken( _  
    ByVal Thickness As Double, _  
    ByVal Direction As Long, _  
    ByVal FaceIndex As Long, _  
    ByVal FillVolume As Boolean, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureChainPattern Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureChainPattern( _  
    ByVal PitchMethod As Long, _  
    ByVal FlipDirection As Boolean, _  
    ByVal FillPath As Boolean, _  
    ByVal Number As Long, _  
    ByVal Spacing As Double, _  
    ByVal GroupOneFlipPlane As Boolean, _  
    ByVal GroupTwoChain As Boolean, _  
    ByVal GroupTwoFlipPlane As Boolean, _  
    ByVal AlignMethod As Long, _  
    ByVal Options As Long _  
) As Feature
```

SOLIDWORKS Type Library

FeatureCircularPattern Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureCircularPattern( _  
    ByVal Num As Long, _  
    ByVal Spacing As Double, _  
    ByVal FlipDir As Boolean, _  
    ByVal DName As String _  
) As Feature
```

SOLIDWORKS Type Library

FeatureCircularPattern2 Method (FeatureManager)

 Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureCircularPattern2( _  
    ByVal Num As Long, _  
    ByVal Spacing As Double, _  
    ByVal FlipDir As Boolean, _  
    ByVal DName As String, _  
    ByVal GeometryPattern As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureCircularPattern3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureCircularPattern3( _  
    ByVal Number As Long, _  
    ByVal Spacing As Double, _  
    ByVal FlipDirection As Boolean, _  
    ByVal DName As String, _  
    ByVal GeometryPattern As Boolean, _  
    ByVal EqualSpacing As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureCircularPattern4 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureCircularPattern4( _  
    ByVal Number As Long, _  
    ByVal Spacing As Double, _  
    ByVal FlipDirection As Boolean, _  
    ByVal DName As String, _  
    ByVal GeometryPattern As Boolean, _  
    ByVal EqualSpacing As Boolean, _  
    ByVal VaryInstance As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureCircularPattern5 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureCircularPattern5( _  
    ByVal Number As Long, _  
    ByVal Spacing As Double, _  
    ByVal FlipDirection As Boolean, _  
    ByVal DName As String, _  
    ByVal GeometryPattern As Boolean, _  
    ByVal EqualSpacing As Boolean, _  
    ByVal VaryInstance As Boolean, _  
    ByVal SyncSubAssemblies As Boolean, _  
    ByVal BDir2 As Boolean, _  
    ByVal BSymmetric As Boolean, _  
    ByVal Number2 As Long, _  
    ByVal Spacing2 As Double, _  
    ByVal DName2 As String, _  
    ByVal EqualSpacing2 As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureCut Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureCut( _  
    ByVal Sd As Boolean, _  
    ByVal Flip As Boolean, _  
    ByVal Dir As Boolean, _  
    ByVal T1 As Long, _  
    ByVal T2 As Long, _  
    ByVal D1 As Double, _  
    ByVal D2 As Double, _  
    ByVal Dchk1 As Boolean, _  
    ByVal Dchk2 As Boolean, _  
    ByVal Ddir1 As Boolean, _
```

```

ByVal Ddir2 As Boolean, _
ByVal Dang1 As Double, _
ByVal Dang2 As Double, _
ByVal OffsetReverse1 As Boolean, _
ByVal OffsetReverse2 As Boolean, _
ByVal TranslateSurface1 As Boolean, _
ByVal TranslateSurface2 As Boolean, _
ByVal NormalCut As Boolean, _
ByVal UseFeatScope As Boolean, _
ByVal UseAutoSelect As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureCut2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureCut2( _
    ByVal Sd As Boolean, _
    ByVal Flip As Boolean, _
    ByVal Dir As Boolean, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal NormalCut As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
    ByVal PropagateFeatureToParts As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureCut3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureCut3( _
    ByVal Sd As Boolean, _
    ByVal Flip As Boolean, _
    ByVal Dir As Boolean, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal NormalCut As Boolean, _

```

```

    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
    ByVal PropagateFeatureToParts As Boolean, _
    ByVal T0 As Long, _
    ByVal StartOffset As Double, _
    ByVal FlipStartOffset As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureCut4 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureCut4( _
    ByVal Sd As Boolean, _
    ByVal Flip As Boolean, _
    ByVal Dir As Boolean, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal NormalCut As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
    ByVal PropagateFeatureToParts As Boolean, _
    ByVal T0 As Long, _
    ByVal StartOffset As Double, _
    ByVal FlipStartOffset As Boolean, _
    ByVal OptimizeGeometry As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureCutThicken Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureCutThicken( _
    ByVal Thickness As Double, _
    ByVal Direction As Long, _
    ByVal FaceIndex As Long, _
    ByVal FillVolume As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureCutThin Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureCutThin( _
    ByVal Sd As Boolean, _
    ByVal Flip As Boolean, _
    ByVal Dir As Boolean, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal Thk1 As Double, _
    ByVal Thk2 As Double, _
    ByVal EndThk As Double, _
    ByVal RevThinDir As Long, _
    ByVal CapEnds As Long, _
    ByVal AddBends As Boolean, _
    ByVal BendRad As Double, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureCutThin2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```

Public Function FeatureCutThin2( _
    ByVal Sd As Boolean, _
    ByVal Flip As Boolean, _
    ByVal Dir As Boolean, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal Thk1 As Double, _
    ByVal Thk2 As Double, _
    ByVal EndThk As Double, _
    ByVal RevThinDir As Long, _
    ByVal CapEnds As Long, _
    ByVal AddBends As Boolean, _
    ByVal BendRad As Double, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal T0 As Long, _
    ByVal StartOffset As Double, _
    ByVal FlipStartOffset As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureDimensionPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureDimensionPattern( _  
    ByVal Num1 As Long, _  
    ByVal Spacing1 As Double, _  
    ByVal Num2 As Long, _  
    ByVal Spacing2 As Double, _  
    ByVal DiagonalOnly As Boolean, _  
    ByVal DName1 As String, _  
    ByVal DName2 As String, _  
    ByVal VaryInstance As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureExtruRefSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub FeatureExtruRefSurface( _  
    ByVal Sd As Boolean, _  
    ByVal Flip As Boolean, _  
    ByVal Dir As Boolean, _  
    ByVal T1 As Long, _  
    ByVal T2 As Long, _  
    ByVal D1 As Double, _  
    ByVal D2 As Double, _  
    ByVal Dchk1 As Boolean, _  
    ByVal Dchk2 As Boolean, _  
    ByVal Ddir1 As Boolean, _  
    ByVal Ddir2 As Boolean, _  
    ByVal Dang1 As Double, _  
    ByVal Dang2 As Double, _  
    ByVal OffsetReverse1 As Boolean, _  
    ByVal OffsetReverse2 As Boolean, _  
    ByVal TranslateSurface1 As Boolean, _  
    ByVal TranslateSurface2 As Boolean, _  
    ByVal CapEnd1 As Boolean, _  
    ByVal CapEnd2 As Boolean, _  
    ByVal DeleteOriginalFace As Boolean, _  
    ByVal KnitResult As Boolean _  
)
```

SOLIDWORKS Type Library

FeatureExtruRefSurface2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub FeatureExtruRefSurface2( _  
    ByVal Sd As Boolean, _  
    ByVal Flip As Boolean, _  
    ByVal Dir As Boolean, _  
    ByVal T1 As Long, _  
    ByVal T2 As Long, _  
    ByVal D1 As Double, _  
    ByVal D2 As Double, _  
    ByVal Dchk1 As Boolean, _  
    ByVal Dchk2 As Boolean, _  
    ByVal Ddir1 As Boolean, _  
    ByVal Ddir2 As Boolean, _  
    ByVal Dang1 As Double, _  
    ByVal Dang2 As Double, _  
    ByVal OffsetReverse1 As Boolean, _  
    ByVal OffsetReverse2 As Boolean, _  
    ByVal TranslateSurface1 As Boolean, _
```

```

    ByVal TranslateSurface2 As Boolean, _
    ByVal CapEnd1 As Boolean, _
    ByVal CapEnd2 As Boolean, _
    ByVal DeleteOriginalFace As Boolean, _
    ByVal KnitResult As Boolean _
)

```

SOLIDWORKS Type Library

FeatureExtruRefSurface3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Sub FeatureExtruRefSurface3( _
    ByVal Sd As Boolean, _
    ByVal Dir As Boolean, _
    ByVal StartCond As Long, _
    ByVal OffsetVal As Double, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal CapEnd1 As Boolean, _
    ByVal CapEnd2 As Boolean, _
    ByVal DeleteOriginalFace As Boolean, _
    ByVal KnitResult As Boolean _
)

```

SOLIDWORKS Type Library

FeatureExtrusion Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureExtrusion( _
    ByVal Sd As Boolean, _
    ByVal Flip As Boolean, _
    ByVal Dir As Boolean, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal Merge As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureExtrusion2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function FeatureExtrusion2( _  
    ByVal Sd As Boolean, _  
    ByVal Flip As Boolean, _  
    ByVal Dir As Boolean, _  
    ByVal T1 As Long, _  
    ByVal T2 As Long, _  
    ByVal D1 As Double, _  
    ByVal D2 As Double, _  
    ByVal Dchk1 As Boolean, _  
    ByVal Dchk2 As Boolean, _  
    ByVal Ddir1 As Boolean, _  
    ByVal Ddir2 As Boolean, _  
    ByVal Dang1 As Double, _  
    ByVal Dang2 As Double, _  
    ByVal OffsetReverse1 As Boolean, _  
    ByVal OffsetReverse2 As Boolean, _  
    ByVal TranslateSurface1 As Boolean, _  
    ByVal TranslateSurface2 As Boolean, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _  
    ByVal T0 As Long, _  
    ByVal StartOffset As Double, _  
    ByVal FlipStartOffset As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureExtrusion3 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function FeatureExtrusion3( _  
    ByVal Sd As Boolean, _  
    ByVal Flip As Boolean, _  
    ByVal Dir As Boolean, _  
    ByVal T1 As Long, _  
    ByVal T2 As Long, _  
    ByVal D1 As Double, _  
    ByVal D2 As Double, _  
    ByVal Dchk1 As Boolean, _  
    ByVal Dchk2 As Boolean, _  
    ByVal Ddir1 As Boolean, _  
    ByVal Ddir2 As Boolean, _  
    ByVal Dang1 As Double, _  
    ByVal Dang2 As Double, _  
    ByVal OffsetReverse1 As Boolean, _  
    ByVal OffsetReverse2 As Boolean, _  
    ByVal TranslateSurface1 As Boolean, _  
    ByVal TranslateSurface2 As Boolean, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _  
    ByVal T0 As Long, _  
    ByVal StartOffset As Double, _  
    ByVal FlipStartOffset As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureExtrusionThin Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function FeatureExtrusionThin( _  
    ByVal Sd As Boolean, _
```

```

ByVal Flip As Boolean, _
ByVal Dir As Boolean, _
ByVal T1 As Long, _
ByVal T2 As Long, _
ByVal D1 As Double, _
ByVal D2 As Double, _
ByVal Dchk1 As Boolean, _
ByVal Dchk2 As Boolean, _
ByVal Ddir1 As Boolean, _
ByVal Ddir2 As Boolean, _
ByVal Dang1 As Double, _
ByVal Dang2 As Double, _
ByVal OffsetReverse1 As Boolean, _
ByVal OffsetReverse2 As Boolean, _
ByVal TranslateSurface1 As Boolean, _
ByVal TranslateSurface2 As Boolean, _
ByVal Merge As Boolean, _
ByVal Thk1 As Double, _
ByVal Thk2 As Double, _
ByVal EndThk As Double, _
ByVal RevThinDir As Long, _
ByVal CapEnds As Long, _
ByVal AddBends As Boolean, _
ByVal BendRad As Double, _
ByVal UseFeatScope As Boolean, _
ByVal UseAutoSelect As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureExtrusionThin2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureExtrusionThin2( _
    ByVal Sd As Boolean, _
    ByVal Flip As Boolean, _
    ByVal Dir As Boolean, _
    ByVal T1 As Long, _
    ByVal T2 As Long, _
    ByVal D1 As Double, _
    ByVal D2 As Double, _
    ByVal Dchk1 As Boolean, _
    ByVal Dchk2 As Boolean, _
    ByVal Ddir1 As Boolean, _
    ByVal Ddir2 As Boolean, _
    ByVal Dang1 As Double, _
    ByVal Dang2 As Double, _
    ByVal OffsetReverse1 As Boolean, _
    ByVal OffsetReverse2 As Boolean, _
    ByVal TranslateSurface1 As Boolean, _
    ByVal TranslateSurface2 As Boolean, _
    ByVal Merge As Boolean, _
    ByVal Thk1 As Double, _
    ByVal Thk2 As Double, _
    ByVal EndThk As Double, _
    ByVal RevThinDir As Long, _
    ByVal CapEnds As Long, _
    ByVal AddBends As Boolean, _
    ByVal BendRad As Double, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal T0 As Long, _
    ByVal StartOffset As Double, _
    ByVal FlipStartOffset As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureFillet Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureFillet( _  
    ByVal Options As Long, _  
    ByVal R1 As Double, _  
    ByVal Ftyp As Long, _  
    ByVal OverflowType As Long, _  
    ByVal Radii As Variant, _  
    ByVal SetBackDistances As Variant, _  
    ByVal PointRadiusArray As Variant _  
) As Object
```

SOLIDWORKS Type Library

FeatureFillet2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureFillet2( _  
    ByVal Options As Long, _  
    ByVal R1 As Double, _  
    ByVal Rho As Double, _  
    ByVal Ftyp As Long, _  
    ByVal OverflowType As Long, _  
    ByVal ConicRhoType As Long, _  
    ByVal Radii As Variant, _  
    ByVal RhoArr As Variant, _  
    ByVal SetBackDistances As Variant, _  
    ByVal PointRadiusArray As Variant, _  
    ByVal PointRhoArray As Variant _  
) As Object
```

SOLIDWORKS Type Library

FeatureFillet3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureFillet3( _  
    ByVal Options As Long, _  
    ByVal R1 As Double, _  
    ByVal R2 As Double, _  
    ByVal Rho As Double, _  
    ByVal Ftyp As Long, _  
    ByVal OverflowType As Long, _  
    ByVal ConicRhoType As Long, _  
    ByVal Radii As Variant, _  
    ByVal Dist2Arr As Variant, _  
    ByVal RhoArr As Variant, _  
    ByVal SetBackDistances As Variant, _  
    ByVal PointRadiusArray As Variant, _  
    ByVal PointDist2Array As Variant, _  
    ByVal PointRhoArray As Variant _  
) As Object
```

SOLIDWORKS Type Library

FeatureFillPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureFillPattern( _  
    ByVal PatternLayoutType As Long, _  
    ByVal LayoutSpacingType As Long, _  
    ByVal InstanceSpacing As Double, _  
    ByVal StaggerAngle As Double, _  
    ByVal Margins As Double, _
```

```

    ByVal LoopSpacing As Double, _
    ByVal NoOfInstances As Long, _
    ByVal PatternLayoutPolygonSides As Long, _
    ByVal FeaturesToPatternType As Long, _
    ByVal CreateSeedCutType As Long, _
    ByVal Diameter As Double, _
    ByVal Dimension As Double, _
    ByVal Rotation As Double, _
    ByVal Diagonal As Double, _
    ByVal CreateSeedCutPolygonSides As Long, _
    ByVal OuterRadius As Double, _
    ByVal InnerRadius As Double, _
    ByVal FlipShapeDirection As Boolean, _
    ByVal GeometryPattern As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureFolderLocation Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureFolderLocation( _
    ByVal Feature As Feature _
) As Feature

```

SOLIDWORKS Type Library

FeatureLinearPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureLinearPattern( _
    ByVal Num1 As Long, _
    ByVal Spacing1 As Double, _
    ByVal Num2 As Long, _
    ByVal Spacing2 As Double, _
    ByVal FlipDir1 As Boolean, _
    ByVal FlipDir2 As Boolean, _
    ByVal DName1 As String, _
    ByVal DName2 As String _
) As Feature

```

SOLIDWORKS Type Library

FeatureLinearPattern2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function FeatureLinearPattern2( _
    ByVal Num1 As Long, _
    ByVal Spacing1 As Double, _
    ByVal Num2 As Long, _
    ByVal Spacing2 As Double, _
    ByVal FlipDir1 As Boolean, _
    ByVal FlipDir2 As Boolean, _
    ByVal DName1 As String, _
    ByVal DName2 As String, _
    ByVal GeometryPattern As Boolean _
) As Feature

```

SOLIDWORKS Type Library

FeatureLinearPattern3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureLinearPattern3( _
    ByVal Num1 As Long, _
    ByVal Spacing1 As Double, _
    ByVal Num2 As Long, _
    ByVal Spacing2 As Double, _
    ByVal FlipDir1 As Boolean, _
    ByVal FlipDir2 As Boolean, _
    ByVal DName1 As String, _
    ByVal DName2 As String, _
    ByVal GeometryPattern As Boolean, _
    ByVal VaryInstance As Boolean _
) As Feature
```

SOLIDWORKS Type Library

FeatureLinearPattern4 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureLinearPattern4( _
    ByVal Num1 As Long, _
    ByVal Spacing1 As Double, _
    ByVal Num2 As Long, _
    ByVal Spacing2 As Double, _
    ByVal FlipDir1 As Boolean, _
    ByVal FlipDir2 As Boolean, _
    ByVal DName1 As String, _
    ByVal DName2 As String, _
    ByVal GeometryPattern As Boolean, _
    ByVal VaryInstance As Boolean, _
    ByVal HasOffset1 As Boolean, _
    ByVal HasOffset2 As Boolean, _
    ByVal CtrlByNum1 As Boolean, _
    ByVal CtrlByNum2 As Boolean, _
    ByVal FromCentroid1 As Boolean, _
    ByVal FromCentroid2 As Boolean, _
    ByVal RevOffset1 As Boolean, _
    ByVal RevOffset2 As Boolean, _
    ByVal Offset1 As Double, _
    ByVal Offset2 As Double _
) As Feature
```

SOLIDWORKS Type Library

FeatureLinearPattern5 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureLinearPattern5( _
    ByVal Num1 As Long, _
    ByVal Spacing1 As Double, _
    ByVal Num2 As Long, _
    ByVal Spacing2 As Double, _
    ByVal FlipDir1 As Boolean, _
    ByVal FlipDir2 As Boolean, _
    ByVal DName1 As String, _
    ByVal DName2 As String, _
    ByVal GeometryPattern As Boolean, _
    ByVal VaryInstance As Boolean, _
    ByVal HasOffset1 As Boolean, _
    ByVal HasOffset2 As Boolean, _
    ByVal CtrlByNum1 As Boolean, _
    ByVal CtrlByNum2 As Boolean, _
    ByVal FromCentroid1 As Boolean, _
    ByVal FromCentroid2 As Boolean, _
    ByVal RevOffset1 As Boolean, _
    ByVal RevOffset2 As Boolean, _
    ByVal Offset1 As Double, _
```

```
ByVal Offset2 As Double, _  
ByVal D2PatternSeedOnly As Boolean, _  
ByVal SyncSubAssemblies As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureLocalCurveDrivenPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureLocalCurveDrivenPattern( _  
    ByVal FlipDir1 As Boolean, _  
    ByVal Num1 As Long, _  
    ByVal EqualSpacing1 As Boolean, _  
    ByVal Spacing1 As Double, _  
    ByVal ReferencePoint As Long, _  
    ByVal CurveMethod As Long, _  
    ByVal AlignMethod As Long, _  
    ByVal Direction2 As Boolean, _  
    ByVal FlipDir2 As Boolean, _  
    ByVal Num2 As Long, _  
    ByVal EqualSpacing2 As Boolean, _  
    ByVal Spacing2 As Double, _  
    ByVal PatternSeedOnly As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureLocalSketchDrivenPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureLocalSketchDrivenPattern( _  
    ByVal ReferencePoint As Long _  
) As Feature
```

SOLIDWORKS Type Library

FeatureName Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property FeatureName( _  
    ByVal NameID As Long _  
) As String
```

SOLIDWORKS Type Library

FeatureRevolve Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureRevolve( _  
    ByVal Angle As Double, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle2 As Double, _  
    ByVal RevType As Long, _  
    ByVal Options As Long, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSel As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureRevolve2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function FeatureRevolve2( _  
    ByVal SingleDir As Boolean, _  
    ByVal IsSolid As Boolean, _  
    ByVal IsThin As Boolean, _  
    ByVal IsCut As Boolean, _  
    ByVal ReverseDir As Boolean, _  
    ByVal BothDirectionUpToSameEntity As Boolean, _  
    ByVal Dir1Type As Long, _  
    ByVal Dir2Type As Long, _  
    ByVal Dir1Angle As Double, _  
    ByVal Dir2Angle As Double, _  
    ByVal OffsetReverse1 As Boolean, _  
    ByVal OffsetReverse2 As Boolean, _  
    ByVal OffsetDistance1 As Double, _  
    ByVal OffsetDistance2 As Double, _  
    ByVal ThinType As Long, _  
    ByVal ThinThickness1 As Double, _  
    ByVal ThinThickness2 As Double, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureRevolveCut Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function FeatureRevolveCut( _  
    ByVal Angle As Double, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle2 As Double, _  
    ByVal RevType As Long, _  
    ByVal Options As Long, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureRevolveCut2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function FeatureRevolveCut2( _  
    ByVal Angle As Double, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle2 As Double, _  
    ByVal RevType As Long, _  
    ByVal Options As Long, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _  
    ByVal AssemblyFeatureScope As Boolean, _  
    ByVal AutoSelectComponents As Boolean, _  
    ByVal PropagateFeatureToParts As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureRevolveThin Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function FeatureRevolveThin( _  
    ByVal Angle As Double, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle2 As Double, _  
    ByVal RevType As Long, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ReverseThinDir As Long, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureRevolveThinCut Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureRevolveThinCut( _  
    ByVal Angle As Double, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle2 As Double, _  
    ByVal RevType As Long, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ReverseThinDir As Long, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureSketchDrivenPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FeatureSketchDrivenPattern( _  
    ByVal UseCentroid As Boolean, _  
    ByVal BGeomPatt As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

FeatureStatistics Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property FeatureStatistics As FeatureStatistics
```

SOLIDWORKS Type Library

FilletXpertChange Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function FilletXpertChange( _  
    ByVal Options As Long, _  
    ByVal R1 As Double, _  
    ByVal Ftyp As Long, _  
    ByVal OverflowType As Long _  
) As Feature
```

SOLIDWORKS Type Library

FilletXpertMakeCorner Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function FilletXpertMakeCorner( _  
    ByVal CornerType As Long _  
) As Feature
```

SOLIDWORKS Type Library

FilletXpertRemove Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function FilletXpertRemove() As Feature
```

SOLIDWORKS Type Library

FinishCornerRelief Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function FinishCornerRelief() As Feature
```

SOLIDWORKS Type Library

FinishSMNormalCut Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function FinishSMNormalCut() As Object
```

SOLIDWORKS Type Library

GetCornerManagementFolders Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function GetCornerManagementFolders() As Variant
```

SOLIDWORKS Type Library

GetCreateFeatureErrors Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function GetCreateFeatureErrors( _  
    ByRef Msgs As Variant, _  
    ByRef FeatureTypeName As String _  
) As Long
```

SOLIDWORKS Type Library

GetFeatureCount Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function GetFeatureCount( _  
    ByVal ToplevelOnly As Boolean _  
) As Long
```

SOLIDWORKS Type Library

GetFeatures Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function GetFeatures( _  
    ByVal ToplevelOnly As Boolean _  
    ) As Variant
```

SOLIDWORKS Type Library

GetFeatureTreeRootItem Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetFeatureTreeRootItem() As TreeControlItem
```

SOLIDWORKS Type Library

GetFeatureTreeRootItem2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetFeatureTreeRootItem2( _  
    ByVal WhichPane As Long _  
    ) As TreeControlItem
```

SOLIDWORKS Type Library

GetFlatPatternFolder Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetFlatPatternFolder() As Object
```

SOLIDWORKS Type Library

GetFreezeLocation Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetFreezeLocation() As Feature
```

SOLIDWORKS Type Library

GetPlasticsShellType Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetPlasticsShellType() As Integer
```

SOLIDWORKS Type Library

GetPreTrimmedBodies Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetPreTrimmedBodies( _  
    ByVal TargetSurface As Body2 _  
    ) As Variant
```

SOLIDWORKS Type Library

GetSelectionSetFolder Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetSelectionSetFolder() As Object
```

SOLIDWORKS Type Library

GetSheetMetalFolder Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetSheetMetalFolder() As Object
```

SOLIDWORKS Type Library

GetSlicingData Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetSlicingData() As Object
```

SOLIDWORKS Type Library

GetStructureSystemFolders Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function GetStructureSystemFolders() As Variant
```

SOLIDWORKS Type Library

GroupComponentInstances Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property GroupComponentInstances As Boolean
```

SOLIDWORKS Type Library

HideBodies Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub HideBodies()
```

SOLIDWORKS Type Library

HideComponentSingleConfigurationOrDisplayStateNames Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property HideComponentSingleConfigurationOrDisplayStateNames As Boolean
```

SOLIDWORKS Type Library

HoleWizard Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function HoleWizard( _  
    ByVal GenericHoleType As Long, _  
    ByVal StandardIndex As Long, _  
    ByVal FastenerTypeIndex As Long, _  
    ByVal SSize As String, _  
    ByVal EndType As Integer, _  
    ByVal Diameter As Double, _  
    ByVal Depth As Double, _  
    ByVal Value1 As Double, _  
    ByVal Value2 As Double, _  
    ByVal Value3 As Double, _  
    ByVal Value4 As Double, _
```

```

    ByVal Value5 As Double, _
    ByVal Value6 As Double, _
    ByVal Value7 As Double, _
    ByVal Value8 As Double, _
    ByVal Value9 As Double, _
    ByVal Value10 As Double, _
    ByVal Value11 As Double, _
    ByVal Value12 As Double _
) As Feature

```

SOLIDWORKS Type Library

HoleWizard2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function HoleWizard2( _
    ByVal GenericHoleType As Long, _
    ByVal StandardIndex As Long, _
    ByVal FastenerTypeIndex As Long, _
    ByVal SSize As String, _
    ByVal EndType As Integer, _
    ByVal Diameter As Double, _
    ByVal Depth As Double, _
    ByVal Value1 As Double, _
    ByVal Value2 As Double, _
    ByVal Value3 As Double, _
    ByVal Value4 As Double, _
    ByVal Value5 As Double, _
    ByVal Value6 As Double, _
    ByVal Value7 As Double, _
    ByVal Value8 As Double, _
    ByVal Value9 As Double, _
    ByVal Value10 As Double, _
    ByVal Value11 As Double, _
    ByVal Value12 As Double, _
    ByVal ThreadClass As String, _
    ByVal RevDir As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean _
) As Feature

```

SOLIDWORKS Type Library

HoleWizard3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function HoleWizard3( _
    ByVal GenericHoleType As Long, _
    ByVal StandardIndex As Long, _
    ByVal FastenerTypeIndex As Long, _
    ByVal SSize As String, _
    ByVal EndType As Integer, _
    ByVal Diameter As Double, _
    ByVal Depth As Double, _
    ByVal Value1 As Double, _
    ByVal Value2 As Double, _
    ByVal Value3 As Double, _
    ByVal Value4 As Double, _
    ByVal Value5 As Double, _
    ByVal Value6 As Double, _
    ByVal Value7 As Double, _
    ByVal Value8 As Double, _
    ByVal Value9 As Double, _
    ByVal Value10 As Double, _
    ByVal Value11 As Double, _

```

```

    ByVal Value12 As Double, _
    ByVal ThreadClass As String, _
    ByVal RevDir As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
    ByVal PropagateFeatureToParts As Boolean _
) As Feature

```

SOLIDWORKS Type Library

HoleWizard4 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function HoleWizard4( _
    ByVal GenericHoleType As Long, _
    ByVal StandardIndex As Long, _
    ByVal FastenerTypeIndex As Long, _
    ByVal SSize As String, _
    ByVal EndType As Integer, _
    ByVal Diameter As Double, _
    ByVal Depth As Double, _
    ByVal Value1 As Double, _
    ByVal Value2 As Double, _
    ByVal Value3 As Double, _
    ByVal Value4 As Double, _
    ByVal Value5 As Double, _
    ByVal Value6 As Double, _
    ByVal Value7 As Double, _
    ByVal Value8 As Double, _
    ByVal Value9 As Double, _
    ByVal Value10 As Double, _
    ByVal Value11 As Double, _
    ByVal Value12 As Double, _
    ByVal ThreadClass As String, _
    ByVal RevDir As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
    ByVal PropagateFeatureToParts As Boolean _
) As Feature

```

SOLIDWORKS Type Library

HoleWizard5 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function HoleWizard5( _
    ByVal GenericHoleType As Long, _
    ByVal StandardIndex As Long, _
    ByVal FastenerTypeIndex As Long, _
    ByVal SSize As String, _
    ByVal EndType As Integer, _
    ByVal Diameter As Double, _
    ByVal Depth As Double, _
    ByVal Length As Double, _
    ByVal Value1 As Double, _
    ByVal Value2 As Double, _
    ByVal Value3 As Double, _
    ByVal Value4 As Double, _
    ByVal Value5 As Double, _
    ByVal Value6 As Double, _
    ByVal Value7 As Double, _
    ByVal Value8 As Double, _
    ByVal Value9 As Double, _
)

```

```

    ByVal Value10 As Double, _
    ByVal Value11 As Double, _
    ByVal Value12 As Double, _
    ByVal ThreadClass As String, _
    ByVal RevDir As Boolean, _
    ByVal FeatureScope As Boolean, _
    ByVal AutoSelect As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
    ByVal PropagateFeatureToParts As Boolean _
) As Feature

```

SOLIDWORKS Type Library

IFeatureFillet Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function IFeatureFillet( _
    ByVal Options As Long, _
    ByVal R1 As Double, _
    ByVal Ftyp As Long, _
    ByVal OverflowType As Long, _
    ByVal NRadii As Long, _
    ByRef Radii As Double, _
    ByVal SetbackDistCount As Long, _
    ByRef SetBackDistances As Double, _
    ByVal PointCount As Long, _
    ByRef PointRadiusArray As Double _
) As Feature

```

SOLIDWORKS Type Library

IFeatureFillet2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function IFeatureFillet2( _
    ByVal Options As Long, _
    ByVal R1 As Double, _
    ByVal Rho As Double, _
    ByVal Ftyp As Long, _
    ByVal OverflowType As Long, _
    ByVal ConicRhoType As Long, _
    ByVal NRadii As Long, _
    ByRef Radii As Double, _
    ByRef RhoArr As Double, _
    ByVal SetbackDistCount As Long, _
    ByRef SetBackDistances As Double, _
    ByVal PointCount As Long, _
    ByRef PointRadiusArray As Double, _
    ByRef PointRhoArray As Double _
) As Feature

```

SOLIDWORKS Type Library

IGetFeatures Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function IGetFeatures( _
    ByVal ToplevelOnly As Boolean, _
    ByVal Count As Long _
) As Feature

```

SOLIDWORKS Type Library

IInsertCombineFeature Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function IInsertCombineFeature( _  
    ByVal OperationType As Long, _  
    ByVal MainBody As Body2, _  
    ByVal ToolsCount As Long, _  
    ByVal ToolsArr As Body2 _  
    ) As Feature
```

SOLIDWORKS Type Library

IInsertMacroFeature Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function IInsertMacroFeature( _  
    ByVal BaseName As String, _  
    ByVal ProgId As String, _  
    ByRef MacroMethods As String, _  
    ByVal ParamCount As Long, _  
    ByRef ParamNames As String, _  
    ByRef ParamTypes As Long, _  
    ByRef ParamValues As String, _  
    ByVal EditBody As Body2, _  
    ByVal Options As Long _  
    ) As Feature
```

SOLIDWORKS Type Library

IInsertMacroFeature2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function IInsertMacroFeature2( _  
    ByVal BaseName As String, _  
    ByVal ProgId As String, _  
    ByRef MacroMethods As String, _  
    ByVal ParamCount As Long, _  
    ByRef ParamNames As String, _  
    ByRef ParamTypes As Long, _  
    ByRef ParamValues As String, _  
    ByVal DimCount As Long, _  
    ByRef DimTypes As Long, _  
    ByRef DimCountValues As Double, _  
    ByVal EditBody As Body2, _  
    ByVal IconCount As Long, _  
    ByRef IconFiles As String, _  
    ByVal Options As Long _  
    ) As Feature
```

SOLIDWORKS Type Library

IInsertMacroFeature3 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function IInsertMacroFeature3( _  
    ByVal BaseName As String, _  
    ByVal ProgId As String, _  
    ByRef MacroMethods As String, _  
    ByVal ParamCount As Long, _  
    ByRef ParamNames As String, _  
    ByRef ParamTypes As Long, _  
    ByRef ParamValues As String, _  
    ByVal DimCount As Long, _  
    ByRef DimTypes As Long, _  
    ByRef DimCountValues As Double, _
```

```
ByVal BodyCount As Long, _  
ByVal EditBodies As Body2, _  
ByVal IconCount As Long, _  
ByRef IconFiles As String, _  
ByVal Options As Long _  
) As Feature
```

SOLIDWORKS Type Library

IInsertMoveFace2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function IInsertMoveFace2( _  
    ByVal MoveType As Long, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle As Double, _  
    ByVal Distance As Double, _  
    ByRef TranslationParams As Double, _  
    ByRef RotationParams As Double _  
) As Feature
```

SOLIDWORKS Type Library

IInsertReferencePoint Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function IInsertReferencePoint( _  
    ByVal NRefPointType As Long, _  
    ByVal NRefPointAlongCurveType As Long, _  
    ByVal DDistance_or_Percent As Double, _  
    ByVal NumberOfRefPoints As Long _  
) As Feature
```

SOLIDWORKS Type Library

IInsertSheetMetalEdgeFlange2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function IInsertSheetMetalEdgeFlange2( _  
    ByVal EdgeCount As Long, _  
    ByVal FlangeEdges As Edge, _  
    ByVal SketchFeatCount As Long, _  
    ByVal SketchFeat As Feature, _  
    ByVal BooleanOptions As Long, _  
    ByVal FlangeAngle As Double, _  
    ByVal FlangeRadius As Double, _  
    ByVal BendPosition As Long, _  
    ByVal FlangeOffsetDist As Double, _  
    ByVal ReliefType As Long, _  
    ByVal FlangeReliefRatio As Double, _  
    ByVal FlangeReliefWidth As Double, _  
    ByVal FlangeReliefDepth As Double, _  
    ByVal FlangeSharpType As Long, _  
    ByVal CustomBendAllowance As CustomBendAllowance _  
) As Feature
```

SOLIDWORKS Type Library

IInsertTableDrivenPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function IInsertTableDrivenPattern( _  
    ByVal FileName As String, _  
    ByVal Count As Long, _
```

```
ByRef PointArr As Double, _  
ByVal UseCentrod As Boolean, _  
ByVal GeomPatt As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertCenterOfMass Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCenterOfMass() As Feature
```

SOLIDWORKS Type Library

InsertCenterOfMassReferencePoint Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCenterOfMassReferencePoint() As Feature
```

SOLIDWORKS Type Library

InsertCombineFeature Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCombineFeature( _  
ByVal OperationType As Long, _  
ByVal MainBody As Body2, _  
ByVal ToolVar As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertConnectionPoint Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertConnectionPoint( _  
ByVal Type As Long, _  
ByVal SubType As Long, _  
ByVal ReverseDirection As Boolean, _  
ByVal Diameter As Double, _  
ByVal StubLength As Double, _  
ByVal MinimumStraight As Double, _  
ByVal EndLengthAdjustment As Double, _  
ByVal ConductorSplitLength As Double, _  
ByVal SchematicPinID As String, _  
ByVal CableWidth As Double, _  
ByVal CableThickness As Double, _  
ByVal SwitchPin1Position As Boolean, _  
ByVal SpecificationFieldName As String, _  
ByVal SpecificationValue As String _  
) As Boolean
```

SOLIDWORKS Type Library

InsertConvertToSheetMetal Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertConvertToSheetMetal( _  
ByVal Thickness As Double, _  
ByVal ReverseThickDir As Boolean, _  
ByVal FindBends As Boolean, _  
ByVal Radius As Double, _
```

```
    ByVal Gap As Double, _  
    ByVal ReliefType As Long, _  
    ByVal ReliefRatio As Double _  
) As Boolean
```