

SOLIDWORKS API (VB6 COM) — Reference (32/102): FeatureManager (part 2 of 3)

SOLIDWORKS API Documentation (converted from CHM)

FeatureManager (part 2 of 3) (Type)

SOLIDWORKS Type Library

InsertConvertToSheetMetal2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertConvertToSheetMetal2( _  
    ByVal Thickness As Double, _  
    ByVal ReverseThickDir As Boolean, _  
    ByVal FindBends As Boolean, _  
    ByVal Radius As Double, _  
    ByVal Gap As Double, _  
    ByVal ReliefType As Long, _  
    ByVal ReliefRatio As Double, _  
    ByVal OverlapType As Long, _  
    ByVal OverlapRatio As Double, _  
    ByVal KeepBody As Boolean _  
) As Boolean
```

SOLIDWORKS Type Library

InsertCoordinateSystem Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertCoordinateSystem( _  
    ByVal XFlippedIn As Boolean, _  
    ByVal YFlippedIn As Boolean, _  
    ByVal ZFlippedIn As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertCosmeticThread Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertCosmeticThread( _  
    ByVal Type As Integer, _  
    ByVal Depth As Double, _  
    ByVal Length As Double, _  
    ByVal Note As String _  
) As String
```

SOLIDWORKS Type Library

InsertCosmeticThread2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertCosmeticThread2( _  
    ByVal Type As Integer, _  
    ByVal Depth As Double, _  
    ByVal Length As Double, _  
    ByVal Note As String _  
) As Feature
```

SOLIDWORKS Type Library

InsertCosmeticThread3 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertCosmeticThread3( _  
    ByVal Standard As Long, _  
    ByVal StandardType As String, _  
    ByVal Size As String, _  
    ByVal Diameter As Double, _  
    ByVal EndType As Long, _  
    ByVal Depth As Double, _  
    ByVal Note As String _  
) As Feature
```

SOLIDWORKS Type Library

InsertCosmeticWeldBead Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCosmeticWeldBead( _  
    ByVal WeldSize As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertCosmeticWeldBead2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCosmeticWeldBead2( _  
    ByVal WeldMode As Long, _  
    ByVal WeldFromFaceOrEdgeSet As Variant, _  
    ByVal WeldToFaceOrEdgeSet As Variant, _  
    ByVal WeldSize As Double _  
) As Variant
```

SOLIDWORKS Type Library

InsertCrossBreak Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCrossBreak( _  
    ByVal Angle As Double, _  
    ByVal Radius As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertCutBlend Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCutBlend( _  
    ByVal Closed As Boolean, _  
    ByVal KeepTangency As Boolean, _  
    ByVal ForceNonRational As Boolean, _  
    ByVal TessToleranceFactor As Double, _  
    ByVal StartMatchingType As Integer, _  
    ByVal EndMatchingType As Integer, _  
    ByVal IsThinBody As Boolean, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ThinType As Integer, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertCutSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCutSurface( _  
    ByVal Flip As Boolean, _  
    ByVal KeepPieceIndex As Long, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _  
    ByVal Bodies As Variant, _  
    ByRef Error As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertCutSwept Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCutSwept( _  
    ByVal Propagate As Boolean, _  
    ByVal Alignment As Boolean, _  
    ByVal TwistCtrlOption As Integer, _  
    ByVal KeepTangency As Boolean, _  
    ByVal ForceNonRational As Boolean, _  
    ByVal StartMatchingType As Integer, _  
    ByVal EndMatchingType As Integer, _  
    ByVal IsThinBody As Boolean, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ThinType As Integer, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertCutSwept2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCutSwept2( _  
    ByVal Propagate As Boolean, _  
    ByVal Alignment As Boolean, _  
    ByVal TwistCtrlOption As Integer, _  
    ByVal KeepTangency As Boolean, _  
    ByVal ForceNonRational As Boolean, _  
    ByVal StartMatchingType As Integer, _  
    ByVal EndMatchingType As Integer, _  
    ByVal IsThinBody As Boolean, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ThinType As Integer, _  
    ByVal PathAlign As Integer, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertCutSwept3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertCutSwept3( _  
    ByVal Propagate As Boolean, _  
    ByVal Alignment As Boolean, _
```

```

    ByVal TwistCtrlOption As Integer, _
    ByVal KeepTangency As Boolean, _
    ByVal BAdvancedSmoothing As Boolean, _
    ByVal StartMatchingType As Integer, _
    ByVal EndMatchingType As Integer, _
    ByVal IsThinBody As Boolean, _
    ByVal Thickness1 As Double, _
    ByVal Thickness2 As Double, _
    ByVal ThinType As Integer, _
    ByVal PathAlign As Integer, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal TwistAngle As Double, _
    ByVal BMergeSmoothFaces As Boolean _
) As Feature

```

SOLIDWORKS Type Library

InsertCutSwept4 Method (FeatureManager)



Visual Basic for Applications (VBA)

```

Public Function InsertCutSwept4( _
    ByVal Propagate As Boolean, _
    ByVal Alignment As Boolean, _
    ByVal TwistCtrlOption As Integer, _
    ByVal KeepTangency As Boolean, _
    ByVal BAdvancedSmoothing As Boolean, _
    ByVal StartMatchingType As Integer, _
    ByVal EndMatchingType As Integer, _
    ByVal IsThinBody As Boolean, _
    ByVal Thickness1 As Double, _
    ByVal Thickness2 As Double, _
    ByVal ThinType As Integer, _
    ByVal PathAlign As Integer, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal TwistAngle As Double, _
    ByVal BMergeSmoothFaces As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
    ByVal PropagateFeatureToParts As Boolean _
) As Feature

```

SOLIDWORKS Type Library

InsertCutSwept5 Method (FeatureManager)



Visual Basic for Applications (VBA)

```

Public Function InsertCutSwept5( _
    ByVal Propagate As Boolean, _
    ByVal Alignment As Boolean, _
    ByVal TwistCtrlOption As Long, _
    ByVal KeepTangency As Boolean, _
    ByVal BAdvancedSmoothing As Boolean, _
    ByVal StartMatchingType As Long, _
    ByVal EndMatchingType As Long, _
    ByVal IsThinBody As Boolean, _
    ByVal Thickness1 As Double, _
    ByVal Thickness2 As Double, _
    ByVal ThinType As Long, _
    ByVal PathAlign As Long, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal TwistAngle As Double, _
    ByVal BMergeSmoothFaces As Boolean, _
    ByVal AssemblyFeatureScope As Boolean, _
    ByVal AutoSelectComponents As Boolean, _
)

```

```
ByVal PropagateFeatureToParts As Boolean, _  
ByVal CircularProfile As Boolean, _  
ByVal CircularProfileDiameter As Double, _  
ByVal Direction As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertDeleteBody Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertDeleteBody() As Feature
```

SOLIDWORKS Type Library

InsertDeleteBody2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertDeleteBody2( _  
ByVal KeepBodies As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertDeleteHoleForSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertDeleteHoleForSurface() As Feature
```

SOLIDWORKS Type Library

InsertDerivedPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertDerivedPattern() As Feature
```

SOLIDWORKS Type Library

InsertDerivedPattern2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertDerivedPattern2() As Feature
```

SOLIDWORKS Type Library

InsertDwgOrDxfFile Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertDwgOrDxfFile( _  
ByVal FileName As String _  
) As Feature
```

SOLIDWORKS Type Library

InsertDwgOrDxfFile2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertDwgOrDxfFile2( _  
    ByVal FileName As String, _  
    ByVal DxfDwgImportData As Object _  
) As Feature
```

SOLIDWORKS Type Library

InsertEdgeMerge Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertEdgeMerge( _  
    ByVal Angular_tolerance As Double, _  
    ByVal Edge_length_tolerance As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertEndCapFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertEndCapFeature( _  
    ByVal Depth As Double, _  
    ByVal BIsGivenOffset As Boolean, _  
    ByVal BIsChamfer As Boolean, _  
    ByVal OffsetValue As Double, _  
    ByVal WallThicknessRatio As Double, _  
    ByVal ChamferValue As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertEndCapFeature2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertEndCapFeature2( _  
    ByVal Depth As Double, _  
    ByVal BIsGivenOffset As Boolean, _  
    ByVal BIsChamfer As Boolean, _  
    ByVal OffsetValue As Double, _  
    ByVal WallThicknessRatio As Double, _  
    ByVal ChamferValue As Double, _  
    ByVal Faces As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertEndCapFeature3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertEndCapFeature3( _  
    ByVal Depth As Double, _  
    ByVal BIsGivenOffset As Boolean, _  
    ByVal BIsChamfer As Boolean, _  
    ByVal OffsetValue As Double, _  
    ByVal WallThicknessRatio As Double, _  
    ByVal ChamferValue As Double, _  
    ByVal BIsCornerTreatment As Boolean, _  
    ByVal DepthOffset As Double, _  
    ByVal BIsReverse As Boolean, _  
    ByVal BIsEndCapInward As Long _  
) As Feature
```

InsertFeatureChamfer Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertFeatureChamfer( _  
    ByVal Options As Long, _  
    ByVal ChamferType As Long, _  
    ByVal Width As Double, _  
    ByVal Angle As Double, _  
    ByVal OtherDist As Double, _  
    ByVal VertexChamDist1 As Double, _  
    ByVal VertexChamDist2 As Double, _  
    ByVal VertexChamDist3 As Double _  
) As Feature
```

InsertFeatureLock Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertFeatureLock() As Feature
```

InsertFeatureTreeFolder Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertFeatureTreeFolder() As Boolean
```

InsertFeatureTreeFolder2 Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertFeatureTreeFolder2( _  
    ByVal Type As Long _  
) As Feature
```

InsertFilletBeadFeature Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertFilletBeadFeature( _  
    ByVal Type1 As Integer, _  
    ByVal Size1 As Double, _  
    ByVal Length1 As Double, _  
    ByVal Pitch As Double, _  
    ByVal Type2 As Integer, _  
    ByVal Size2 As Double, _  
    ByVal Length2 As Double, _  
    ByVal Flag As Long, _  
    ByVal EdgeNum1 As Long, _  
    ByVal DeSelEdge1 As Variant, _  
    ByVal EdgeNum2 As Long, _  
    ByVal DeSelEdge2 As Variant _  
) As Feature
```

InsertFilletBeadFeature2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertFilletBeadFeature2( _  
    ByVal Type1 As Integer, _  
    ByVal Size1 As Double, _  
    ByVal Length1 As Double, _  
    ByVal PenetrationType1 As Integer, _  
    ByVal PenetrationValue1 As Double, _  
    ByVal Pitch As Double, _  
    ByVal Type2 As Integer, _  
    ByVal Size2 As Double, _  
    ByVal Length2 As Double, _  
    ByVal PenetrationType2 As Integer, _  
    ByVal PenetrationValue2 As Double, _  
    ByVal Flag As Long, _  
    ByVal EdgeNum1 As Long, _  
    ByVal DeSelEdge1 As Variant, _  
    ByVal EdgeNum2 As Long, _  
    ByVal DeSelEdge2 As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertFilletBeadFeature3 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertFilletBeadFeature3( _  
    ByVal Type1 As Integer, _  
    ByVal Size1 As Double, _  
    ByVal Length1 As Double, _  
    ByVal PenetrationType1 As Integer, _  
    ByVal PenetrationValue1 As Double, _  
    ByVal Pitch As Double, _  
    ByVal Type2 As Integer, _  
    ByVal Size2 As Double, _  
    ByVal Length2 As Double, _  
    ByVal PenetrationType2 As Integer, _  
    ByVal PenetrationValue2 As Double, _  
    ByVal Flag As Long, _  
    ByVal EdgeNum1 As Long, _  
    ByVal DeSelEdge1 As Variant, _  
    ByVal EdgeNum2 As Long, _  
    ByVal DeSelEdge2 As Variant, _  
    ByVal FaceSet1 As Variant, _  
    ByVal FaceSet2 As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertFillSurface Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertFillSurface( _  
    ByVal Resolution As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertFillSurface2 Method (FeatureManager)



Visual Basic for Applications (VBA)

```
Public Function InsertFillSurface2( _  
    ByVal Resolutions As Long, _  
    ByVal Options As Long, _
```

```
ByVal VPatchBoundaries As Variant, _  
ByVal VCurvatureControlType As Variant, _  
ByVal VFaces As Variant, _  
ByVal VConstraintCurves As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertFlattenSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertFlattenSurface( _  
ByVal AccuracyFactor As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertFlattenSurface2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertFlattenSurface2( _  
ByVal AccuracyFactor As Long, _  
ByVal ShouldUseTears As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertFlexFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertFlexFeature( _  
ByVal RotX As Double, _  
ByVal RotY As Double, _  
ByVal RotZ As Double, _  
ByVal TanX As Double, _  
ByVal TanY As Double, _  
ByVal TanZ As Double, _  
ByVal RadX As Double, _  
ByVal RadY As Double, _  
ByVal RadZ As Double, _  
ByVal Angle As Double, _  
ByVal PivotX As Double, _  
ByVal PivotY As Double, _  
ByVal PivotZ As Double, _  
ByVal Type As Long, _  
ByVal LeftTrim As Double, _  
ByVal RightTrim As Double, _  
ByVal HardEdges As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertFormToolFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertFormToolFeature( _  
ByVal Path As String, _  
ByVal Flip As Boolean, _  
ByVal RotAngle As Double, _  
ByVal Config As String, _  
ByVal OverrideDoc As Boolean, _  
ByVal ShowPunch As Boolean, _  
ByVal ShowProfile As Boolean, _  
ByVal ShowCenter As Boolean, _
```

```
ByVal LinkToPart As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertFreeform Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertFreeform( _  
    ByVal Continuity0 As Integer, _  
    ByVal Continuity1 As Integer, _  
    ByVal Continuity2 As Integer, _  
    ByVal Continuity3 As Integer, _  
    ByVal Symmetric0 As Boolean, _  
    ByVal Symmetric1 As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertFreeform2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertFreeform2( _  
    ByVal Nsided As Boolean, _  
    ByVal Symmetric0 As Boolean, _  
    ByVal Symmetric1 As Boolean, _  
    ByVal Angle As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertGlobalBoundingBox Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertGlobalBoundingBox( _  
    ByVal BBoxType As Long, _  
    ByVal IncludeHiddenBodies As Boolean, _  
    ByVal IncludeSurfaceBodies As Boolean, _  
    ByRef Status As Long _  
) As Object
```

SOLIDWORKS Type Library

InsertGlobalBoundingBox2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertGlobalBoundingBox2( _  
    ByVal BBoxType As Long, _  
    ByVal lwtaDirectionType As Long, _  
    ByVal IncludeHiddenBodies As Boolean, _  
    ByVal IncludeSurfaceBodies As Boolean, _  
    ByRef Status As Long _  
) As Object
```

SOLIDWORKS Type Library

InsertGridFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertGridFeature( _  
    ByVal HeightDoubles As Variant _  
    ) As Feature
```

SOLIDWORKS Type Library

InsertGroundPlane Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertGroundPlane( _  
    ByVal ReverseDirection As Boolean _  
    ) As Feature
```

SOLIDWORKS Type Library

InsertGussetFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertGussetFeature( _  
    ByVal Depth As Double, _  
    ByVal DirType As Integer, _  
    ByVal LocType As Integer, _  
    ByVal BIsProfile As Boolean, _  
    ByVal ProfileD1 As Double, _  
    ByVal ProfileD2 As Double, _  
    ByVal ProfileD3 As Double, _  
    ByVal ProfileAngle As Double, _  
    ByVal ProfileD4 As Double, _  
    ByVal BOffset As Boolean, _  
    ByVal DProfileOffset As Double, _  
    ByVal CrvIndex As Long, _  
    ByVal BReverseDir As Boolean, _  
    ByVal BReverseFace As Boolean, _  
    ByVal BUseLenDim As Boolean _  
    ) As Feature
```

SOLIDWORKS Type Library

InsertGussetFeature2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertGussetFeature2( _  
    ByVal Depth As Double, _  
    ByVal DirType As Integer, _  
    ByVal LocType As Integer, _  
    ByVal BIsProfile As Boolean, _  
    ByVal ProfileD1 As Double, _  
    ByVal ProfileD2 As Double, _  
    ByVal ProfileD3 As Double, _  
    ByVal ProfileAngle As Double, _  
    ByVal ProfileD4 As Double, _  
    ByVal BOffset As Boolean, _  
    ByVal DProfileOffset As Double, _  
    ByVal CrvIndex As Long, _  
    ByVal BReverseDir As Boolean, _  
    ByVal BReverseFace As Boolean, _  
    ByVal BUseLenDim As Boolean, _  
    ByVal Faces As Variant _  
    ) As Feature
```

SOLIDWORKS Type Library

InsertGussetFeature3 Method (FeatureManager)

Syntax

```
Public Function InsertGussetFeature3( _
    ByVal Depth As Double, _
    ByVal DirType As Integer, _
    ByVal LocType As Integer, _
    ByVal BIsProfile As Boolean, _
    ByVal ProfileD1 As Double, _
    ByVal ProfileD2 As Double, _
    ByVal ProfileD3 As Double, _
    ByVal ProfileAngle As Double, _
    ByVal ProfileD4 As Double, _
    ByVal BOffset As Boolean, _
    ByVal DProfileOffset As Double, _
    ByVal CrvIndex As Long, _
    ByVal BReverseDir As Boolean, _
    ByVal BReverseFace As Boolean, _
    ByVal BUseLenDim As Boolean, _
    ByVal ProfileD5 As Double, _
    ByVal ProfileD6 As Double, _
    ByVal ProfileChamferAngle As Double, _
    ByVal BUseLenDimForChamfer As Boolean, _
    ByVal BNeedChamferInGusset As Boolean _
) As Feature
```

SOLIDWORKS Type Library

InsertIndent Method (FeatureManager)

 Syntax

```
Public Function InsertIndent( _
    ByVal Thickness As Double, _
    ByVal Clearance As Double, _
    ByVal Exclude As Boolean, _
    ByVal ClrDir As Boolean, _
    ByVal Cut As Boolean, _
    ByVal CutDir As Boolean _
) As Feature
```

SOLIDWORKS Type Library

InsertLiveSectionPlane Method (FeatureManager)

 Syntax

```
Public Function InsertLiveSectionPlane( _
    ByVal Type As Integer _
) As Feature
```

SOLIDWORKS Type Library

InsertMacroFeature Method (FeatureManager)

 Syntax

```
Public Function InsertMacroFeature( _
    ByVal BaseName As String, _
    ByVal ProgId As String, _
    ByVal MacroMethods As Variant, _
    ByVal ParamNames As Variant, _
    ByVal ParamTypes As Variant, _
    ByVal ParamValues As Variant, _
    ByVal EditBody As Body2, _
    ByVal Options As Long _
) As Feature
```

SOLIDWORKS Type Library

InsertMacroFeature2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMacroFeature2( _  
    ByVal BaseName As String, _  
    ByVal ProgId As String, _  
    ByVal MacroMethods As Variant, _  
    ByVal ParamNames As Variant, _  
    ByVal ParamTypes As Variant, _  
    ByVal ParamValues As Variant, _  
    ByVal DimTypes As Variant, _  
    ByVal DimValues As Variant, _  
    ByVal EditBody As Body2, _  
    ByVal IconFiles As Variant, _  
    ByVal Options As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertMacroFeature3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMacroFeature3( _  
    ByVal BaseName As String, _  
    ByVal ProgId As String, _  
    ByVal MacroMethods As Variant, _  
    ByVal ParamNames As Variant, _  
    ByVal ParamTypes As Variant, _  
    ByVal ParamValues As Variant, _  
    ByVal DimTypes As Variant, _  
    ByVal DimValues As Variant, _  
    ByVal EditBodies As Variant, _  
    ByVal IconFiles As Variant, _  
    ByVal Options As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertMateReference Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMateReference( _  
    ByVal BstrMateReferenceName As String, _  
    ByVal PrimaryReferenceEntity As Entity, _  
    ByVal PrimaryReferenceType As Long, _  
    ByVal PrimaryReferenceAlignment As Long, _  
    ByVal SecondaryReferenceEntity As Entity, _  
    ByVal SecondaryReferenceType As Long, _  
    ByVal SecondaryReferenceAlignment As Long, _  
    ByVal TertiaryReferenceEntity As Entity, _  
    ByVal TertiaryReferenceType As Long, _  
    ByVal TertiaryReferenceAlignment As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertMateReference2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMateReference2( _  
    ByVal BstrMateReferenceName As String, _  
    ByVal PrimaryReferenceEntity As Entity, _  
    ByVal PrimaryReferenceType As Long, _
```

```
ByVal PrimaryReferenceAlignment As Long, _  
ByVal PrimaryReferenceAlignAxes As Boolean, _  
ByVal SecondaryReferenceEntity As Entity, _  
ByVal SecondaryReferenceType As Long, _  
ByVal SecondaryReferenceAlignment As Long, _  
ByVal SecondaryReferenceAlignAxes As Boolean, _  
ByVal TertiaryReferenceEntity As Entity, _  
ByVal TertiaryReferenceType As Long, _  
ByVal TertiaryReferenceAlignment As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertMidSurface Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMidSurface( _  
    ByVal PBodyIn As Body2, _  
    ByVal PPartDocIn As ModelDoc2, _  
    ByVal Placement As Double, _  
    ByVal KnitFlag As Boolean _  
) As Object
```

SOLIDWORKS Type Library

InsertMirrorFeature Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMirrorFeature( _  
    ByVal BMirrorBody As Boolean, _  
    ByVal BGeometryPattern As Boolean, _  
    ByVal BMerge As Boolean, _  
    ByVal BKnit As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertMirrorFeature2 Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMirrorFeature2( _  
    ByVal BMirrorBody As Boolean, _  
    ByVal BGeometryPattern As Boolean, _  
    ByVal BMerge As Boolean, _  
    ByVal BKnit As Boolean, _  
    ByVal ScopeOptions As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoldCoreCavitySolids Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoldCoreCavitySolids( _  
    ByVal Dist1 As Double, _  
    ByVal Dist2 As Double, _  
    ByVal Setback As Boolean, _  
    ByVal Angle As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoldPartingLine Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoldPartingLine( _  
    ByVal BFlipDir As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoldPartingSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoldPartingSurface( _  
    ByVal Radiate As Long, _  
    ByVal ReverseAlignment As Boolean, _  
    ByVal ReverseOffset As Boolean, _  
    ByVal OffsetDistance As Double, _  
    ByVal Angle As Double, _  
    ByVal Smooth As Long, _  
    ByVal SmoothDistance As Double, _  
    ByVal Knit As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoldShutOffSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoldShutOffSurface() As Feature
```

SOLIDWORKS Type Library

InsertMoveCopyBody Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoveCopyBody( _  
    ByVal TransX As Double, _  
    ByVal TransY As Double, _  
    ByVal TransZ As Double, _  
    ByVal TransDist As Double, _  
    ByVal RotPointX As Double, _  
    ByVal RotPointY As Double, _  
    ByVal RotPointZ As Double, _  
    ByVal RotAngleX As Double, _  
    ByVal RotAngleY As Double, _  
    ByVal RotAngleZ As Double, _  
    ByVal BCopy As Boolean, _  
    ByVal NumCopies As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoveCopyBody2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoveCopyBody2( _  
    ByVal TransX As Double, _  
    ByVal TransY As Double, _  
    ByVal TransZ As Double, _  
    ByVal TransDist As Double, _  
    ByVal RotPointX As Double, _  
    ByVal RotPointY As Double, _  
    ByVal RotPointZ As Double, _
```

```
ByVal RotAngleX As Double, _  
ByVal RotAngleY As Double, _  
ByVal RotAngleZ As Double, _  
ByVal BCopy As Boolean, _  
ByVal NumCopies As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoveFace Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoveFace( _  
    ByVal MoveType As Long, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle As Double, _  
    ByVal Distance As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoveFace2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoveFace2( _  
    ByVal MoveType As Long, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle As Double, _  
    ByVal Distance As Double, _  
    ByVal TranslationParams As Variant, _  
    ByVal RotationParams As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertMoveFace3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMoveFace3( _  
    ByVal MoveType As Long, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle As Double, _  
    ByVal Distance As Double, _  
    ByVal TranslationParams As Variant, _  
    ByVal RotationParams As Variant, _  
    ByVal EndConditionType As Long, _  
    ByVal OffsetDistance As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertMultiFaceDraft Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertMultiFaceDraft( _  
    ByVal Angle As Double, _  
    ByVal FlipDir As Boolean, _  
    ByVal EdgeDraft As Boolean, _  
    ByVal PropType As Long, _  
    ByVal IsStepDraft As Boolean, _  
    ByVal IsBodyDraft As Boolean _  
) As Feature
```



Visual Basic for Applications (VBA)

```
Public Function InsertNetBlend( _
    ByVal Type As Integer, _
    ByVal NCurvesDir1 As Integer, _
    ByVal NCurvesDir2 As Integer, _
    ByVal HasCenterline As Boolean, _
    ByVal TessTolFactor As Double, _
    ByVal WantsSolid As Boolean, _
    ByVal MergeBody As Boolean, _
    ByVal FeatureScope As Boolean, _
    ByVal AutoSelect As Boolean, _
    ByVal Thin As Boolean, _
    ByVal Thickness1 As Double, _
    ByVal Thickness2 As Double, _
    ByVal ReverseThickness As Boolean, _
    ByVal ThinSolidType As Integer, _
    ByVal UseSharedThickness As Boolean, _
    ByVal CapEnds As Boolean, _
    ByVal EndThickness As Double, _
    ByVal AutoFillet As Boolean, _
    ByVal FilletRadius As Double, _
    ByVal ForceNonRational As Boolean _
) As Feature
```



Visual Basic for Applications (VBA)

```
Public Function InsertNetBlend2( _
    ByVal Type As Integer, _
    ByVal NCurvesDir1 As Integer, _
    ByVal NCurvesDir2 As Integer, _
    ByVal HasCenterline As Boolean, _
    ByVal TessTolFactor As Double, _
    ByVal WantsSolid As Boolean, _
    ByVal MergeBody As Boolean, _
    ByVal FeatureScope As Boolean, _
    ByVal AutoSelect As Boolean, _
    ByVal Thin As Boolean, _
    ByVal Thickness1 As Double, _
    ByVal Thickness2 As Double, _
    ByVal ReverseThickness As Boolean, _
    ByVal ThinSolidType As Integer, _
    ByVal UseSharedThickness As Boolean, _
    ByVal CapEnds As Boolean, _
    ByVal EndThickness As Double, _
    ByVal AutoFillet As Boolean, _
    ByVal FilletRadius As Double, _
    ByVal ForceNonRational As Boolean, _
    ByVal CreateSolid As Boolean _
) As Feature
```



Visual Basic for Applications (VBA)

```
Public Function InsertProtrusionBlend( _
    ByVal Closed As Boolean, _
    ByVal KeepTangency As Boolean, _
    ByVal ForceNonRational As Boolean, _
```

```

ByVal TessToleranceFactor As Double, _
ByVal StartMatchingType As Integer, _
ByVal EndMatchingType As Integer, _
ByVal StartTangentLength As Double, _
ByVal EndTangentLength As Double, _
ByVal StartTangentDir As Boolean, _
ByVal EndTangentDir As Boolean, _
ByVal IsThinBody As Boolean, _
ByVal Thickness1 As Double, _
ByVal Thickness2 As Double, _
ByVal ThinType As Integer, _
ByVal Merge As Boolean, _
ByVal UseFeatScope As Boolean, _
ByVal UseAutoSelect As Boolean _
) As Feature

```

SOLIDWORKS Type Library

InsertProtrusionBlend2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function InsertProtrusionBlend2( _
    ByVal Closed As Boolean, _
    ByVal KeepTangency As Boolean, _
    ByVal ForceNonRational As Boolean, _
    ByVal TessToleranceFactor As Double, _
    ByVal StartMatchingType As Integer, _
    ByVal EndMatchingType As Integer, _
    ByVal StartTangentLength As Double, _
    ByVal EndTangentLength As Double, _
    ByVal StartTangentDir As Boolean, _
    ByVal EndTangentDir As Boolean, _
    ByVal IsThinBody As Boolean, _
    ByVal Thickness1 As Double, _
    ByVal Thickness2 As Double, _
    ByVal ThinType As Integer, _
    ByVal Merge As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean, _
    ByVal GuideCurveInfluence As Long _
) As Feature

```

SOLIDWORKS Type Library

InsertProtrusionSwept Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function InsertProtrusionSwept( _
    ByVal Propagate As Boolean, _
    ByVal Alignment As Boolean, _
    ByVal TwistCtrlOption As Integer, _
    ByVal KeepTangency As Boolean, _
    ByVal ForceNonRational As Boolean, _
    ByVal StartMatchingType As Integer, _
    ByVal EndMatchingType As Integer, _
    ByVal IsThinBody As Boolean, _
    ByVal Thickness1 As Double, _
    ByVal Thickness2 As Double, _
    ByVal ThinType As Integer, _
    ByVal Merge As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean _
) As Feature

```

SOLIDWORKS Type Library

InsertProtrusionSwept2 Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertProtrusionSwept2( _  
    ByVal Propagate As Boolean, _  
    ByVal Alignment As Boolean, _  
    ByVal TwistCtrlOption As Integer, _  
    ByVal KeepTangency As Boolean, _  
    ByVal ForceNonRational As Boolean, _  
    ByVal StartMatchingType As Integer, _  
    ByVal EndMatchingType As Integer, _  
    ByVal IsThinBody As Boolean, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ThinType As Integer, _  
    ByVal PathAlign As Integer, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertProtrusionSwept3 Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertProtrusionSwept3( _  
    ByVal Propagate As Boolean, _  
    ByVal Alignment As Boolean, _  
    ByVal TwistCtrlOption As Integer, _  
    ByVal KeepTangency As Boolean, _  
    ByVal BAdvancedSmoothing As Boolean, _  
    ByVal StartMatchingType As Integer, _  
    ByVal EndMatchingType As Integer, _  
    ByVal IsThinBody As Boolean, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ThinType As Integer, _  
    ByVal PathAlign As Integer, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _  
    ByVal TwistAngle As Double, _  
    ByVal BMergeSmoothFaces As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertProtrusionSwept4 Method (FeatureManager)



Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertProtrusionSwept4( _  
    ByVal Propagate As Boolean, _  
    ByVal Alignment As Boolean, _  
    ByVal TwistCtrlOption As Long, _  
    ByVal KeepTangency As Boolean, _  
    ByVal BAdvancedSmoothing As Boolean, _  
    ByVal StartMatchingType As Long, _  
    ByVal EndMatchingType As Long, _  
    ByVal IsThinBody As Boolean, _  
    ByVal Thickness1 As Double, _  
    ByVal Thickness2 As Double, _  
    ByVal ThinType As Long, _  
    ByVal PathAlign As Long, _  
    ByVal Merge As Boolean, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _
```

```
ByVal TwistAngle As Double, _  
ByVal BMergeSmoothFaces As Boolean, _  
ByVal CircularProfile As Boolean, _  
ByVal CircularProfileDiameter As Double, _  
ByVal Direction As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertReferencePoint Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertReferencePoint( _  
    ByVal NRefPointType As Long, _  
    ByVal NRefPointAlongCurveType As Long, _  
    ByVal DDistance_or_Percent As Double, _  
    ByVal NumberOfRefPoints As Long _  
) As Variant
```

SOLIDWORKS Type Library

InsertRefPlane Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertRefPlane( _  
    ByVal FirstConstraint As Long, _  
    ByVal FirstConstraintAngleOrDistance As Double, _  
    ByVal SecondConstraint As Long, _  
    ByVal SecondConstraintAngleOrDistance As Double, _  
    ByVal ThirdConstraint As Long, _  
    ByVal ThirdConstraintAngleOrDistance As Double _  
) As Object
```

SOLIDWORKS Type Library

InsertRevolvedRefSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertRevolvedRefSurface( _  
    ByVal Angle As Double, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Angle2 As Double, _  
    ByVal RevType As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertRib Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub InsertRib( _  
    ByVal Is2Sided As Boolean, _  
    ByVal ReverseThicknessDir As Boolean, _  
    ByVal Thickness As Double, _  
    ByVal ReferenceEdgeIndex As Long, _  
    ByVal ReverseMaterialDir As Boolean, _  
    ByVal IsDrafted As Boolean, _  
    ByVal DraftOutward As Boolean, _  
    ByVal DraftAngle As Double, _  
    ByVal IsNormToSketch As Boolean, _  
    ByVal IsDraftedFromWall As Boolean _  
)
```

InsertRuledSurfaceFromEdge Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertRuledSurfaceFromEdge( _  
    ByVal Type As Long, _  
    ByVal Length As Double, _  
    ByVal FlipPullDir As Boolean, _  
    ByVal FlipDir As Boolean, _  
    ByVal TrimAndSew As Boolean, _  
    ByVal Angle As Double, _  
    ByVal CoordInput As Boolean, _  
    ByVal X As Double, _  
    ByVal Y As Double, _  
    ByVal Z As Double _  
    ) As Feature
```

InsertRuledSurfaceFromEdge2 Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertRuledSurfaceFromEdge2( _  
    ByVal Type As Long, _  
    ByVal Length As Double, _  
    ByVal FlipPullDir As Boolean, _  
    ByVal FlipDir As Boolean, _  
    ByVal TrimAndSew As Boolean, _  
    ByVal Angle As Double, _  
    ByVal CoordInput As Boolean, _  
    ByVal X As Double, _  
    ByVal Y As Double, _  
    ByVal Z As Double, _  
    ByVal BConnectSurface As Boolean _  
    ) As Feature
```

InsertSaveOutBodies Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertSaveOutBodies() As Boolean
```

InsertScale Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertScale( _  
    ByVal Type As Integer, _  
    ByVal Uniform As Boolean, _  
    ByVal Xscale As Double, _  
    ByVal Yscale As Double, _  
    ByVal Zscale As Double _  
    ) As Feature
```

InsertSecurityNote Method (FeatureManager)**Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertSecurityNote( _  
    ByVal Text As String, _  
    ByVal FeatureOwner As Feature _  
) As Note
```

SOLIDWORKS Type Library

InsertSewRefSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSewRefSurface( _  
    ByVal UseGapFilters As Boolean, _  
    ByVal TryToFormSolid As Boolean, _  
    ByVal MergeEntities As Boolean, _  
    ByVal KnitTolerance As Double, _  
    ByVal MaxValueForGapRange As Double _  
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetal3dBend Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetal3dBend( _  
    ByVal Angle As Double, _  
    ByVal BUseDefaultRadius As Boolean, _  
    ByVal Radius As Double, _  
    ByVal FlipDir As Boolean, _  
    ByVal BendPos As Integer, _  
    ByVal PCBA As CustomBendAllowance _  
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalBaseFlange Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalBaseFlange( _  
    ByVal Thickness As Double, _  
    ByVal ThickenDir As Boolean, _  
    ByVal Radius As Double, _  
    ByVal ExtrudeDist1 As Double, _  
    ByVal ExtrudeDist2 As Double, _  
    ByVal FlipExtruDir As Boolean, _  
    ByVal EndCondition1 As Long, _  
    ByVal EndCondition2 As Long, _  
    ByVal DirToUse As Long, _  
    ByVal PCBA As CustomBendAllowance, _  
    ByVal UseDefaultRelief As Boolean, _  
    ByVal ReliefType As Long, _  
    ByVal ReliefWidth As Double, _  
    ByVal ReliefDepth As Double, _  
    ByVal ReliefRatio As Double, _  
    ByVal UseReliefRatio As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalBaseFlange2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalBaseFlange2( _
    ByVal Thickness As Double, _
    ByVal ThickenDir As Boolean, _
    ByVal Radius As Double, _
    ByVal ExtrudeDist1 As Double, _
    ByVal ExtrudeDist2 As Double, _
    ByVal FlipExtruDir As Boolean, _
    ByVal EndCondition1 As Long, _
    ByVal EndCondition2 As Long, _
    ByVal DirToUse As Long, _
    ByVal PCBA As CustomBendAllowance, _
    ByVal UseDefaultRelief As Boolean, _
    ByVal ReliefType As Long, _
    ByVal ReliefWidth As Double, _
    ByVal ReliefDepth As Double, _
    ByVal ReliefRatio As Double, _
    ByVal UseReliefRatio As Boolean, _
    ByVal Merge As Boolean, _
    ByVal UseFeatScope As Boolean, _
    ByVal UseAutoSelect As Boolean _
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalCornerTrim Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalCornerTrim( _
    ByVal InternalCornerFlag As Long, _
    ByVal BreakType As Long, _
    ByVal BreakDist As Double, _
    ByVal ReliefType As Long, _
    ByVal Param As Double _
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalEdgeFlange Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalEdgeFlange( _
    ByVal FlangeEdge As Edge, _
    ByVal SketchFeat As Feature, _
    ByVal BooleanOptions As Long, _
    ByVal DAngle As Double, _
    ByVal DRadius As Double, _
    ByVal BendPosition As Long, _
    ByVal DOffsetDist As Double, _
    ByVal ReliefType As Long, _
    ByVal DReliefRatio As Double, _
    ByVal DReliefWidth As Double, _
    ByVal DReliefDepth As Double, _
    ByVal FlangeSharpType As Long, _
    ByVal PCBA As CustomBendAllowance _
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalEdgeFlange2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalEdgeFlange2( _
    ByVal FlangeEdges As Variant, _
    ByVal SketchFeats As Variant, _
```

```

ByVal BooleanOptions As Long, _
ByVal FlangeAngle As Double, _
ByVal FlangeRadius As Double, _
ByVal BendPosition As Long, _
ByVal FlangeOffsetDist As Double, _
ByVal ReliefType As Long, _
ByVal FlangeReliefRatio As Double, _
ByVal FlangeReliefWidth As Double, _
ByVal FlangeReliefDepth As Double, _
ByVal FlangeSharpType As Long, _
ByVal CustomBendAllowance As CustomBendAllowance _
) As Feature

```

SOLIDWORKS Type Library

InsertSheetMetalGussetFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function InsertSheetMetalGussetFeature( _
    ByVal BOffset As Boolean, _
    ByVal DOffset As Double, _
    ByVal BFlipOffsetSide As Boolean, _
    ByVal ProfDimType As Long, _
    ByVal DIndentDepth As Double, _
    ByVal DLength As Double, _
    ByVal BUseAngle As Boolean, _
    ByVal DHeight As Double, _
    ByVal DAngle As Double, _
    ByVal BFlipSides As Boolean, _
    ByVal DWidth As Double, _
    ByVal DThickness As Double, _
    ByVal BDraft As Boolean, _
    ByVal DDraftAngle As Double, _
    ByVal BInnerCornerFillet As Boolean, _
    ByVal DInnerCornerFilletRadius As Double, _
    ByVal BOuterCornerFillet As Boolean, _
    ByVal DOuterCornerFilletRadius As Double, _
    ByVal GussetType As Long, _
    ByVal BEdgeFillet As Boolean, _
    ByVal DEdgeFilletRadius As Double _
) As Feature

```

SOLIDWORKS Type Library

InsertSheetMetalGussetFeature2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function InsertSheetMetalGussetFeature2( _
    ByVal BOffset As Boolean, _
    ByVal DOffset As Double, _
    ByVal BFlipOffsetSide As Boolean, _
    ByVal ProfDimType As Long, _
    ByVal DIndentDepth As Double, _
    ByVal DLength As Double, _
    ByVal BUseAngle As Boolean, _
    ByVal DHeight As Double, _
    ByVal DAngle As Double, _
    ByVal BFlipSides As Boolean, _
    ByVal DWidth As Double, _
    ByVal DThickness As Double, _
    ByVal BDraft As Boolean, _
    ByVal DDraftAngle As Double, _
    ByVal BInnerCornerFillet As Boolean, _
    ByVal DInnerCornerFilletRadius As Double, _
    ByVal BOuterCornerFillet As Boolean, _
    ByVal DOuterCornerFilletRadius As Double, _
    ByVal GussetType As Long, _

```

```
ByVal BEdgeFillet As Boolean, _  
ByVal DEdgeFilletRadius As Double, _  
ByVal ArrayOfFaces As Variant, _  
ByVal ArrayRefLines As Variant, _  
ByVal ArrayRefPoints As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalGussetFeature3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalGussetFeature3( _  
    ByVal BOffset As Boolean, _  
    ByVal DOffset As Double, _  
    ByVal BFlipOffsetSide As Boolean, _  
    ByVal ProfDimType As Long, _  
    ByVal DIndentDepth As Double, _  
    ByVal DLength As Double, _  
    ByVal BUseAngle As Boolean, _  
    ByVal DHeight As Double, _  
    ByVal DAngle As Double, _  
    ByVal BFlipSides As Boolean, _  
    ByVal DWidth As Double, _  
    ByVal DThickness As Double, _  
    ByVal BDraft As Boolean, _  
    ByVal DDraftAngle As Double, _  
    ByVal BInnerCornerFillet As Boolean, _  
    ByVal DInnerCornerFilletRadius As Double, _  
    ByVal BOuterCornerFillet As Boolean, _  
    ByVal DOuterCornerFilletRadius As Double, _  
    ByVal GussetType As Long, _  
    ByVal BEdgeFillet As Boolean, _  
    ByVal DEdgeFilletRadius As Double, _  
    ByVal BOverrideDoc As Boolean, _  
    ByVal BShowProfile As Boolean, _  
    ByVal BShowCenter As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalHem Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalHem( _  
    ByVal Type As Long, _  
    ByVal Position As Long, _  
    ByVal Reverse As Boolean, _  
    ByVal DLength As Double, _  
    ByVal DGap As Double, _  
    ByVal DAngle As Double, _  
    ByVal DRad As Double, _  
    ByVal DMiterGap As Double, _  
    ByVal PCBA As CustomBendAllowance _  
) As Feature
```

SOLIDWORKS Type Library

InsertSheetMetalHem2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSheetMetalHem2( _  
    ByVal Type As Long, _  
    ByVal Position As Long, _  
    ByVal Reverse As Boolean, _
```

```

    ByVal DLength As Double, _
    ByVal DGap As Double, _
    ByVal DAngle As Double, _
    ByVal DRad As Double, _
    ByVal DMiterGap As Double, _
    ByVal PCBA As CustomBendAllowance, _
    ByVal UseDefaultRelief As Boolean, _
    ByVal ReliefType As Long, _
    ByVal ReliefTearTypes As Long, _
    ByVal UseReliefRatio As Boolean, _
    ByVal ReliefRatio As Double, _
    ByVal ReliefWidth As Double, _
    ByVal ReliefDepth As Double _
) As Feature

```

SOLIDWORKS Type Library

InsertSheetMetalLoftedBend Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function InsertSheetMetalLoftedBend( _
    ByVal ThickDirType As Long, _
    ByVal Thickness As Double _
) As Feature

```

SOLIDWORKS Type Library

InsertSheetMetalLoftedBend2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function InsertSheetMetalLoftedBend2( _
    ByVal ThickDirType As Long, _
    ByVal Thickness As Double, _
    ByVal BFormed As Boolean, _
    ByVal DRadius As Double, _
    ByVal BReferToEndPoint As Boolean, _
    ByVal EFacetOption As Long, _
    ByVal DChordTol As Double, _
    ByVal INumBends As Long, _
    ByVal DSegLength As Double, _
    ByVal DSegAngle As Double _
) As Feature

```

SOLIDWORKS Type Library

InsertSheetMetalMiterFlange Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```

Public Function InsertSheetMetalMiterFlange( _
    ByVal UseDefaultRadius As Boolean, _
    ByVal GlobalRadius As Double, _
    ByVal RipGap As Double, _
    ByVal UseDefaultRelief As Boolean, _
    ByVal UseReliefRatio As Boolean, _
    ByVal ReliefRatio As Double, _
    ByVal ReliefWidth As Double, _
    ByVal ReliefDepth As Double, _
    ByVal ReliefType As Long, _
    ByVal TrimSideBends As Boolean, _
    ByVal FlangePos As Long, _
    ByVal OffsetDist1 As Double, _
    ByVal OffsetDist2 As Double, _
    ByVal PCBA As CustomBendAllowance _
) As Feature

```

InsertSlicing Method (FeatureManager) **Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertSlicing( _  
    ByVal SlicingData As Object, _  
    ByRef Errors As Long _  
    ) As Variant
```

InsertSplitLineIntersect Method (FeatureManager) **Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertSplitLineIntersect( _  
    ByVal CompleteOption As Long _  
    ) As Feature
```

InsertStructuralWeldment Method (FeatureManager) **Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertStructuralWeldment( _  
    ByVal Path As String, _  
    ByVal EndCond As Long, _  
    ByVal Angle As Double _  
    ) As Feature
```

InsertStructuralWeldment2 Method (FeatureManager) **Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertStructuralWeldment2( _  
    ByVal Path As String, _  
    ByVal EndCond As Long, _  
    ByVal Angle As Double, _  
    ByVal Merge As Boolean _  
    ) As Feature
```

InsertStructuralWeldment3 Method (FeatureManager) **Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertStructuralWeldment3( _  
    ByVal Path As String, _  
    ByVal EndCond As Long, _  
    ByVal Angle As Double, _  
    ByVal Merge As Boolean, _  
    ByVal Groups As Variant _  
    ) As Feature
```

InsertStructuralWeldment4 Method (FeatureManager) **Syntax**

Visual Basic for Applications (VBA)

```
Public Function InsertStructuralWeldment4( _  
    ByVal Path As String, _  
    ByVal ConnectedSegmentsOption As Long, _  
    ByVal AllowProtrusion As Boolean, _  
    ByVal Groups As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertStructuralWeldment5 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertStructuralWeldment5( _  
    ByVal Path As String, _  
    ByVal ConnectedSegmentsOption As Long, _  
    ByVal AllowProtrusion As Boolean, _  
    ByVal Groups As Variant, _  
    ByVal ConfigurationName As String _  
) As Feature
```

SOLIDWORKS Type Library

InsertSubFolder Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSubFolder() As Feature
```

SOLIDWORKS Type Library

InsertSubWeldFolder Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSubWeldFolder() As Feature
```

SOLIDWORKS Type Library

InsertSubWeldFolder2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSubWeldFolder2( _  
    ByVal BodyArray As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertSweepSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSweepSurface( _  
    ByVal Propagate As Boolean, _  
    ByVal TwistCtrlOption As Integer, _  
    ByVal KeepTangency As Boolean, _  
    ByVal ForceNonRational As Boolean, _  
    ByVal StartMatchingType As Integer, _  
    ByVal EndMatchingType As Integer, _  
    ByVal PathAlign As Integer _  
) As Feature
```

SOLIDWORKS Type Library

InsertSweepSurface2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSweepSurface2( _  
    ByVal Propagate As Boolean, _  
    ByVal TwistCtrlOption As Integer, _  
    ByVal KeepTangency As Boolean, _  
    ByVal BAdvancedSmoothing As Boolean, _  
    ByVal StartMatchingType As Integer, _  
    ByVal EndMatchingType As Integer, _  
    ByVal PathAlign As Integer, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _  
    ByVal TwistAngle As Double, _  
    ByVal BMergeSmoothFaces As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertSweepSurface3 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertSweepSurface3( _  
    ByVal Propagate As Boolean, _  
    ByVal TwistCtrlOption As Long, _  
    ByVal KeepTangency As Boolean, _  
    ByVal BAdvancedSmoothing As Boolean, _  
    ByVal StartMatchingType As Long, _  
    ByVal EndMatchingType As Long, _  
    ByVal PathAlign As Long, _  
    ByVal UseFeatScope As Boolean, _  
    ByVal UseAutoSelect As Boolean, _  
    ByVal TwistAngle As Double, _  
    ByVal BMergeSmoothFaces As Boolean, _  
    ByVal CircularProfile As Boolean, _  
    ByVal CircularProfileDiameter As Double, _  
    ByVal Direction As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertTableDrivenPattern Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertTableDrivenPattern( _  
    ByVal FileName As String, _  
    ByVal PointVar As Variant, _  
    ByVal UseCentrod As Boolean, _  
    ByVal GeomPatt As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertTableDrivenPattern2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertTableDrivenPattern2( _  
    ByVal FileName As String, _  
    ByVal PointVar As Variant, _  
    ByVal UseCentroid As Boolean, _  
    ByVal GeomPattern As Boolean, _  
    ByVal PropVisProps As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertUntrimSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertUntrimSurface( _  
    ByVal FaceUntrimType As Long, _  
    ByVal EdgeUntrimType As Long, _  
    ByVal Distance As Double, _  
    ByVal BMerge As Boolean _  
    ) As Feature
```

SOLIDWORKS Type Library

InsertUntrimSurface2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertUntrimSurface2( _  
    ByVal FaceUntrimType As Long, _  
    ByVal EdgeUntrimType As Long, _  
    ByVal Distance As Double, _  
    ByVal BMerge As Boolean, _  
    ByVal BTrimOppositeSide As Boolean _  
    ) As Feature
```

SOLIDWORKS Type Library

InsertVariablePitchHelix Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertVariablePitchHelix( _  
    ByVal Reversed As Boolean, _  
    ByVal Clockwise As Boolean, _  
    ByVal Helixdef As Long, _  
    ByVal Startangle As Double _  
    ) As Boolean
```

SOLIDWORKS Type Library

InsertVaryInstanceIncrement Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertVaryInstanceIncrement( _  
    ByVal DName As String, _  
    ByVal PatternType As Long, _  
    ByVal IncrementType As Long, _  
    ByVal Direction As Long, _  
    ByVal IncrementValue As Double _  
    ) As Boolean
```

SOLIDWORKS Type Library

InsertVaryInstanceOverride Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertVaryInstanceOverride( _  
    ByVal DName As String, _  
    ByVal PatternType As Long, _  
    ByVal OverrideType As Long, _  
    ByVal Direction As Long, _  
    ByVal InstanceRowIndex As Long, _  
    ByVal InstanceColumnIndex As Long, _
```

```
ByVal OverrideValue As Double _  
) As Boolean
```

SOLIDWORKS Type Library

InsertWeldmentCutList Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertWeldmentCutList() As Feature
```

SOLIDWORKS Type Library

InsertWeldmentCutList2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertWeldmentCutList2( _  
    ByVal Bodies As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertWeldmentFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertWeldmentFeature() As Feature
```

SOLIDWORKS Type Library

InsertWeldmentTrimFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertWeldmentTrimFeature( _  
    ByVal EndCond As Long _  
) As Feature
```

SOLIDWORKS Type Library

InsertWeldmentTrimFeature2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertWeldmentTrimFeature2( _  
    ByVal EndCond As Long, _  
    ByVal Options As Long, _  
    ByVal GapValue As Double, _  
    ByVal BodiesToTrim As Variant, _  
    ByVal BodiesOrFaces As Variant _  
) As Feature
```

SOLIDWORKS Type Library

InsertWrapFeature Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertWrapFeature( _  
    ByVal Type As Long, _  
    ByVal Thickness As Double, _  
    ByVal ReverseDir As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

InsertWrapFeature2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function InsertWrapFeature2( _  
    ByVal Type As Long, _  
    ByVal Thickness As Double, _  
    ByVal ReverseDir As Boolean, _  
    ByVal Method As Long, _  
    ByVal MeshFactor As Long _  
) As Feature
```

SOLIDWORKS Type Library

IsNameUsed Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function IsNameUsed( _  
    ByVal Type As Long, _  
    ByVal Name As String _  
) As Boolean
```

SOLIDWORKS Type Library

MakeStyledCurves Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub MakeStyledCurves( _  
    ByVal Tol As Double, _  
    ByVal Mode As Long _  
)
```

SOLIDWORKS Type Library

MakeStyledCurves2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function MakeStyledCurves2( _  
    ByVal Tolerance As Double, _  
    ByVal Mode As Long _  
) As Boolean
```

SOLIDWORKS Type Library

MoldUndercutDetect Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub MoldUndercutDetect( _  
    ByVal ColUndercut As Long, _  
    ByVal ColBase As Long, _  
    ByVal BCoordInput As Boolean, _  
    ByVal Dx As Double, _  
    ByVal Dy As Double, _  
    ByVal Dz As Double _  
)
```

SOLIDWORKS Type Library

MoldUndercutDetect2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Sub MoldUndercutDetect2( _
    ByVal ColUndercut1 As Long, _
    ByVal ColUndercut2 As Long, _
    ByVal ColOccluded As Long, _
    ByVal ColStraddle As Long, _
    ByVal ColBase As Long, _
    ByVal BCoordInput As Boolean, _
    ByVal Dx As Double, _
    ByVal Dy As Double, _
    ByVal Dz As Double _
)
```

SOLIDWORKS Type Library

MoveRotateLiveSectionPlane Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function MoveRotateLiveSectionPlane( _
    ByVal Feat As String, _
    ByVal Type As Integer, _
    ByVal XorDeltaX As Double, _
    ByVal YorDeltaY As Double, _
    ByVal ZorDeltaZ As Double, _
    ByVal Axisx As Double, _
    ByVal Axisy As Double, _
    ByVal Axisz As Double, _
    ByVal Angle As Double _
) As Boolean
```

SOLIDWORKS Type Library

MoveSizeFeatures Property (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Property MoveSizeFeatures As Boolean
```

SOLIDWORKS Type Library

MoveToFolder Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function MoveToFolder( _
    ByVal MoveToFeat As String, _
    ByVal MoveFromFeat As String, _
    ByVal IsFolder As Boolean _
) As Boolean
```

SOLIDWORKS Type Library

PostIntersect Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function PostIntersect( _
    ByVal IntersectionsToExclude As Variant, _
    ByVal Merge As Boolean, _
    ByVal Consume As Boolean _
) As Feature
```

SOLIDWORKS Type Library

PostSplitBody Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function PostSplitBody( _  
    ByVal BodiesToMark As Variant, _  
    ByVal ConsumeCut As Boolean, _  
    ByVal Origins As Variant, _  
    ByVal SavePaths As Variant _  
) As Feature
```

SOLIDWORKS Type Library

PostSplitBody2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function PostSplitBody2( _  
    ByVal BodiesToMark As Variant, _  
    ByVal ConsumeCut As Boolean, _  
    ByVal Origins As Variant, _  
    ByVal SavePaths As Variant, _  
    ByVal OverrideTemplateName As String _  
) As Object
```

SOLIDWORKS Type Library

PostTrimSurface Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function PostTrimSurface( _  
    ByVal BSewSurfaceIn As Boolean _  
) As Feature
```

SOLIDWORKS Type Library

PreIntersect Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function PreIntersect( _  
    ByVal CapPlanar As Boolean _  
) As Variant
```

SOLIDWORKS Type Library

PreIntersect2 Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function PreIntersect2( _  
    ByVal CapPlanar As Boolean, _  
    ByVal RegionType As Long _  
) As Variant
```

SOLIDWORKS Type Library

PreSplitBody Method (FeatureManager)

Syntax

Visual Basic for Applications (VBA)

```
Public Function PreSplitBody() As Variant
```

SOLIDWORKS Type Library

PreSplitBody2 Method (FeatureManager)

Syntax

```
Public Function PreSplitBody2() As Variant
```

SOLIDWORKS Type Library

PreTrimSurface Method (FeatureManager)

Visual Basic for Applications (VBA)

```
Public Function PreTrimSurface( _  
    ByVal BMutualTrimIn As Boolean, _  
    ByVal BSplitSystemIn As Boolean, _  
    ByVal BSplitLinearIn As Boolean, _  
    ByVal BRemovePickedIn As Boolean _  
    ) As Boolean
```

SOLIDWORKS Type Library

SetComponentIdentifiers Method (FeatureManager)

Visual Basic for Applications (VBA)

```
Public Function SetComponentIdentifiers( _  
    ByVal Primary As Long, _  
    ByVal Secondary As Long, _  
    ByVal Tertiary As Long _  
    ) As Long
```

SOLIDWORKS Type Library

SetFreeformBoundaryContinuity Method (FeatureManager)

Visual Basic for Applications (VBA)

```
Public Sub SetFreeformBoundaryContinuity( _  
    ByVal BoundaryIndex As Integer, _  
    ByVal Continuity As Integer _  
    )
```