

SOLIDWORKS Inspection Add-in API (.NET) — Examples (1/1): Getting Started-Welcome

SOLIDWORKS API Documentation (converted from CHM)

Getting Started (Topic)

SOLIDWORKS Inspection API Help

Getting Started

[Send Feedback](#)

Activate SOLIDWORKS Inspection

To use the SOLIDWORKS Inspection add-in API, you must first:

- Install SOLIDWORKS Design Professional or Premium 2022 (or later).
- Install SOLIDWORKS Inspection 2022 (or later) with a valid license key.
- Activate the SOLIDWORKS Inspection add-in from SOLIDWORKS **Tools > Add-Ins...**

After activation, you can access the user-interface help for SOLIDWORKS Inspection by selecting **Tools > SOLIDWORKS Inspection > Help and Quick Start Tour**. See how SOLIDWORKS Inspection works in the user interface before trying to balloon drawings using the SOLIDWORKS Inspection APIs.

How to balloon a drawing using the SOLIDWORKS Inspection APIs

1. Refer to the Examples in [InspectionAddinMgr](#).
2. Get the IInspectionMgr add-in object.
Read [Accessing SOLIDWORKS Add-in Objects](#) to determine GUID or ProgID of the SOLIDWORKS Inspection add-in.

For example in VBA,

```
...  
Dim inspectionMgr As SwInspectionAddin.InspectionAddinMgr  
Set progID = "Inspection.ExtSwAddin"  
Set inspectionMgr = SwApp.GetAddInObject(progID)
```

3. Create inspection project data.

```
Dim projData As SwInspectionAddin.InspectionProjectData  
Set projData = inspectionMgr.CreateInspectionProjectData  
'Specify properties in projData, e.g.,  
projData.AutoBalloon = True  
projData.StartNumber = 1  
projData.IncludeNotes = True  
projData.NotesAutoExplode = True  
projData.Extraction = swCharacteristicInfoExtraction_e.swiExtraction_Automatic  
4. Balloon the drawing by creating an inspection project based on an inspection template and project data.  
Templates are located in install_drive:\ProgramData\SOLIDWORKS\SolidWorks Inspection\yyyy\Addin\Templates.
```

```
Dim inspectionProj As SwInspectionAddin.InspectionProject  
Set inspectionProj = inspectionMgr.CreateInspectionProject("dir_name\template_name.swidot", projData)
```

How to modify the Bill of Characteristics

All of the inspection characteristics that you extracted during creation of the inspection project appear in a Bill of Characteristics.

Modifying Characteristics

After the model is ballooned, you can add/edit characteristics using:

```
inspectionMgr.AddCharacteristics(annotationArray)  
inspectionMgr.GetCharacteristicIDs  
  
Set charData = inspectionMgr.GetCharacteristicsData(charID)  
inspectionMgr.EditCharacteristic(charID, charData)
```

Exploding Characteristics

You can separate characteristics into multiple instances whenever charData.[Quantity](#) >= 1 by setting:

```
projData.CreateForEachInstance = True
```

How to add/edit balloons

Adding/Editing

If you set projData.[AutoBalloon](#) to false, you can manually add inspection balloons.

```
Set aBalloonSettingsObject = inspectionMgr.GetBalloonSettings  
'Specify the offsets and/or properties in the aBalloonSettingsObject.  
Call inspectionMgr.AddOrEditBalloons(aBalloonSettingsObject)
```

Removing

You can remove all balloons from the document.

```
Call inspectionMgr.RemoveBalloons
```

Selecting

You can select all balloons in the document.

Call inspectionMgr.[SelectBalloons](#)

How to add customizations to the inspection report

Manage vendor, operation, and inspection method lists to fit company requirements by using:

- inspectionMgr.[GetVendors](#)
- inspectionMgr.[AddVendor](#)
- inspectionMgr.[DeleteVendors](#)
- inspectionMgr.[GetInspectionMethods](#)
- inspectionMgr.[AddInspectionMethod](#)
- inspectionMgr.[DeleteInspectionMethods](#)
- inspectionMgr.[GetOperations](#)
- inspectionMgr.[AddOperation](#)
- inspectionMgr.[DeleteOperations](#)

How to publish and export inspection reports using the SOLIDWORKS Inspection APIs

After you finish ballooning the drawing, you can export the inspection report in a variety of file types:

- inspectionProj.[ExportTo2DPDF](#)
- inspectionProj.[ExportTo3DPDF](#) (valid only for Parts)
- inspectionProj.[ExportToExcel](#)
- inspectionProj.[ExportToEDrawings](#)

Release Notes (Topic)

SOLIDWORKS Inspection API Help

Release Notes

[Send Feedback](#)

No new functionality was introduced in this release of the SOLIDWORKS Inspection API.

SolidWorks.Interop.swinspectionAddIn (Topic)

SolidWorks.Interop.swinspectionAddIn Assembly



Namespaces

Namespace	Description
SolidWorks.Interop.swinspectionAddIn	

Welcome (Topic)

SOLIDWORKS Inspection API Help

Welcome

[Send Feedback](#)

The SOLIDWORKS Inspection API:

- Helps you automate ballooned inspection drawings, quality inspection reports, and quality sampling sheets for SOLIDWORKS Design drawings.
- Allows you to save inspection characteristic data in SOLIDWORKS Design files, make changes, export to multiple inspection reports, and export ballooned documents to other formats such as PDF and eDrawings.