

SOLIDWORKS Inspection Add-in API (.NET) — Reference (1/7): namespace hierarchy — CharacteristicsData

SOLIDWORKS API Documentation (converted from CHM)

namespace_hierarchy (Type)

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

SolidWorks.Interop.swinspectionAddIn Namespace Inheritance Hierarchy

[See Also](#)



Inheritance Hierarchy

System.Object

[SolidWorks.Interop.swinspectionAddIn.BalloonSettingsClass](#)

[SolidWorks.Interop.swinspectionAddIn.CharacteristicsDataClass](#)

[SolidWorks.Interop.swinspectionAddIn.InspectionAddInMgrClass](#)

[SolidWorks.Interop.swinspectionAddIn.InspectionProjectClass](#)

[SolidWorks.Interop.swinspectionAddIn.InspectionProjectDataClass](#)

See Also

[SolidWorks.Interop.swinspectionAddIn Assembly](#)

BalloonSettings (Type)

BalloonSettings Interface

[See Also](#) [Members](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : BalloonSettings Interface

.NET Syntax

Visual Basic (Declaration)

Public Interface BalloonSettings
Inherits [IBalloonSettings](#)

Visual Basic (Usage)



Dim instance As [BalloonSettings](#)

C#

public interface BalloonSettings : [IBalloonSettings](#)

C++/CLI

public interface class BalloonSettings : public [IBalloonSettings](#)

See Also

[BalloonSettings Members](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

BalloonSettings Interface Methods

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : BalloonSettings Interface

For a list of all members of this type, see [BalloonSettings members](#).

See Also

[BalloonSettings Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

BalloonSettings Interface Members

[See Also](#) [Properties](#) [Methods](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : BalloonSettings Interface

The following tables list the members exposed by [BalloonSettings](#).

See Also

[BalloonSettings Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

BalloonSettings Interface Properties

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : BalloonSettings Interface

For a list of all members of this type, see [BalloonSettings members](#).

See Also

[BalloonSettings Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

Apply Method (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : Apply Method (BalloonSettings)

Applies any modified balloon settings and re-balloons the model.

.NET Syntax

Visual Basic (Declaration)

```
Function Apply() As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettings  
Dim value As System.Boolean
```

```
value = instance.Apply()
```

C#

```
System.bool Apply()
```

C++/CLI

```
System.bool Apply();
```

Return Value

True if balloon settings successfully applied, false if not

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) methods.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

AttachToCharacteristic Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : AttachToCharacteristic Property (BalloonSettings)

Gets and sets whether to attach this balloon to each characteristic (item extracted from the drawing).

.NET Syntax

Visual Basic (Declaration)

```
Property AttachToCharacteristic As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettings
Dim value As System.Boolean

instance.AttachToCharacteristic = value
value = instance.AttachToCharacteristic
```

C#

```
System.bool AttachToCharacteristic {get; set;}
```

C++/CLI

```
property System.bool AttachToCharacteristic {
    System.bool get();
    void set ( & System.bool value);
}
```

Property Value

True to attach this balloon to each characteristic, false to not

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

Remarks

This property is valid only for drawings.

If this property is set to true, then when the balloon moves the dimension characteristic moves with it.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Fit Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : Fit Property (BalloonSettings)

Gets and sets the number of digits that fit in a regular characteristic balloon.

.NET Syntax

Visual Basic (Declaration)

```
Property Fit As System.Integer
```

Visual Basic (Usage)



```
Dim instance As BalloonSettings
Dim value As System.Integer
```

```
instance.Fit = value
```

```
value = instance.Fit
```

C#

```
System.int Fit {get; set;}
```

C++/CLI

```
property System.int Fit {
    System.int get();
    void set ( & System.int value);
}
```

Property Value

Number of digits that fit as defined by [swiBalloonSettingsFit_e](#)

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

GetOffsets Method (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : GetOffsets Method (BalloonSettings)

Gets whether to balloon the specified offset type in the document and gets the current offsets for the specified offset type.

.NET Syntax

Visual Basic (Declaration)

```
Function GetOffsets( _
    ByVal Type As System.Integer, _
    ByRef IsVisible As System.Boolean, _
    ByRef X\_Offset As System.Double, _
    ByRef Y\_Offset As System.Double _
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettings
Dim Type As System.Integer
Dim IsVisible As System.Boolean
Dim X_Offset As System.Double
Dim Y_Offset As System.Double
Dim value As System.Boolean
```

```
value = instance.GetOffsets(Type, IsVisible, X_Offset, Y_Offset)
```

C#

```
System.bool GetOffsets(
    System.int Type,
    out System.bool IsVisible,
    out System.double X\_Offset,
    out System.double Y\_Offset
)
```

C++/CLI

```
System.bool GetOffsets(
    & System.int Type,
    & [Out] System.bool IsVisible,
    & [Out] System.double X\_Offset,
```

```
& [Out] System.double Y_Offset
)
```

Parameters

Type

Offset type as defined by [swiBalloonSettingsOffsetTypes_e](#)

isVisible

True to balloon the offset type in the document, false to just include it in the inspection report

X_Offset

X offset for the default location of the balloons

Y_Offset

Y offset for the default location of the balloons

Return Value

True if offset settings successfully retrieved, false if not

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) methods.

Remarks

X_Offset and Y_Offset are from the upper left-hand corner of the attribute to the upper left-hand corner of the balloon. The offsets can be positive or negative numbers.

For more information, see the Ballooning Settings PropertyManager - Offsets section of the **SOLIDWORKS Inspection Add-in user-interface help > SOLIDWORKS Inspection > SOLIDWORKS Inspection Add-in > Getting Started > Balloons** topic.

See Also

[BalloonSettings Interface](#)

[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

KeyCharFit Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : KeyCharFit Property (BalloonSettings)

Gets and sets the number of digits that fit in a key characteristic balloon.

.NET Syntax

Visual Basic (Declaration)

```
Property KeyCharFit As System.Integer
```

Visual Basic (Usage)



```
Dim instance As BalloonSettings
```

```
Dim value As System.Integer
```

```
instance.KeyCharFit = value
```

```
value = instance.KeyCharFit
```

C#

```
System.int KeyCharFit {get; set;}
```

C++/CLI

```
property System.int KeyCharFit {  
    System.int get();
```

```
void set ( & System.int value);  
}
```

Property Value

Number of digits that fit as defined by [swiBalloonSettingsFit_e](#)

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

Remarks

Key characteristics are characteristics whose variation has a significant impact on the quality of the part.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

KeyCharPrefix Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : KeyCharPrefix Property (BalloonSettings)

Gets and sets the prefix to add to the balloons for key characteristics.

.NET Syntax

Visual Basic (Declaration)

Property KeyCharPrefix As System.String

Visual Basic (Usage)



```
Dim instance As BalloonSettings  
Dim value As System.String  
  
instance.KeyCharPrefix = value  
  
value = instance.KeyCharPrefix
```

C#

```
System.string KeyCharPrefix {get; set;}
```

C++/CLI

```
property System.String^ KeyCharPrefix {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Prefix

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

Remarks

Key characteristics are characteristics whose variation has a significant impact on the quality of the part.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

KeyCharShape Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : KeyCharShape Property (BalloonSettings)

Gets and sets the balloon shape for key characteristics.

.NET Syntax

Visual Basic (Declaration)

Property KeyCharShape As System.Integer

Visual Basic (Usage)



```
Dim instance As BalloonSettings  
Dim value As System.Integer
```

```
instance.KeyCharShape = value
```

```
value = instance.KeyCharShape
```

C#

```
System.int KeyCharShape {get; set;}
```

C++/CLI

```
property System.int KeyCharShape {  
    System.int get();  
    void set ( & System.int value);  
}
```

Property Value

Balloon shape as defined by [swBalloonSettingsShape_e](#)

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

Remarks

Key characteristics are characteristics whose variation has a significant impact on the quality of the part.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Layer Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : Layer Property (BalloonSettings)

Gets and sets the drawing layer to which to add this balloon.

.NET Syntax

Visual Basic (Declaration)

Property Layer As System.Integer

Visual Basic (Usage)



```
Dim instance As BalloonSettings  
Dim value As System.Integer
```

```
instance.Layer = value
```

```
value = instance.Layer
```

C#

```
System.int Layer {get; set;}
```

C++/CLI

```
property System.int Layer {  
    System.int get();  
    void set ( & System.int value);  
}
```

Property Value

Drawing layer as defined by [swiBalloonSettingLayer_e](#)

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

Remarks

This property is valid only for drawings.

If you set this property to swiLayer_UseSpecificLayer, use [IBalloonSettings::UserSpecifiedLayer](#) to set the name of the layer.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Prefix Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : Prefix Property (BalloonSettings)

Gets and sets the prefix to add to the balloons of regular characteristics.

.NET Syntax

Visual Basic (Declaration)

Property Prefix As System.String

Visual Basic (Usage)

```
Dim instance As BalloonSettings  
Dim value As System.String  
  
instance.Prefix = value  
  
value = instance.Prefix
```

C#

```
System.string Prefix {get; set;}
```

C++/CLI

```
property System.String^ Prefix {  
    System.String^ get();  
    void set ( &    System.String^ value);  
}
```

Property Value

Prefix

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

RotateToMatchCharacteristic Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : RotateToMatchCharacteristic Property (BalloonSettings)

Gets and sets whether to rotate this balloon to match the angle of the characteristic.

.NET Syntax

Visual Basic (Declaration)

```
Property RotateToMatchCharacteristic As System.Boolean
```

Visual Basic (Usage)

```
Dim instance As BalloonSettings  
Dim value As System.Boolean  
  
instance.RotateToMatchCharacteristic = value  
  
value = instance.RotateToMatchCharacteristic
```

C#

```
System.bool RotateToMatchCharacteristic {get; set;}
```

C++/CLI

```
property System.bool RotateToMatchCharacteristic {  
    System.bool get();
```

```
void set ( & System.bool value);  
}
```

Property Value

True to rotate the balloon to match the characteristic's angle, false to not

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

Remarks

This property is valid only for drawings.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

SetOffsets Method (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [BalloonSettings Interface](#) : SetOffsets Method (BalloonSettings)

Sets whether to balloon the specified offset type in the document and gets the current offsets for the specified offset type.

.NET Syntax

Visual Basic (Declaration)

```
Function SetOffsets( _  
    ByVal Type As System.Integer, _  
    ByVal IsVisible As System.Boolean, _  
    ByVal X\_Offset As System.Double, _  
    ByVal Y\_Offset As System.Double _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettings  
Dim Type As System.Integer  
Dim IsVisible As System.Boolean  
Dim X_Offset As System.Double  
Dim Y_Offset As System.Double  
Dim value As System.Boolean
```

```
value = instance.SetOffsets(Type, IsVisible, X_Offset, Y_Offset)
```

C#

```
System.bool SetOffsets(  
    System.int Type,  
    System.bool IsVisible,  
    System.double X\_Offset,  
    System.double Y\_Offset  
)
```

C++/CLI

```
System.bool SetOffsets(  
& System.int Type,  
& System.bool IsVisible,
```

```
& System.double X_Offset,  
& System.double Y_Offset  
)
```

Parameters

Type

Offset type as defined by [swiBalloonSettingsOffsetTypes_e](#)

isVisible

True to balloon the offset type in the document, false to just include it in the inspection report

X_Offset

X offset for the default location of the balloons

Y_Offset

Y offset for the default location of the balloons

Return Value

True if offset settings successfully set, false if not

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) methods.

Remarks

X_Offset and Y_Offset are from the upper left-hand corner of the attribute to the upper left-hand corner of the balloon. The offsets can be positive or negative numbers.

For more information, see the Ballooning Settings PropertyManager - Offsets section of the **SOLIDWORKS Inspection Add-in user-interface help > SOLIDWORKS Inspection > SOLIDWORKS Inspection Add-in > Getting Started > Balloons** topic.

See Also

[BalloonSettings Interface](#)

[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Shape Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [BalloonSettings Interface](#) : Shape Property (BalloonSettings)

Gets and sets the balloon shape for regular characteristics.

.NET Syntax

Visual Basic (Declaration)

Property Shape As System.Integer

Visual Basic (Usage)



```
Dim instance As BalloonSettings  
Dim value As System.Integer
```

```
instance.Shape = value
```

```
value = instance.Shape
```

C#

```
System.int Shape {get; set;}
```

C++/CLI

```
property System.int Shape {  
    System.int get();
```

```
void set ( & System.int value);  
}
```

Property Value

Balloon shape as defined by [swiBalloonSettingsShape_e](#)

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

UserSpecifiedLayer Property (BalloonSettings)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettings Interface](#) : UserSpecifiedLayer Property (BalloonSettings)

Gets and sets the user-specified layer.

.NET Syntax

Visual Basic (Declaration)

```
Property UserSpecifiedLayer As System.String
```

Visual Basic (Usage)



```
Dim instance As BalloonSettings  
Dim value As System.String  
  
instance.UserSpecifiedLayer = value  
value = instance.UserSpecifiedLayer
```

C#

```
System.string UserSpecifiedLayer {get; set;}
```

C++/CLI

```
property System.String^ UserSpecifiedLayer {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Name of user-specified layer

Visual Basic for Applications (VBA) Syntax

See [BalloonSettings](#) properties.

Remarks

This property is valid only:

- for drawings.
- when [IBalloonSettings::Layer](#) is set to [swiBalloonSettingLayer_e.swiLayer_UseSpecificLayer](#).

See Also

[BalloonSettings Interface](#)
[BalloonSettings Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

BalloonSettingsClass (Type)

BalloonSettingsClass Class

[See Also](#) [Members](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : BalloonSettingsClass Class

Object Model

BalloonSettingsClass

.NET Syntax

Visual Basic (Declaration)

```
Public Class BalloonSettingsClass
    Implements BalloonSettings, IBalloonSettings
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass
```

C#

```
public class BalloonSettingsClass : BalloonSettings, IBalloonSettings
```

C++/CLI

```
public ref class BalloonSettingsClass : public BalloonSettings, IBalloonSettings
```

See Also

[BalloonSettingsClass Members](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

BalloonSettingsClass Class Methods

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : BalloonSettingsClass Class

For a list of all members of this type, see [BalloonSettingsClass members](#).

Public Methods

Name	Description
Apply	
GetOffsets	
SetOffsets	

[Top](#)

See Also

[BalloonSettingsClass Class](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

BalloonSettingsClass Class Members

[See Also](#) [Properties](#) [Methods](#)



The following tables list the members exposed by [BalloonSettingsClass](#).

 Public Constructors

Name	Description
 public Cons BalloonSettingsClass Constructor	

[Top](#)

 Public Properties

Name	Description
 public Pr AttachToCharacteristic	
 public Pr Fit	
 public Pr KeyCharFit	
 public Pr KeyCharPrefix	
 public Pr KeyCharShape	
 public Pr Layer	
 public Pr Prefix	
 public Pr RotateToMatchCharacteristic	
 public Pr Shape	
 public Pr UserSpecifiedLayer	

[Top](#)

 Public Methods

Name	Description
 public M Apply	
 public M GetOffsets	
 public M SetOffsets	

[Top](#)

 See Also

[BalloonSettingsClass Class](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

BalloonSettingsClass Class Properties

[See Also](#)



For a list of all members of this type, see [BalloonSettingsClass members](#).

 Public Properties

Name	Description
 public Pr AttachToCharacteristic	
 public Pr Fit	
 public Pr KeyCharFit	
 public Pr KeyCharPrefix	
 public Pr KeyCharShape	
 public Pr Layer	

	Prefix
	RotateToMatchCharacteristic
	Shape
	UserSpecifiedLayer

[Top](#)

 See Also

- [BalloonSettingsClass Class](#)
- [SolidWorks.Interop.swinspectionAddIn Namespace](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

BalloonSettingsClass Constructor

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : BalloonSettingsClass Constructor

 .NET Syntax

Visual Basic (Declaration)

```
Public Function New()
```

Visual Basic (Usage)



```
Dim instance As New BalloonSettingsClass()
```

C#

```
public BalloonSettingsClass()
```

C++/CLI

```
public:
    BalloonSettingsClass();
```

 See Also

- [BalloonSettingsClass Class](#)
- [BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Apply Method (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : Apply Method (BalloonSettingsClass)

 .NET Syntax

Visual Basic (Declaration)

```
Public Overridable Function Apply() As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass
Dim value As System.Boolean
```

```
value = instance.Apply()
```

C#

```
public virtual System.bool Apply()
```

C++/CLI

```
public:  
virtual System.bool Apply();
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

AttachToCharacteristic Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : AttachToCharacteristic Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property AttachToCharacteristic As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.Boolean  
  
instance.AttachToCharacteristic = value  
value = instance.AttachToCharacteristic
```

C#

```
public virtual System.bool AttachToCharacteristic {get; set;}
```

C++/CLI

```
public:  
virtual property System.bool AttachToCharacteristic {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Fit Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : Fit Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property Fit As System.Integer
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.Integer
```

```
instance.Fit = value
```

```
value = instance.Fit
```

C#

```
public virtual System.int Fit {get; set;}
```

C++/CLI

```
public:  
virtual property System.int Fit {  
    System.int get();  
    void set ( & System.int value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

GetOffsets Method (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : GetOffsets Method (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Function GetOffsets( _  
    ByVal Type As System.Integer, _  
    ByRef IsVisible As System.Boolean, _  
    ByRef X\_Offset As System.Double, _  
    ByRef Y\_Offset As System.Double _  
    ) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim Type As System.Integer  
Dim IsVisible As System.Boolean  
Dim X_Offset As System.Double  
Dim Y_Offset As System.Double  
Dim value As System.Boolean  
  
value = instance.GetOffsets(Type, IsVisible, X_Offset, Y_Offset)
```

C#

```
public virtual System.bool GetOffsets(  
    System.int Type,  
    out System.bool IsVisible,  
    out System.double X\_Offset,  
    out System.double Y\_Offset  
)
```

C++/CLI

```
public:  
virtual System.bool GetOffsets(  
& System.int Type,  
& [Out] System.bool IsVisible,  
& [Out] System.double X\_Offset,  
& [Out] System.double Y\_Offset  
)
```

Parameters

Type
IsVisible
X_Offset
Y_Offset

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

KeyCharFit Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : KeyCharFit Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property KeyCharFit As System.Integer
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.Integer  
  
instance.KeyCharFit = value  
value = instance.KeyCharFit
```

C#

```
public virtual System.int KeyCharFit {get; set;}
```

C++/CLI

```
public:  
virtual property System.int KeyCharFit {  
    System.int get();  
    void set ( & System.int value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

KeyCharPrefix Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : KeyCharPrefix Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property KeyCharPrefix As System.String
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.String
```

```
instance.KeyCharPrefix = value  
value = instance.KeyCharPrefix
```

C#

```
public virtual System.string KeyCharPrefix {get; set;}
```

C++/CLI

```
public:  
virtual property System.String^ KeyCharPrefix {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

KeyCharShape Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : KeyCharShape Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property KeyCharShape As System.Integer
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.Integer
```

```
instance.KeyCharShape = value
```

```
value = instance.KeyCharShape
```

C#

```
public virtual System.int KeyCharShape {get; set;}
```

C++/CLI

```
public:  
virtual property System.int KeyCharShape {  
    System.int get();  
    void set ( & System.int value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Layer Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : Layer Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property Layer As System.Integer
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.Integer
```

```
instance.Layer = value
```

```
value = instance.Layer
```

C#

```
public virtual System.int Layer {get; set;}
```

C++/CLI

```
public:  
virtual property System.int Layer {  
    System.int get();  
    void set ( & System.int value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Prefix Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : Prefix Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property Prefix As System.String
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.String
```

```
instance.Prefix = value
```

```
value = instance.Prefix
```

C#

```
public virtual System.string Prefix {get; set;}
```

C++/CLI

```
public:  
virtual property System.String^ Prefix {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

RotateToMatchCharacteristic Property (BalloonSettingsClass)

[See Also](#)[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : RotateToMatchCharacteristic Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property RotateToMatchCharacteristic As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.Boolean  
  
instance.RotateToMatchCharacteristic = value  
  
value = instance.RotateToMatchCharacteristic
```

C#

```
public virtual System.bool RotateToMatchCharacteristic {get; set;}
```

C++/CLI

```
public:  
virtual property System.bool RotateToMatchCharacteristic {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SetOffsets Method (BalloonSettingsClass)

[See Also](#)[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : SetOffsets Method (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Function SetOffsets( _  
    ByVal Type As System.Integer, _  
    ByVal IsVisible As System.Boolean, _  
    ByVal X\_Offset As System.Double, _  
    ByVal Y\_Offset As System.Double _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim Type As System.Integer  
Dim IsVisible As System.Boolean  
Dim X_Offset As System.Double  
Dim Y_Offset As System.Double  
Dim value As System.Boolean  
  
value = instance.SetOffsets(Type, IsVisible, X_Offset, Y_Offset)
```

C#

```
public virtual System.bool SetOffsets(  
    System.int Type,  
    System.bool IsVisible,  
    System.double X\_Offset,  
    System.double Y\_Offset  
)
```

C++/CLI

```
public:  
virtual System.bool SetOffsets(  
& System.int Type,  
& System.bool IsVisible,  
& System.double X\_Offset,  
& System.double Y\_Offset  
)
```

Parameters

Type
IsVisible
X_Offset
Y_Offset

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Shape Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : Shape Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property Shape As System.Integer
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.Integer
```

```
instance.Shape = value
```

```
value = instance.Shape
```

C#

```
public virtual System.int Shape {get; set;}
```

C++/CLI

```
public:  
virtual property System.int Shape {  
    System.int get();  
    void set ( & System.int value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

UserSpecifiedLayer Property (BalloonSettingsClass)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [BalloonSettingsClass Class](#) : UserSpecifiedLayer Property (BalloonSettingsClass)

.NET Syntax

Visual Basic (Declaration)

```
Public Overridable Property UserSpecifiedLayer As System.String
```

Visual Basic (Usage)



```
Dim instance As BalloonSettingsClass  
Dim value As System.String
```

```
instance.UserSpecifiedLayer = value
```

```
value = instance.UserSpecifiedLayer
```

C#

```
public virtual System.string UserSpecifiedLayer {get; set;}
```

C++/CLI

```
public:  
virtual property System.String^ UserSpecifiedLayer {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

See Also

[BalloonSettingsClass Class](#)
[BalloonSettingsClass Members](#)

CharacteristicsData (Type)

 

[SolidWorks.Interop.swinspectionAddIn Namespace](#) : CharacteristicsData Interface

 .NET Syntax

Visual Basic (Declaration)

Public Interface CharacteristicsData
Inherits [ICharacteristicsData](#)

Visual Basic (Usage)

Dim instance As [CharacteristicsData](#)

C#

public interface CharacteristicsData : [ICharacteristicsData](#)

C++/CLI

public interface class CharacteristicsData : public [ICharacteristicsData](#)

 See Also

[CharacteristicsData Members](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

 

[SolidWorks.Interop.swinspectionAddIn Namespace](#) : CharacteristicsData Interface

The following tables list the members exposed by [CharacteristicsData](#).

 See Also

[CharacteristicsData Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

 

[SolidWorks.Interop.swinspectionAddIn Namespace](#) : CharacteristicsData Interface

For a list of all members of this type, see [CharacteristicsData members](#).

 See Also

[CharacteristicsData Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

 

[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Accept Property (CharacteristicsData)

Gets the threshold of defective units for accepting the entire lot.

 .NET Syntax

Visual Basic (Declaration)

ReadOnly Property Accept As System.String

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
value = instance.Accept
```

C#

```
System.string Accept {get;}
```

C++/CLI

```
property System.String^ Accept {  
    System.String^ get();  
}
```

Property Value

Threshold of defective units for acceptance of the lot

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The threshold is based on the sampling plan you selected for this dimension.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

AQL Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [CharacteristicsData Interface](#) : AQL Property (CharacteristicsData)

Gets and sets the acceptable quality level (AQL) for this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
Property AQL As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
instance.AQL = value
```

```
value = instance.AQL
```

C#

```
System.string AQL {get; set;}
```

C++/CLI

```
property System.String^ AQL {
    System.String^ get();
    void set ( & System.String^ value);
}
```

Property Value

Acceptable quality level for this characteristic

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

CharId Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : CharId Property (CharacteristicsData)

Gets the unique ID of the individual characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property CharId As System.Double
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData
Dim value As System.Double

value = instance.CharId
```

C#

```
System.double CharId {get;}
```

C++/CLI

```
property System.double CharId {
    System.double get();
}
```

Property Value

Characteristic ID

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

CharZone Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : CharZone Property (CharacteristicsData)

Gets the grid location of this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property CharZone As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String  
  
value = instance.CharZone
```

C#

```
System.string CharZone {get;}
```

C++/CLI

```
property System.String^ CharZone {  
    System.String^ get();  
}
```

Property Value

Grid location

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

Classification Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Classification Property (CharacteristicsData)

Gets and sets the classification of defects for this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
Property Classification As System.Integer
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.Integer
```

```
instance.Classification = value  
value = instance.Classification
```

C#

```
System.int Classification {get; set;}
```

C++/CLI

```
property System.int Classification {  
    System.int get();  
    void set ( &    System.int value);  
}
```

Property Value

Classification of defects as defined by [swiCharacteristicClassification_e](#)

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Comments Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Comments Property (CharacteristicsData)

Gets and sets the comment for this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Comments As System.String

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
instance.Comments = value
```

```
value = instance.Comments
```

C#

```
System.string Comments {get; set;}
```

C++/CLI

```
property System.String^ Comments {  
    System.String^ get();  
    void set ( &    System.String^ value);  
}
```

Property Value

Comment

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

ConfigurationName Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : ConfigurationName Property (CharacteristicsData)

Gets the SOLIDWORKS configuration associated with this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property ConfigurationName As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
value = instance.ConfigurationName
```

C#

```
System.string ConfigurationName {get;}
```

C++/CLI

```
property System.String^ ConfigurationName {  
    System.String^ get();  
}
```

Property Value

Name of a SOLIDWORKS configuration

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

ID Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : ID Property (CharacteristicsData)

Gets the GUID of this characteristic data set.

.NET Syntax

Visual Basic (Declaration)

ReadOnly Property ID As System.String

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String  
  
value = instance.ID
```

C#

```
System.string ID {get;}
```

C++/CLI

```
property System.String^ ID {  
    System.String^ get();  
}
```

Property Value

GUID

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Key Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Key Property (CharacteristicsData)

Gets and sets whether this characteristic is a key characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Key As System.Boolean

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.Boolean  
  
instance.Key = value  
  
value = instance.Key
```

C#

```
System.bool Key {get; set;}
```

C++/CLI

```
property System.bool Key {
    System.bool get();
    void set ( & System.bool value);
}
```

Property Value

True if key, false if regular

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

Key characteristics are characteristics whose variation has a significant impact on the quality of the part.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

LowerLimit Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : LowerLimit Property (CharacteristicsData)

Gets and sets the absolute lower limit of this characteristic's dimension.

.NET Syntax

Visual Basic (Declaration)

```
Property LowerLimit As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData
Dim value As System.String
```

```
instance.LowerLimit = value
```

```
value = instance.LowerLimit
```

C#

```
System.string LowerLimit {get; set;}
```

C++/CLI

```
property System.String^ LowerLimit {
    System.String^ get();
    void set ( & System.String^ value);
}
```

Property Value

Absolute lower limit

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The absolute lower limit of a dimension is its nominal value minus its lower tolerance value.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Method Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Method Property (CharacteristicsData)

Gets and sets the inspection method used for this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Method As System.String

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
instance.Method = value
```

```
value = instance.Method
```

C#

```
System.string Method {get; set;}
```

C++/CLI

```
property System.String^ Method {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Name of an inspection method

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Operation Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Operation Property (CharacteristicsData)

Gets and sets the inspection process used for this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Operation As System.String

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
instance.Operation = value
```

```
value = instance.Operation
```

C#

```
System.string Operation {get; set;}
```

C++/CLI

```
property System.String^ Operation {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Name of an inspection operation

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Quantity Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Quantity Property (CharacteristicsData)

Gets and sets the number of this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Quantity As System.Integer

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.Integer
```

```
instance.Quantity = value
```

```
value = instance.Quantity
```

C#

```
System.int Quantity {get; set;}
```

C++/CLI

```
property System.int Quantity {  
    System.int get();  
    void set ( & System.int value);  
}
```

Property Value

Number of this characteristic

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Reference Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Reference Property (CharacteristicsData)

Gets and sets whether this characteristic is a reference dimension.

.NET Syntax

Visual Basic (Declaration)

```
Property Reference As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.Boolean
```

```
instance.Reference = value
```

```
value = instance.Reference
```

C#

```
System.bool Reference {get; set;}
```

C++/CLI

```
property System.bool Reference {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

Property Value

True if a reference dimension, false if not

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Reject Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Reject Property (CharacteristicsData)

Gets the threshold of defective units for rejecting the entire lot.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property Reject As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
value = instance.Reject
```

C#

```
System.string Reject {get;}
```

C++/CLI

```
property System.String^ Reject {  
    System.String^ get();  
}
```

Property Value

Threshold of defective units for rejecting the entire lot

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The threshold is based on the sampling plan you selected for this dimension.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

SampleSize Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : SampleSize Property (CharacteristicsData)

Gets and sets the sample size for this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property SampleSize As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String  
  
value = instance.SampleSize
```

C#

```
System.string SampleSize {get;}
```

C++/CLI

```
property System.String^ SampleSize {  
    System.String^ get();  
}
```

Property Value

Sample size

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Selected Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Selected Property (CharacteristicsData)

Gets and sets whether to include this characteristic in the inspection report.

.NET Syntax

Visual Basic (Declaration)

```
Property Selected As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.Boolean  
  
instance.Selected = value  
  
value = instance.Selected
```

C#

```
System.bool Selected {get; set;}
```

C++/CLI

```
property System.bool Selected {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

Property Value

True to include, false to not

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Sheet Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Sheet Property (CharacteristicsData)

Gets the SOLIDWORKS drawing sheet where this characteristic is located.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property Sheet As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String  
  
value = instance.Sheet
```

C#

```
System.string Sheet {get;}
```

C++/CLI

```
property System.String^ Sheet {  
    System.String^ get();  
}
```

Property Value

Name of a SOLIDWORKS drawing sheet

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

SubType Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : SubType Property (CharacteristicsData)

Gets the sub-type of this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property SubType As System.Integer
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.Integer
```

```
value = instance.SubType
```

C#

```
System.int SubType {get;}
```

C++/CLI

```
property System.int SubType {  
    System.int get();  
}
```

Property Value

Sub-type as defined by [swCharacteristicSubType_e](#)

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

ToleranceMinus Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : ToleranceMinus Property (CharacteristicsData)

Gets and sets this characteristic's lower tolerance value.

.NET Syntax

Visual Basic (Declaration)

```
Property ToleranceMinus As System.String
```

Visual Basic (Usage)

```
Dim instance As CharacteristicsData
Dim value As System.String

instance.ToleranceMinus = value

value = instance.ToleranceMinus
```

C#

```
System.string ToleranceMinus {get; set;}
```

C++/CLI

```
property System.String^ ToleranceMinus {
    System.String^ get();
    void set ( &    System.String^ value);
}
```

Property Value

Lower tolerance value

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

TolerancePlus Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : TolerancePlus Property (CharacteristicsData)

Gets and sets this characteristic's upper tolerance value.

.NET Syntax

Visual Basic (Declaration)

```
Property TolerancePlus As System.String
```

Visual Basic (Usage)

```
Dim instance As CharacteristicsData
Dim value As System.String

instance.TolerancePlus = value

value = instance.TolerancePlus
```

C#

```
System.string TolerancePlus {get; set;}
```

C++/CLI

```
property System.String^ TolerancePlus {
    System.String^ get();
```

```
void set ( & System.String^ value);  
}
```

Property Value

Upper tolerance value

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Units Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Units Property (CharacteristicsData)

Gets the units for this characteristic's nominal and tolerance values.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property Units As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
value = instance.Units
```

C#

```
System.string Units {get;}
```

C++/CLI

```
property System.String^ Units {  
    System.String^ get();  
}
```

Property Value

Units of nominal and tolerance values:

"in"

"mm"

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

UpperLimit Property (CharacteristicsData)

[See Also](#)[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : UpperLimit Property (CharacteristicsData)

Gets and sets the absolute upper limit of this characteristic's dimension.

.NET Syntax

Visual Basic (Declaration)

```
Property UpperLimit As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
instance.UpperLimit = value
```

```
value = instance.UpperLimit
```

C#

```
System.string UpperLimit {get; set;}
```

C++/CLI

```
property System.String^ UpperLimit {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Absolute upper limit

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The absolute upper limit of a dimension is its nominal value plus its upper tolerance value.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

Value Property (CharacteristicsData)

[See Also](#)[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : Value Property (CharacteristicsData)

Gets and sets the value of this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Value As System.String

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
instance.Value = value
```

```
value = instance.Value
```

C#

```
System.string Value {get; set;}
```

C++/CLI

```
property System.String^ Value {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Value

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

View Property (CharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [CharacteristicsData Interface](#) : View Property (CharacteristicsData)

Gets the SOLIDWORKS drawing view with which this characteristic is associated.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property View As System.String
```

Visual Basic (Usage)



```
Dim instance As CharacteristicsData  
Dim value As System.String
```

```
value = instance.View
```

C#

```
System.string View {get;}
```

C++/CLI

```
property System.String^ View {  
    System.String^ get();  
}
```

}

Property Value

Name of a SOLIDWORKS drawing view

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[CharacteristicsData Interface](#)
[CharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS