

SOLIDWORKS Inspection Add-in API (.NET) — Reference (3/7): ICharacteristicsData- IInspectionAddinMgr

SOLIDWORKS API Documentation (converted from CHM)

ICharacteristicsData (Type)

ICharacteristicsData Interface

[See Also](#) [Members](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : ICharacteristicsData Interface

Allows access to characteristics data.
NOTE: Click the **Members** link, located near the top of the topic, to see this interface's methods and properties.

.NET Syntax

Visual Basic (Declaration)

Public Interface ICharacteristicsData

Visual Basic (Usage)



Dim instance As [ICharacteristicsData](#)

C#

public interface ICharacteristicsData

C++/CLI

public interface class ICharacteristicsData

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#).

Remarks

Characteristics are items that have been extracted from the drawing to incorporate in the inspection report. Use this interface to change data for specific characteristics after it has been extracted.

For more information, see:

SOLIDWORKS Inspection Add-in user-interface help > SOLIDWORKS Inspection > Working with Templates > Mapping Characteristic Tokens to Report Templates > Characteristic Tokens topic.

SOLIDWORKS Inspection Add-in user-interface help > SOLIDWORKS Inspection > SOLIDWORKS Inspection Add-in > Getting Started : Using the Bill of Characteristics topic.

Accessors

[IInspectionAddinMgr::AddCharacteristics](#)

[IInspectionAddinMgr::GetCharacteristicsData](#)

See Also

[ICharacteristicsData Members](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

ICharacteristicsData Interface Members

[See Also](#) [Properties](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) : ICharacteristicsData Interface

The following tables list the members exposed by [ICharacteristicsData](#).

Public Properties

Name	Description
Accept	Gets the threshold of defective units for accepting the entire lot.

 AQL	Gets and sets the acceptable quality level (AQL) for this characteristic.
 CharId	Gets the unique ID of the individual characteristic.
 CharZone	Gets the grid location of this characteristic.
 Classification	Gets and sets the classification of defects for this characteristic.
 Comments	Gets and sets the comment for this characteristic.
 ConfigurationName	Gets the SOLIDWORKS configuration associated with this characteristic.
 ID	Gets the GUID of this characteristic data set.
 Key	Gets and sets whether this characteristic is a key characteristic.
 LowerLimit	Gets and sets the absolute lower limit of this characteristic's dimension.
 Method	Gets and sets the inspection method used for this characteristic.
 Operation	Gets and sets the inspection process used for this characteristic.
 Quantity	Gets and sets the number of this characteristic.
 Reference	Gets and sets whether this characteristic is a reference dimension.
 Reject	Gets the threshold of defective units for rejecting the entire lot.
 SampleSize	Gets and sets the sample size for this characteristic.
 Selected	Gets and sets whether to include this characteristic in the inspection report.
 Sheet	Gets the SOLIDWORKS drawing sheet where this characteristic is located.
 SubType	Gets the sub-type of this characteristic.
 ToleranceMinus	Gets and sets this characteristic's lower tolerance value.
 TolerancePlus	Gets and sets this characteristic's upper tolerance value.
 Units	Gets the units for this characteristic's nominal and tolerance values.
 UpperLimit	Gets and sets the absolute upper limit of this characteristic's dimension.
 Value	Gets and sets the value of this characteristic.
 View	Gets the SOLIDWORKS drawing view with which this characteristic is associated.

[Top](#)

See Also

[ICharacteristicsData Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

ICharacteristicsData Interface Properties

[See Also](#)

[SolidWorks.Interop.swinspectionAddIn Namespace](#) : ICharacteristicsData Interface

For a list of all members of this type, see [ICharacteristicsData members](#).

Public Properties

Name	Description
 Accept	Gets the threshold of defective units for accepting the entire lot.
 AQL	Gets and sets the acceptable quality level (AQL) for this characteristic.
 CharId	Gets the unique ID of the individual characteristic.
 CharZone	Gets the grid location of this characteristic.
 Classification	Gets and sets the classification of defects for this characteristic.
 Comments	Gets and sets the comment for this characteristic.
 ConfigurationName	Gets the SOLIDWORKS configuration associated with this characteristic.
ID	Gets the GUID of this characteristic data set.

Key	Gets and sets whether this characteristic is a key characteristic.
LowerLimit	Gets and sets the absolute lower limit of this characteristic's dimension.
Method	Gets and sets the inspection method used for this characteristic.
Operation	Gets and sets the inspection process used for this characteristic.
Quantity	Gets and sets the number of this characteristic.
Reference	Gets and sets whether this characteristic is a reference dimension.
Reject	Gets the threshold of defective units for rejecting the entire lot.
SampleSize	Gets and sets the sample size for this characteristic.
Selected	Gets and sets whether to include this characteristic in the inspection report.
Sheet	Gets the SOLIDWORKS drawing sheet where this characteristic is located.
SubType	Gets the sub-type of this characteristic.
ToleranceMinus	Gets and sets this characteristic's lower tolerance value.
TolerancePlus	Gets and sets this characteristic's upper tolerance value.
Units	Gets the units for this characteristic's nominal and tolerance values.
UpperLimit	Gets and sets the absolute upper limit of this characteristic's dimension.
Value	Gets and sets the value of this characteristic.
View	Gets the SOLIDWORKS drawing view with which this characteristic is associated.

[Top](#)

See Also

[ICharacteristicsData Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Accept Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Accept Property (ICharacteristicsData)

Gets the threshold of defective units for accepting the entire lot.

.NET Syntax

Visual Basic (Declaration)

ReadOnly Property Accept As System.String

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData
Dim value As System.String
```

```
value = instance.Accept
```

C#

```
System.string Accept {get;}
```

C++/CLI

```
property System.String^ Accept {
    System.String^ get();
}
```

Property Value

Threshold of defective units for acceptance of the lot

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The threshold is based on the sampling plan you selected for this dimension.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

AQL Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : AQL Property (ICharacteristicsData)

Gets and sets the acceptable quality level (AQL) for this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property AQL As System.String

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.AQL = value
```

```
value = instance.AQL
```

C#

```
System.string AQL {get; set;}
```

C++/CLI

```
property System.String^ AQL {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Acceptable quality level for this characteristic

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

CharId Property (ICharacteristicsData)

[See Also](#)[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : CharId Property (ICharacteristicsData)

Gets the unique ID of the individual characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property CharId As System.Double
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData
Dim value As System.Double

value = instance.CharId
```

C#

```
System.double CharId {get;}
```

C++/CLI

```
property System.double CharId {
    System.double get();
}
```

Property Value

Characteristic ID

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

CharZone Property (ICharacteristicsData)

[See Also](#)[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : CharZone Property (ICharacteristicsData)

Gets the grid location of this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property CharZone As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData
Dim value As System.String

value = instance.CharZone
```

C#

```
System.string CharZone {get;}
```

C++/CLI

```
property System.String^ CharZone {  
    System.String^ get();  
}
```

Property Value

Grid location

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Classification Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Classification Property (ICharacteristicsData)

Gets and sets the classification of defects for this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
Property Classification As System.Integer
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.Integer
```

```
instance.Classification = value
```

```
value = instance.Classification
```

C#

```
System.int Classification {get; set;}
```

C++/CLI

```
property System.int Classification {  
    System.int get();  
    void set ( & System.int value);  
}
```

Property Value

Classification of defects as defined by [swiCharacteristicClassification_e](#)

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Comments Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Comments Property (ICharacteristicsData)

Gets and sets the comment for this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Comments As System.String

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.Comments = value
```

```
value = instance.Comments
```

C#

```
System.string Comments {get; set;}
```

C++/CLI

```
property System.String^ Comments {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Comment

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

ConfigurationName Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : ConfigurationName Property (ICharacteristicsData)

Gets the SOLIDWORKS configuration associated with this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property ConfigurationName As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String  
  
value = instance.ConfigurationName
```

C#

```
System.string ConfigurationName {get;}
```

C++/CLI

```
property System.String^ ConfigurationName {  
    System.String^ get();  
}
```

Property Value

Name of a SOLIDWORKS configuration

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

ID Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : ID Property (ICharacteristicsData)

Gets the GUID of this characteristic data set.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property ID As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String  
  
value = instance.ID
```

C#

```
System.string ID {get;}
```

C++/CLI

```
property System.String^ ID {
    System.String^ get();
}
```

Property Value

GUID

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Key Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Key Property (ICharacteristicsData)

Gets and sets whether this characteristic is a key characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Key As System.Boolean

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData
Dim value As System.Boolean
```

```
instance.Key = value
```

```
value = instance.Key
```

C#

```
System.bool Key {get; set;}
```

C++/CLI

```
property System.bool Key {
    System.bool get();
    void set ( & System.bool value);
}
```

Property Value

True if key, false if regular

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

Key characteristics are characteristics whose variation has a significant impact on the quality of the part.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

LowerLimit Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : LowerLimit Property (ICharacteristicsData)

Gets and sets the absolute lower limit of this characteristic's dimension.

.NET Syntax

Visual Basic (Declaration)

```
Property LowerLimit As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.LowerLimit = value
```

```
value = instance.LowerLimit
```

C#

```
System.string LowerLimit {get; set;}
```

C++/CLI

```
property System.String^ LowerLimit {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Absolute lower limit

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The absolute lower limit of a dimension is its nominal value minus its lower tolerance value.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Method Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Method Property (ICharacteristicsData)

Gets and sets the inspection method used for this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Method As System.String

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.Method = value
```

```
value = instance.Method
```

C#

```
System.string Method {get; set;}
```

C++/CLI

```
property System.String^ Method {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Name of an inspection method

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Operation Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Operation Property (ICharacteristicsData)

Gets and sets the inspection process used for this characteristic.

.NET Syntax

Visual Basic (Declaration)

Property Operation As System.String

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.Operation = value
```

```
value = instance.Operation
```

C#

```
System.string Operation {get; set;}
```

C++/CLI

```
property System.String^ Operation {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Name of an inspection operation

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

Quantity Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [ICharacteristicsData Interface](#) : Quantity Property (ICharacteristicsData)

Gets and sets the number of this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
Property Quantity As System.Integer
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.Integer
```

```
instance.Quantity = value
```

```
value = instance.Quantity
```

C#

```
System.int Quantity {get; set;}
```

C++/CLI

```
property System.int Quantity {  
    System.int get();  
    void set ( & System.int value);  
}
```

Property Value

Number of this characteristic

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Reference Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Reference Property (ICharacteristicsData)

Gets and sets whether this characteristic is a reference dimension.

.NET Syntax

Visual Basic (Declaration)

Property Reference As System.Boolean

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.Boolean
```

```
instance.Reference = value
```

```
value = instance.Reference
```

C#

```
System.bool Reference {get; set;}
```

C++/CLI

```
property System.bool Reference {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

Property Value

True if a reference dimension, false if not

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Reject Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Reject Property (ICharacteristicsData)

Gets the threshold of defective units for rejecting the entire lot.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property Reject As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
value = instance.Reject
```

C#

```
System.string Reject {get;}
```

C++/CLI

```
property System.String^ Reject {  
    System.String^ get();  
}
```

Property Value

Threshold of defective units for rejecting the entire lot

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The threshold is based on the sampling plan you selected for this dimension.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

SampleSize Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : SampleSize Property (ICharacteristicsData)

Gets and sets the sample size for this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property SampleSize As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
value = instance.SampleSize
```

C#

```
System.string SampleSize {get;}
```

C++/CLI

```
property System.String^ SampleSize {  
    System.String^ get();  
}
```

Property Value

Sample size

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Selected Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Selected Property (ICharacteristicsData)

Gets and sets whether to include this characteristic in the inspection report.

.NET Syntax

Visual Basic (Declaration)

```
Property Selected As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.Boolean
```

```
instance.Selected = value
```

```
value = instance.Selected
```

C#

```
System.bool Selected {get; set;}
```

C++/CLI

```
property System.bool Selected {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

Property Value

True to include, false to not

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

 See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

 Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Sheet Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Sheet Property (ICharacteristicsData)

Gets the SOLIDWORKS drawing sheet where this characteristic is located.

 .NET Syntax

Visual Basic (Declaration)

ReadOnly Property Sheet As System.String

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String  
  
value = instance.Sheet
```

C#

```
System.string Sheet {get;}
```

C++/CLI

```
property System.String^ Sheet {  
    System.String^ get();  
}
```

Property Value

Name of a SOLIDWORKS drawing sheet

 Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

 See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

 Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

SubType Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : SubType Property (ICharacteristicsData)

Gets the sub-type of this characteristic.

 .NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property SubType As System.Integer
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.Integer  
  
value = instance.SubType
```

C#

```
System.int SubType {get;}
```

C++/CLI

```
property System.int SubType {  
    System.int get();  
}
```

Property Value

Sub-type as defined by [swiCharacteristicSubType_e](#)

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

ToleranceMinus Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : ToleranceMinus Property (ICharacteristicsData)

Gets and sets this characteristic's lower tolerance value.

.NET Syntax

Visual Basic (Declaration)

```
Property ToleranceMinus As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String  
  
instance.ToleranceMinus = value  
value = instance.ToleranceMinus
```

C#

```
System.string ToleranceMinus {get; set;}
```

C++/CLI

```
property System.String^ ToleranceMinus {  
    System.String^ get();
```

```
void set ( & System.String^ value);  
}
```

Property Value

Lower tolerance value

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

TolerancePlus Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : TolerancePlus Property (ICharacteristicsData)

Gets and sets this characteristic's upper tolerance value.

.NET Syntax

Visual Basic (Declaration)

Property TolerancePlus As System.String

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.TolerancePlus = value
```

```
value = instance.TolerancePlus
```

C#

```
System.string TolerancePlus {get; set;}
```

C++/CLI

```
property System.String^ TolerancePlus {  
    System.String^ get();  
    void set ( & System.String^ value);  
}
```

Property Value

Upper tolerance value

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

Units Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Units Property (ICharacteristicsData)

Gets the units for this characteristic's nominal and tolerance values.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property Units As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData
Dim value As System.String

value = instance.Units
```

C#

```
System.string Units {get;}
```

C++/CLI

```
property System.String^ Units {
    System.String^ get();
}
```

Property Value

Units of nominal and tolerance values:

"in"

"mm"

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

UpperLimit Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : UpperLimit Property (ICharacteristicsData)

Gets and sets the absolute upper limit of this characteristic's dimension.

.NET Syntax

Visual Basic (Declaration)

```
Property UpperLimit As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.UpperLimit = value
```

```
value = instance.UpperLimit
```

C#

```
System.string UpperLimit {get; set;}
```

C++/CLI

```
property System.String^ UpperLimit {  
    System.String^ get();  
    void set ( &    System.String^ value);  
}
```

Property Value

Absolute upper limit

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

Remarks

The absolute upper limit of a dimension is its nominal value plus its upper tolerance value.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

Value Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : Value Property (ICharacteristicsData)

Gets and sets the value of this characteristic.

.NET Syntax

Visual Basic (Declaration)

```
Property Value As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData  
Dim value As System.String
```

```
instance.Value = value
```

```
value = instance.Value
```

C#

```
System.string Value {get; set;}
```

C++/CLI

```
property System.String^ Value {
    System.String^ get();
    void set ( & System.String^ value);
}
```

Property Value

Value

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

View Property (ICharacteristicsData)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [ICharacteristicsData Interface](#) : View Property (ICharacteristicsData)

Gets the SOLIDWORKS drawing view with which this characteristic is associated.

.NET Syntax

Visual Basic (Declaration)

```
ReadOnly Property View As System.String
```

Visual Basic (Usage)



```
Dim instance As ICharacteristicsData
Dim value As System.String

value = instance.View
```

C#

```
System.string View {get;}
```

C++/CLI

```
property System.String^ View {
    System.String^ get();
}
```

Property Value

Name of a SOLIDWORKS drawing view

Visual Basic for Applications (VBA) Syntax

See [CharacteristicsData](#) properties.

See Also

[ICharacteristicsData Interface](#)
[ICharacteristicsData Members](#)

Availability

IInspectionAddinMgr (Type)

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

IInspectionAddinMgr Interface

[See Also](#) [Members](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) : IInspectionAddinMgr Interface

Allows access to the inspection add-in manager.

NOTE: Click the **Members** link, located near the top of the topic, to see this interface's methods and properties.

.NET Syntax

Visual Basic (Declaration)

Public Interface IInspectionAddinMgr

Visual Basic (Usage)



Dim instance As [IInspectionAddinMgr](#)

C#

public interface IInspectionAddinMgr

C++/CLI

public interface class IInspectionAddinMgr

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#).

Example

```
'=====
'Preconditions:
'1. Activate the SOLIDWORKS Inspection Add-in (SOLIDWORKS Tools menu > Add-ins... > SOLIDWORKS Inspection).
'2. Ensure c:\templExport Testing exists.
'3. Ensure the templates specified in the macro exist.
'4. Open Public_Documents\SOLIDWORKS\SOLIDWORKS 2022\samples\tutorial\api\nist_ftc_08_asme1_rc_sw1702_ra.sldprt.
'5. Select SOLIDWORKS File menu > Make drawing from part.
'   a. Select default settings in Sheet Format/Size dialog.
'   b. In View Palette select all Import Annotations check boxes.
'   c. Drag and drop "A" views onto the drawing sheet.
'6. Open an Immediate window.
'
'Postconditions:
'1. Click OK to close message boxes as they appear.
'2. Configures general and extraction settings.
'3. Creates an inspection project.
'4. Balloons the drawing. (Ballooning starts at Char ID = 17.)
'5. Displays all the characteristic IDs.
'6. Adds a vendor named Sample.
'7. Displays inspection methods, operations, and vendors.
'8. Exports Inspection reports (Microsoft Excel, 2D PDF, eDrawings) to c:\templExport Testing.
'9. Close the Excel spreadsheet after it appears.
'10. Deletes vendor named Sample.
'11. Edits the inspection project by adding a document name.
'12. Re-balloons the drawing.
'13. Edits and applies the balloon settings.
'14. Re-balloons the drawing.
'15. Inspect the Immediate window.
'
'NOTE: Because the drawing is used elsewhere, do not save changes to it.
'=====
```

```
Dim swApp As SldWorks.SldWorks
Dim INSPECTIONMgr As SWInspectionAddin.InspectionAddinMgr
Dim InspectionPrj As SWInspectionAddin.InspectionProject
Dim InspectionPrjData As SWInspectionAddin.InspectionProjectData
Dim BalloonSetting As SWInspectionAddin.BalloonSettings
Dim CharData As SWInspectionAddin.CharacteristicsData
```

```

Dim OperationList As Variant
Dim OperationIDs As Variant
Dim VendorList As Variant
Dim MethodList As Variant
Dim MethodIDs As Variant
Dim Arr As Variant
Dim TemplatePath As String
Dim FilePath As String
Dim Multisheet As Boolean
Dim Status As Boolean
Dim a As Long
Dim str As String
Dim err As Long
Dim boolstatus As Boolean

Option Explicit
Sub main()

    Set swApp = Application.SldWorks

    Set INSPECTIONMgr = swApp.GetAddInObject("Inspection.ExtSwAddin")
    Set InspectionPrjData = INSPECTIONMgr.CreateInspectionProjectData("C:\\ProgramData\\SOLIDWORKS\\SOLIDWORKS Inspection 202\\Addin\\Templates\\default.swidot")

    'General settings
    Debug.Print "Inspection general settings..."
    Debug.Print ""
    InspectionPrjData.StartNumber = 17

    InspectionPrjData.Sort = 1
    Debug.Print "Characteristic sort as defined by swiCharacteristicInfoSort_e: " & InspectionPrjData.Sort

    InspectionPrjData.Classification = 0
    Debug.Print "Defect classification as defined by swiCharacteristicClassification_e: " & InspectionPrjData.Classification

    InspectionPrjData.Extraction = 0
    Debug.Print "Type of extraction as defined by swiCharacteristicInfoExtraction_e: " & InspectionPrjData.Extraction

    InspectionPrjData.AutoBalloon = True
    Debug.Print "Autoballoon drawing? " & InspectionPrjData.AutoBalloon

    'Extraction settings
    Debug.Print ""
    Debug.Print "Inspection extraction settings..."
    Debug.Print ""
    InspectionPrjData.Basic = True
    Debug.Print "Basic dimensioning? " & InspectionPrjData.Basic

    InspectionPrjData.SecondaryUnits = True
    Debug.Print "Extract dual dimensions? " & InspectionPrjData.SecondaryUnits

    'Create inspection project and balloon drawing
    Set InspectionPrj = INSPECTIONMgr.CreateInspectionProject(InspectionPrjData, True, err)
    If InspectionPrj Is Nothing Or Not err = swiErrorCode_e.swiSuccess Then
        MsgBox ("Project not created")
    End If

    'Balloon settings only available after inspection project is created and model is ballooned
    Debug.Print ""
    Debug.Print "Inspection balloon settings..."
    Debug.Print ""
    Set BalloonSetting = INSPECTIONMgr.GetBalloonSettings()

    If Not BalloonSetting Is Nothing Then

        Dim offsetType As Long
        offsetType = swiBalloonSettingsOffsetTypes_e.swiType_Dimensions

        Dim i As Integer
        i = 0

        For i = 0 To 6

            Dim isVis As Boolean
            Dim x As Double
            Dim y As Double

            Status = BalloonSetting.GetOffsets(i, isVis, x, y)

            Debug.Print "Offset type as defined by swiBalloonSettingsOffsetTypes_e: " & i & ", Balloon in document? " & isVis
            Debug.Print "X-offset: " & x & ", Y-offset: " & y

```

Next i

```
Debug.Print "BalloonBalloonSetting.as defined by swiBalloonSettingsFit_e: " & BalloonSetting.Fit
Debug.Print "BalloonBalloonSetting.as defined by swiBalloonSettingsShape_e: " & BalloonSetting.Shape
Debug.Print "BalloonBalloonSetting.as defined by swiBalloonSettingsFit_e: " & BalloonSetting.KeyCharFit
Debug.Print "BalloonBalloonSetting.as defined by swiBalloonSettingsShape_e: " & BalloonSetting.KeyCharShape
Debug.Print "Prefix: " & BalloonSetting.Prefix
Debug.Print "KeyCharPrefix: " & BalloonSetting.KeyCharPrefix
Debug.Print "BalloonBalloonSetting.: " & BalloonSetting.AttachToCharacteristic
Debug.Print "BalloonBalloonSetting.: " & BalloonSetting.RotateToMatchCharacteristic
Debug.Print "BalloonBalloonSetting.as defined by swiBalloonSettingLayer_e: " & BalloonSetting.Layer
Debug.Print "BalloonBalloonSetting.: " & BalloonSetting.UserSpecifiedLayer
```

End If

'Get characteristics data

Arr = INSPECTIONMgr.**GetCharacteristicIDs**()

str = "Characteristic IDs: "

str = str & vbCrLf

For i = 0 To UBound(Arr)

 'Add code here to get data for each characteristic

 'Set CharData = INSPECTIONMgr.**GetCharacteristicsData**(Arr(i))

 'Dim charID as Double

 'Debug.Print "Characteristic ID = " & Arr(i) & " is a reference dimension? " & CharData.**Reference**

 str = str & vbCrLf & Arr(i)

Next

MsgBox (str)

'Get inspection methods

str = "Inspection methods: "

str = str & vbCrLf

MethodList = Empty

Status = INSPECTIONMgr.**GetInspectionMethods**(MethodList, MethodIDs)

If Not Status Then

 MsgBox ("Error getting inspection methods")

Else

 For a = LBound(MethodList) To UBound(MethodList)

 str = str & vbCrLf & MethodList(a)

 Next

 MsgBox (str)

End If

'Add inspection method

'If Not INSPECTIONMgr.**AddInspectionMethod**("aa") Then

 'MsgBox ("Error adding inspection method")

'End If

'Edit inspection method

'If Not INSPECTIONMgr.**EditInspectionMethod**("9", "hh") Then

 'MsgBox ("Error editing inspection method")

'End If

'Get operations

OperationList = Empty

OperationIDs = Empty

str = "Operations: "

str = str & vbCrLf

Status = INSPECTIONMgr.**GetOperations**(OperationList, OperationIDs)

If Not Status Then

 MsgBox ("Error getting operations")

Else

 For a = LBound(OperationList) To UBound(OperationList)

 str = str & vbCrLf & OperationList(a)

 Next

 MsgBox (str)

End If

'Add operation

'If Not INSPECTIONMgr.**AddOperation**("Sample") Then

 'MsgBox ("Error adding operation")

'End If

'Add vendor

If Not INSPECTIONMgr.**AddVendor**("Sample", swiVendorsInspectionType_e.swiREDUCED) Then

 MsgBox ("Error adding vendor")

```

End If

'Get vendors
VendorList = Empty
str = "Vendors: "
str = str & vbCrLf
Status = INSPECTIONMgr.GetVendors(VendorList)

If Not Status Then
    MsgBox ("Error getting vendors")
Else
    For a = LBound(VendorList) To UBound(VendorList)
        str = str & vbCrLf & VendorList(a)
    Next
    MsgBox (str)
End If

'Export Inspection report to Microsoft Excel
TemplatePath = "C:\ProgramData\SOLIDWORKS\SOLIDWORKS Inspection 2022 Addin\Templates\PPAP - Dimensional Test Results.xlt"
FilePath = "c:\temp\Export Testing\MyTestexcel.xlsx"
Multisheet = True

If Not InspectionPrj.ExportToExcel(TemplatePath, FilePath, Multisheet) Then
    MsgBox ("Error exporting to Excel")
End If

'Export Inspection report to 2D PDF
If Not InspectionPrj.ExportTo2DPDF("c:\temp\Export Testing\MyTest2DPDF.PDF") Then
    MsgBox ("Error exporting to 2D PDF")
End If

'Export Inspection report to 3D PDF - only valid for Parts
'If Not InspectionPrj.ExportTo3DPDF("c:\temp\Export Testing\MyTest3DPDF.PDF") Then
'    MsgBox ("Error exporting to 3D PDF")
'End If

'Export Inspection report to eDrawings
If Not InspectionPrj.ExportToEDrawings("c:\temp\Export Testing\MyTestEDrawing.edrw") Then
    MsgBox ("Error exporting to eDrawings")
End If

'Delete one inspection method
'aa
Dim delMethod(0) As Variant
Dim errorArray As Variant
delMethod(0) = "aa"
'errorArray = INSPECTIONMgr.DeleteInspectionMethods(delMethod)

'Delete one operation
'Sample
Dim delOperation(0) As Variant
delOperation(0) = "Sample"
'errorArray = INSPECTIONMgr.DeleteOperations(delOperation)

'Delete one vendor
'Sample
Dim delVendor(0) As Variant
delVendor(0) = "Sample"
errorArray = INSPECTIONMgr.DeleteVendors(delVendor)

Debug.Print "Vendor Sample deleted? " & errorArray(0)

'Edit inspection project and re-balloon the drawing
Set InspectionPrjData = INSPECTIONMgr.GetInspectionProjectData
InspectionPrjData.DocumentName = "Test drawing"
boolstatus = INSPECTIONMgr.EditInspectionProject(InspectionPrjData)

'Change and apply balloon settings and re-balloon the drawing
Set BalloonSetting = INSPECTIONMgr.GetBalloonSettings()
Debug.Print ""
Debug.Print "Balloon setting changes..."
Debug.Print ""

BalloonSetting.Prefix = "B"
Debug.Print "Prefix: " & BalloonSetting.Prefix

BalloonSetting.KeyCharPrefix = "C"
Debug.Print "KeyCharPrefix: " & BalloonSetting.KeyCharPrefix

BalloonSetting.AttachToCharacteristic = True
Debug.Print "BalloonBalloonSetting.AttachToCharacteristic: " & BalloonSetting.AttachToCharacteristic

```

```

BalloonSetting.RotateToMatchCharacteristic = True
Debug.Print "BalloonBalloonSetting.RotateToMatchCharacteristic: " & BalloonSetting.RotateToMatchCharacteristic

BalloonSetting.Layer = 0
Debug.Print "BalloonBalloonSetting.Layer as defined by swiBalloonSettingLayer_e: " & BalloonSetting.Layer

Status = BalloonSetting.Apply

End Sub

```

Remarks

For more information, read:

- [Getting Started](#)
- **SOLIDWORKS Inspection Add-in user-interface help > SOLIDWORKS Inspection > SOLIDWORKS Inspection Add-in > Getting Started and Customization** topics.

Accessors

[ISldWorks::GetAddInObject](#)

See Also

[IInspectionAddInMgr Members](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

IInspectionAddInMgr Interface Methods

[See Also](#)

[SolidWorks.Interop.swinspectionAddIn Namespace](#) : IInspectionAddInMgr Interface

For a list of all members of this type, see [IInspectionAddInMgr members](#).

Public Methods

Name	Description
 AddCharacteristics	Adds characteristics for the specified annotations.
 AddInspectionMethod	Adds the specified inspection method to the list of inspection methods.
 AddOperation	Adds the specified operation to the list of operations.
 AddOrEditBalloons	Specifies settings for adding or modifying balloons in a drawing.
 AddVendor	Adds the specified vendor to the list of vendors.
 CreateInspectionProject	Creates an inspection project using the specified template and project data and balloons the model.
 CreateInspectionProjectData	Creates inspection project data.
 DeleteInspectionMethods	Deletes the specified inspection methods.
 DeleteOperations	Deletes the specified operations.
 DeleteVendors	Deletes the specified vendors.
 EditInspectionMethod	Edits the specified inspection method.
 EditInspectionProject	Edits the inspection project and re-balloons the model.
 GetBalloonSettings	Gets a balloon settings object.
 GetCharacteristicIDs	Gets the characteristic IDs.
 GetCharacteristicsData	Gets the specified characteristic data.
 GetInspectionMethods	Gets the list of inspection methods.
 GetInspectionProject	Gets an inspection project.
 GetInspectionProjectData	Gets the inspection project data object.
 GetOperations	Gets the list of operations.
 GetVendors	Gets the list of vendors.

	RemoveBalloons	Removes all balloons.
	SelectBalloons	Selects all balloons.

[Top](#)

See Also

[IInspectionAddinMgr Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

IInspectionAddinMgr Interface Members

[See Also](#) [Methods](#)

[SolidWorks.Interop.swinspectionAddIn Namespace](#) : IInspectionAddinMgr Interface

The following tables list the members exposed by [IInspectionAddinMgr](#).

Public Methods

Name	Description
	AddCharacteristics Adds characteristics for the specified annotations.
	AddInspectionMethod Adds the specified inspection method to the list of inspection methods.
	AddOperation Adds the specified operation to the list of operations.
	AddOrEditBalloons Specifies settings for adding or modifying balloons in a drawing.
	AddVendor Adds the specified vendor to the list of vendors.
	CreateInspectionProject Creates an inspection project using the specified template and project data and balloons the model.
	CreateInspectionProjectData Creates inspection project data.
	DeleteInspectionMethods Deletes the specified inspection methods.
	DeleteOperations Deletes the specified operations.
	DeleteVendors Deletes the specified vendors.
	EditInspectionMethod Edits the specified inspection method.
	EditInspectionProject Edits the inspection project and re-balloons the model.
	GetBalloonSettings Gets a balloon settings object.
	GetCharacteristicIDs Gets the characteristic IDs.
	GetCharacteristicsData Gets the specified characteristic data.
	GetInspectionMethods Gets the list of inspection methods.
	GetInspectionProject Gets an inspection project.
	GetInspectionProjectData Gets the inspection project data object.
	GetOperations Gets the list of operations.
	GetVendors Gets the list of vendors.
	RemoveBalloons Removes all balloons.
	SelectBalloons Selects all balloons.

[Top](#)

See Also

[IInspectionAddinMgr Interface](#)
[SolidWorks.Interop.swinspectionAddIn Namespace](#)

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

AddCharacteristics Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [IInspectionAddinMgr Interface](#) : AddCharacteristics Method (IInspectionAddinMgr)

Adds characteristics for the specified annotations.

 .NET Syntax

Visual Basic (Declaration)

```
Function AddCharacteristics( _  
    ByRef AnnotationsIn As System.Object _  
) As System.Object
```

Visual Basic (Usage) 

```
Dim instance As IInspectionAddinMgr  
Dim AnnotationsIn As System.Object  
Dim value As System.Object  
  
value = instance.AddCharacteristics(AnnotationsIn)
```

C#

```
System.object AddCharacteristics(  
    ref System.object AnnotationsIn  
)
```

C++/CLI

```
System.Object^ AddCharacteristics(  
& System.Object^% AnnotationsIn  
)
```

Parameters

AnnotationsIn
Array of annotations

Return Value

[ICharacteristicsData](#)

 Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

 Remarks

This method is valid only if [InspectionProjectData::Extraction](#) is set to [swiCharacteristicInfoExtraction_e.swiExtraction_Manual](#).

 See Also

[IInspectionAddinMgr Interface](#)
[InspectionAddinMgr Members](#)

 Availability

SOLIDWORKS Inspection API 2022 FCS

AddInspectionMethod Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddIn Namespace](#) > [InspectionAddinMgr Interface](#) : AddInspectionMethod Method (IInspectionAddinMgr)

Adds the specified inspection method to the list of inspection methods.

 .NET Syntax

Visual Basic (Declaration)

```
Function AddInspectionMethod(  
    ByVal MethodName As System.String _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim MethodName As System.String  
Dim value As System.Boolean  
  
value = instance.AddInspectionMethod(MethodName)
```

C#

```
System.bool AddInspectionMethod(  
    System.string MethodName  
)
```

C++/CLI

```
System.bool AddInspectionMethod(  
& System.String^ MethodName  
)
```

Parameters

MethodName
Name of inspection method

Return Value

True if inspection method successfully added, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

AddOperation Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionaddin Namespace](#) > [IInspectionAddinMgr Interface](#) : AddOperation Method (IInspectionAddinMgr)

Adds the specified operation to the list of operations.

.NET Syntax

Visual Basic (Declaration)

```
Function AddOperation(  
    ByVal Operation As System.String _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim Operation As System.String  
Dim value As System.Boolean
```

```
value = instance.AddOperation(Operation)
```

C#

```
System.bool AddOperation(  
    System.string Operation  
)
```

C++/CLI

```
System.bool AddOperation(  
& System.String^ Operation  
)
```

Parameters

Operation
Name of operation

Return Value

True if operation successfully added, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

AddOrEditBalloons Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : AddOrEditBalloons Method (IInspectionAddinMgr)

Specifies settings for adding or modifying balloons in a drawing.

.NET Syntax

Visual Basic (Declaration)

```
Function AddOrEditBalloons(  
    ByVal BalloonSettings As System.Object _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim BalloonSettings As System.Object  
Dim value As System.Boolean
```

```
value = instance.AddOrEditBalloons(BalloonSettings)
```

C#

```
System.bool AddOrEditBalloons(  
    System.object BalloonSettings  
)
```

C++/CLI

```
System.bool AddOrEditBalloons(  
& System.Object^ BalloonSettings  
)
```

Parameters

[BalloonSettings](#)
[IBalloonSettings](#)

Return Value

True if balloon settings successfully applied, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

Remarks

This method is valid only:

- for ballooned drawings.
- when IInspectionProjectData::Extraction is set to [swiCharacteristicInfoExtraction_e.swiExtraction_Manual](#).

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

AddVendor Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : AddVendor Method (IInspectionAddinMgr)

Adds the specified vendor to the list of vendors.

.NET Syntax

Visual Basic (Declaration)

```
Function AddVendor(  
    ByVal VendorName As System.String, _  
    ByVal VendorType As System.Integer _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim VendorName As System.String  
Dim VendorType As System.Integer  
Dim value As System.Boolean
```

```
value = instance.AddVendor(VendorName, VendorType)
```

C#

```
System.bool AddVendor(  
    System.string VendorName,  
    System.int VendorType  
)
```

C++/CLI

```
System.bool AddVendor(  
& System.String^ VendorName,  
& System.int VendorType  
)
```

Parameters

VendorName

Name of vendor

VendorType

Type of vendor as defined by [swiVendorsInspectionType_e](#)

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)

[InspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

CreateInspectionProject Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : CreateInspectionProject Method (IInspectionAddinMgr)

Creates an inspection project using the specified template and project data and balloons the model.

.NET Syntax

Visual Basic (Declaration)

```
Function CreateInspectionProject( _  
    ByVal InspectionProjectData As System.Object, _  
    ByVal DeleteOld As System.Boolean, _  
    ByRef ErrorCode As System.Integer _  
) As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim InspectionProjectData As System.Object  
Dim DeleteOld As System.Boolean  
Dim ErrorCode As System.Integer  
Dim value As System.Object
```

```
value = instance.CreateInspectionProject(InspectionProjectData, DeleteOld, ErrorCode)
```

C#

```
System.object CreateInspectionProject(  
    System.object InspectionProjectData,  
    System.bool DeleteOld,  
    out System.int ErrorCode  
)
```

C++/CLI

```
System.Object^ CreateInspectionProject(  
& System.Object^ InspectionProjectData,  
& System.bool DeleteOld,  
& [Out] System.int ErrorCode  
)
```

Parameters

InspectionProjectData

[IInspectionProjectData](#)

DeleteOld

True to delete the existing project and create a new one, false to get the existing project

ErrorCode

Error code as defined by [swiErrorCode_e](#)

Return Value

[IInspectionProject](#)

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)

[InspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

CreateInspectionProjectData Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : CreateInspectionProjectData Method (IInspectionAddinMgr)

Creates inspection project data.

.NET Syntax

Visual Basic (Declaration)

```
Function CreateInspectionProjectData( _  
    ByVal TemplatePathIn As System.String _  
) As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim TemplatePathIn As System.String  
Dim value As System.Object  
  
value = instance.CreateInspectionProjectData(TemplatePathIn)
```

C#

```
System.object CreateInspectionProjectData(  
    System.string TemplatePathIn  
)
```

C++/CLI

```
System.Object^ CreateInspectionProjectData(  
& System.String^ TemplatePathIn  
)
```

Parameters

TemplatePathIn

Full path name of inspection project template (see **Remarks**)

Return Value

[IInspectionProjectData](#)

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

Remarks

The templates are installed in c:\ProgramData\SOLIDWORKS\SOLIDWORKS Inspection 2022 Addin\Templates.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

DeleteInspectionMethods Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : DeleteInspectionMethods Method (IInspectionAddinMgr)

Deletes the specified inspection methods.

.NET Syntax

Visual Basic (Declaration)

```
Function DeleteInspectionMethods( _  
    ByRef MethodList As System.Object _  
) As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim MethodList As System.Object  
Dim value As System.Object  
  
value = instance.DeleteInspectionMethods(MethodList)
```

C#

```
System.object DeleteInspectionMethods(  
    ref System.object MethodList  
)
```

C++/CLI

```
System.Object^ DeleteInspectionMethods(  
& System.Object^% MethodList  
)
```

Parameters

MethodList
Array of inspection methods to delete

Return Value

Array of booleans indicating whether each inspection method is successfully deleted

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

DeleteOperations Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : DeleteOperations Method (IInspectionAddinMgr)

Deletes the specified operations.

.NET Syntax

Visual Basic (Declaration)

```
Function DeleteOperations( _  
    ByRef OperationList As System.Object _  
) As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim OperationList As System.Object  
Dim value As System.Object  
  
value = instance.DeleteOperations(OperationList)
```

C#

```
System.object DeleteOperations(  
    ref System.object OperationList  
)
```

C++/CLI

```
System.Object^ DeleteOperations(  
& System.Object^% OperationList  
)
```

Parameters

OperationList
Array of operations to delete

Return Value

Array of booleans indicating whether each operation is successfully deleted

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

DeleteVendors Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : DeleteVendors Method (IInspectionAddinMgr)

Deletes the specified vendors.

.NET Syntax

Visual Basic (Declaration)

```
Function DeleteVendors( _  
    ByRef VendorList As System.Object _  
) As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim VendorList As System.Object  
Dim value As System.Object  
  
value = instance.DeleteVendors(VendorList)
```

C#

```
System.object DeleteVendors(  
    ref System.object VendorList  
)
```

C++/CLI

```
System.Object^ DeleteVendors(  
& System.Object^% VendorList  
)
```

Parameters

VendorList
Array of vendors to delete

Return Value

Array of booleans indicating whether each vendor is successfully deleted

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

EditInspectionMethod Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : EditInspectionMethod Method (IInspectionAddinMgr)

Edits the specified inspection method.

.NET Syntax

Visual Basic (Declaration)

```
Function EditInspectionMethod( _  
    ByVal MethodID As System.String, _  
    ByVal MethodName As System.String _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr
Dim MethodID As System.String
Dim MethodName As System.String
Dim value As System.Boolean

value = instance.EditInspectionMethod(MethodID, MethodName)
```

C#

```
System.bool EditInspectionMethod(
    System.string MethodID,
    System.string MethodName
)
```

C++/CLI

```
System.bool EditInspectionMethod(
    & System.String^ MethodID,
    & System.String^ MethodName
)
```

Parameters

MethodID
ID of inspection method
MethodName
Name of inspection method

Return Value

True if inspection method successfully modified, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

EditInspectionProject Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : EditInspectionProject Method (IInspectionAddinMgr)

Edits the inspection project and re-balloons the model.

.NET Syntax

Visual Basic (Declaration)

```
Function EditInspectionProject( _
    ByVal InspectionProjectData As System.Object _
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr
Dim InspectionProjectData As System.Object
Dim value As System.Boolean

value = instance.EditInspectionProject(InspectionProjectData)
```

C#

```
System.bool EditInspectionProject(  
    System.object InspectionProjectData  
)
```

C++/CLI

```
System.bool EditInspectionProject(  
& System.Object^ InspectionProjectData  
)
```

Parameters

[InspectionProjectData](#)
[InspectionProjectData](#)

Return Value

True if inspection project successfully modified, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[InspectionAddinMgr Interface](#)
[InspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

GetBalloonSettings Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [InspectionAddinMgr Interface](#) : GetBalloonSettings Method (IInspectionAddinMgr)

Gets a balloon settings object.

.NET Syntax

Visual Basic (Declaration)

```
Function GetBalloonSettings() As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim value As System.Object
```

```
value = instance.GetBalloonSettings()
```

C#

```
System.object GetBalloonSettings()
```

C++/CLI

```
System.Object^ GetBalloonSettings();
```

Return Value

[IBalloonSettings](#)

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

GetCharacteristicIDs Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : GetCharacteristicIDs Method (IInspectionAddinMgr)

Gets the characteristic IDs.

.NET Syntax

Visual Basic (Declaration)

```
Function GetCharacteristicIDs() As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim value As System.Object  
  
value = instance.GetCharacteristicIDs()
```

C#

```
System.object GetCharacteristicIDs()
```

C++/CLI

```
System.Object^ GetCharacteristicIDs();
```

Return Value

Array of characteristic IDs

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

GetCharacteristicsData Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : GetCharacteristicsData Method (IInspectionAddinMgr)

Gets the specified characteristic data.

.NET Syntax

Visual Basic (Declaration)

```
Function GetCharacteristicsData( _  
    ByVal CharId As System.Double _  
    ) As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim CharId As System.Double  
Dim value As System.Object  
  
value = instance.GetCharacteristicsData(CharId)
```

C#

```
System.object GetCharacteristicsData(  
    System.double CharId  
)
```

C++/CLI

```
System.Object^ GetCharacteristicsData(  
& System.double CharId  
)
```

Parameters

CharId
ID of characteristic to retrieve

Return Value

[ICharacteristicsData](#)

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

GetInspectionMethods Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : GetInspectionMethods Method (IInspectionAddinMgr)

Gets the list of inspection methods.

.NET Syntax

Visual Basic (Declaration)

```
Function GetInspectionMethods( _  
    ByRef MethodList As System.Object, _  
    ByRef MethodIDs As System.Object _  
    ) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim MethodList As System.Object  
Dim MethodIDs As System.Object
```

```
Dim value As System.Boolean
```

```
value = instance.GetInspectionMethods(MethodList, MethodIDs)
```

C#

```
System.bool GetInspectionMethods(  
    out System.object MethodList,  
    out System.object MethodIDs  
)
```

C++/CLI

```
System.bool GetInspectionMethods(  
& [Out] System.Object^ MethodList,  
& [Out] System.Object^ MethodIDs  
)
```

Parameters

MethodList

Array of inspection methods

MethodIDs

Array of inspection method IDs

Return Value

True if inspection methods successfully retrieved, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)

[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

GetInspectionProject Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : GetInspectionProject Method (IInspectionAddinMgr)

Gets an inspection project.

.NET Syntax

Visual Basic (Declaration)

```
Function GetInspectionProject() As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim value As System.Object
```

```
value = instance.GetInspectionProject()
```

C#

```
System.object GetInspectionProject()
```

C++/CLI

```
System.Object^ GetInspectionProject();
```

Return Value

[IInspectionProject](#)

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

GetInspectionProjectData Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : GetInspectionProjectData Method (IInspectionAddinMgr)

Gets the inspection project data object.

.NET Syntax

Visual Basic (Declaration)

```
Function GetInspectionProjectData() As System.Object
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim value As System.Object  
  
value = instance.GetInspectionProjectData()
```

C#

```
System.object GetInspectionProjectData()
```

C++/CLI

```
System.Object^ GetInspectionProjectData();
```

Return Value

[IInspectionProjectData](#)

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments on this topic.](#)

GetOperations Method (IInspectionAddinMgr)

[See Also](#)



Gets the list of operations.

.NET Syntax

Visual Basic (Declaration)

```
Function GetOperations( _  
    ByRef OperationList As System.Object, _  
    ByRef OperationIDs As System.Object _  
    ) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddInMgr  
Dim OperationList As System.Object  
Dim OperationIDs As System.Object  
Dim value As System.Boolean  
  
value = instance.GetOperations(OperationList, OperationIDs)
```

C#

```
System.bool GetOperations(  
    out System.object OperationList,  
    out System.object OperationIDs  
)
```

C++/CLI

```
System.bool GetOperations(  
& [Out] System.Object^ OperationList,  
& [Out] System.Object^ OperationIDs  
)
```

Parameters

OperationList
Array of operations
OperationIDs
Array of operation IDs

Return Value

True if operations successfully retrieved, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddInMgr](#) methods.

See Also

[IInspectionAddInMgr Interface](#)
[IInspectionAddInMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

GetVendors Method (IInspectionAddInMgr)

[See Also](#)



Gets the list of vendors.

.NET Syntax

Visual Basic (Declaration)

```
Function GetVendors( _  
    ByRef VendorList As System.Object _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim VendorList As System.Object  
Dim value As System.Boolean  
  
value = instance.GetVendors(VendorList)
```

C#

```
System.bool GetVendors(  
    out System.object VendorList  
)
```

C++/CLI

```
System.bool GetVendors(  
& [Out] System.Object^ VendorList  
)
```

Parameters

VendorList
Array of vendors

Return Value

True if vendors successfully retrieved, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[IInspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

RemoveBalloons Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [IInspectionAddinMgr Interface](#) : RemoveBalloons Method (IInspectionAddinMgr)

Removes all balloons.

.NET Syntax

Visual Basic (Declaration)

```
Function RemoveBalloons() As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim value As System.Boolean  
  
value = instance.RemoveBalloons()
```

C#

```
System.bool RemoveBalloons()
```

C++/CLI

```
System.bool RemoveBalloons();
```

Return Value

True if all balloons removed, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[InspectionAddinMgr Members](#)

Availability

SOLIDWORKS Inspection API 2022 FCS

SOLIDWORKS Inspection API Help

[Send comments](#) on this topic.

SelectBalloons Method (IInspectionAddinMgr)

[See Also](#)



[SolidWorks.Interop.swinspectionAddin Namespace](#) > [InspectionAddinMgr Interface](#) : SelectBalloons Method (IInspectionAddinMgr)

Selects all balloons.

.NET Syntax

Visual Basic (Declaration)

```
Function SelectBalloons() As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IInspectionAddinMgr  
Dim value As System.Boolean  
  
value = instance.SelectBalloons()
```

C#

```
System.bool SelectBalloons()
```

C++/CLI

```
System.bool SelectBalloons();
```

Return Value

True if all balloons selected, false if not

Visual Basic for Applications (VBA) Syntax

See [InspectionAddinMgr](#) methods.

See Also

[IInspectionAddinMgr Interface](#)
[InspectionAddinMgr Members](#)

Availability

