

SOLIDWORKS Inspection Add-in API (VB6 COM)

— Examples (1/1): Getting Started—

SWInspectionAddin_references

SOLIDWORKS API Documentation (converted from CHM)

Getting Started (Topic)

Inspection API Help - Visual Basic for Applications (VBA)

Getting Started

[Send Feedback](#)

Introduction (Topic)

Inspection API Help - Visual Basic for Applications (VBA)

Introduction

[Send Feedback](#)

Overview (Topic)

Inspection API Help - Visual Basic for Applications (VBA)

Overview

[Send Feedback](#)

SWInspectionAddin_gettingstarted (Topic)

SWInspectionAddinActiveX DLL

Getting Started

SWInspectionAddin_P (Topic)

SWInspectionAddinActiveX.DLL

Project Overview



Classes

Class Module	Description
BalloonSettings	
CharacteristicsData	
InspectionAddinMgr	
InspectionProject	
InspectionProjectData	

Public Enumerations

Enumeration	Description
swiBalloonSettingLayer_e	
swiBalloonSettingsFit_e	
swiBalloonSettingsOffsetTypes_e	
swiBalloonSettingsShape_e	
swiCharacteristicClassification_e	
swiCharacteristicInfoExtraction_e	
swiCharacteristicInfoSort_e	
swiCharacteristicSubType_e	
swiErrorCode_e	
swiSamplingLevel_e	
swiSamplingType_e	
swiVendorsInspectionType_e	

SWInspectionAddin_references (Topic)

SWInspectionAddinActiveX DLL

References

