## **INA2321 amp Parts Tray (passives)**

Resistors – all 0603 1%:
1M: R5,6
100K: R7,8
3k9: R12,9
22k: R10,11,13,14
1k: R4,2
330k: R1,3
Caps:
4x 100p @ inputs
3x10n: @ inputs and C25
1μFx5r0603 C13,14,7,17
100n0603: C4,5,26,11,15
10μ0805: C27

1nF: C6,12