

s224c Inspection Report

Prepared for:

53B Remiger Road Puhoi

Inspector Name: Hamish McLachlan

Application Number: SUB60315119-A

Document Sign-off

Revision	Report Issue Date	Job Reference	Status	Author/Editor	Authorised by
1	23/05/25	J8237	Final	Hamish McLachlan	Will Michell

Contents

1. Introduction 4
1.1. Consent Conditions 4
1.2. Applicant Details 4
2. Inspection results 5
2.1. Site Assessment 5
2.2. Photographic Evidence Supplied During Inspection 5
3. Summary of situation at Inspection 8
4. Conclusion 8
APPENDIX A 9
Report Limitations 9
APPENDIX B 10
Site Map 10

List of Figures

Figure 1. Seven-wire post and batten fence protecting covenant area CY. 5
Figure 2. Seven-wire post and batten fence protecting covenant area CO. 6
Figure 3. Seven-wire post and batten fence protecting covenant area CS. 6
Figure 4. Seven-wire post and batten fence protecting covenant area CS. 7
Figure 5. Map provided to NZBSL for inspection. 10

1. INTRODUCTION

This report[1], prepared by New Zealand Biosecurity Services Limited (NZBSL), on behalf of Auckland Council for Ray Nicklin presents completion of an inspection and recommendations against consent conditions for SUBDIVISION at 53B Remiger Road.

Specifically, this plan details inspection results for the conditions stated in section 1.1 following Auckland Council resource consent number SUB60315119-A:

1.1. Consent Conditions

The following conditions were evaluated in accordance with Auckland Council's consent condition document:

5a. Stock Proof Fence

1.2. Applicant Details

Ray Nicklin was met onsite to discuss how the conditions had been met. The covenant areas CP- CV, CO, CX, CZ and CY were assessed as per the consent condition document.

[1] This report is subject to the Report Limitations provided in Appendix A.

2. INSPECTION RESULTS

2.1. Site Assessment

An inspection was completed on 23/05/25The Inspector's comments following the site visit are below.

47m) Stock Proof Fence

A permanent ungated, continuous stock-proof fence has been installed in the form of a seven-wire post and batten fence around the perimeter of the Riparian Planting areas CO, CX, CY & CZ and bush areas CP-CV.

2.2. Photographic Evidence Supplied During Inspection



Figure 1. Seven-wire post and batten fence protecting covenant area CY.



Figure 2. Seven-wire post and batten fence protecting covenant area CO.



Figure 3. Seven-wire post and batten fence protecting covenant area CS.



Figure 4. Seven-wire post and batten fence protecting covenant area CS.

3. SUMMARY OF SITUATION AT INSPECTION

23/05/25

The applicable conditions have been assessed and the current standing of each condition is as below:

47m) Stock Proof Fence

The applicant has met the condition requirements.

4. CONCLUSION

A site inspection has been completed and follow up actions by NZBSL and the client are recorded in this report. The situation of the consent conditions at the date of inspection are presented to Auckland Council for decision-making.

APPENDIX A

Report Limitations

This Report/Document has been provided by New Zealand Biosecurity Services (NZBSL) subject to the following limitations:

i) This Report/Document has been prepared for the particular purpose outlined in NZBSL's contracted obligations with Auckland Regional Council and no responsibility is accepted for the use of this Report/Document, in whole or in part, in other contexts or for any other purpose.

ii) The scope and the period of NZBSL's services are as per initial agreement and are subject to restrictions and limitations. NZBSL did not perform a complete assessment of all possible conditions or circumstances that may exist at the site referenced in the Report/Document. If a service is not expressly indicated, do not assume it has been provided. If a matter is not addressed, do not assume that any determination has been made by NZBSL in regard to it.

iii) Conditions may exist which were undetectable given the limited nature of the enquiry NZBSL was retained to undertake with respect to the site. Variations in conditions may occur between investigatory locations, and there may be special conditions pertaining to the site which have not been revealed by the investigation and which have not therefore been taken into account in the Report/Document. Accordingly, if information in addition to that contained in this report is sought, additional studies and actions may be required.

iv) The passage of time affects the information and assessment provided in this Report/Document. NZBSL's opinions/recommendations are based upon information that existed at the time of the production of the Report/Document. The Services provided allowed NZBSL to form no more than an opinion of the actual conditions of the site at the time the site was visited and cannot be used to assess the effect of any subsequent changes in the quality of the site, or its surroundings, or any laws or regulations.

v) Any assessments, recommendations and advice made in this Report/Document are based on the conditions indicated from published sources and the investigation described. No warranty is included, either express or implied, that the actual conditions will conform exactly to the assessments contained in this Report/Document.

vi) Where data supplied by the client or other external sources, including previous site investigation data, have been used, it has been assumed that the information is correct unless otherwise stated. No responsibility is accepted by NZBSL for incomplete or inaccurate data supplied by others.

vii) This Report/Document is provided for sole use by the Client/Auckland Council and is confidential to it. No responsibility whatsoever for the contents of this Report/Document will be accepted to any person other than the Client/Auckland Council. Any use which a third party makes of this Report/Document, or any reliance on or decisions to be made based on it, is the responsibility of such third parties. NZBSL accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this Report/Document.

APPENDIX B

Site Map




Figure 5. Map provided to NZBSL for inspection.