Sun & Shield Power Solutions

43 Oshola Street, Ifako-Ijaiye, Lagos State
Tel: +2348066190685 | Sunshieldpowersolutions@gmail.com

CUSTOMER SERVICE REPORT

SASCSR-000004

2026-10-26 COMPLETE

PROTOTYPE LAYOUT · LOGO AND SIGNATURE ARTWORK ARE PLACEHOLDERS, TO BE REPLACED WITH THE ORIGINAL ASSETS

01 CLIENT INFORMATION

TATA International, Nigeria

CORPORATE ADDRESS	Plot C89, Amuwo Odofin Industrial Layout, Along Oshodi – Apapa Express Way, Lagos, Nigeria
CALL TYPE	Preventive Maintenance
SERVICE BASIS	Paid Service
SERVICE DATE	2026-10-26
SYSTEM STATE	OPERATIONAL

02 EQUIPMENT INFORMATION

MAKE & MODEL
Cummins
NT-855-G6

RATED CAPACITY
350 kVA

EQUIPMENT TYPE
Generator

SERIAL NO.	-
ENGINE NO.	25598493
SITE / EQUIPMENT LOCATION	Plot C89, Amuwo Odofin Industrial Layout, Along Oshodi-Mile 2 Expressway, Lagos

03 OPERATIONAL READINGS

GEN. VOLTAGE (V)	FREQUENCY (HZ)	BATTERY / ALT. (VDC)	TEMPERATURE (°C)	PRESSURE	ENGINE HOURS
392 V	50 Hz	27.3 V	74 °C	704 kPa	9329.4

04 PROBLEM REPORTED

Generator recommended for routine service because it had exceeded 250 operating hours since the service interval.

05 SERVICE RENDERED

Replaced fuel filter FS1212, oil filter LF9009, water filter WF2074, and 50 litres of engine oil. Tested the generator after servicing.

06 OBSERVATIONS & DEFECTS FOUND

The diesel tank has no air valve. Staff fold the fuel hose to stop fuel flow when required. This gradually damages and deforms the hose, restricting free fuel flow.

07 ENGINEER'S REMARKS

The generator ran smoothly during testing at 1500 RPM. No oil leaks, fuel leaks, unusual smoke, or other issues were observed. Install an air valve on the diesel tank.

08 PARTS & MATERIALS SCHEDULE

4 ITEMS

01	02	03	04
Fuel Filter FS1212	Oil Filter LF9009	Water Filter WF2074	Engine Oil
QUANTITY 2	QUANTITY 1	QUANTITY 1	QUANTITY 50 LITRES

09 SIGN-OFF

SERVICE ENGINEER

SIGNATURE

FULL NAME: JAIYEOLA MONDAY
DESIGNATION: Technical director
DATE:

CLIENT REPRESENTATIVE

SIGNATURE

FULL NAME:
DESIGNATION:
DATE: