



SUN & SHIELD
POWER
SOLUTIONS

Generator Sales
Maintenance
Installation
Rental
Facility Mgmt

SERVICE
REPORT

Sasi-6347ty6v-B169

43, Oshola Street
Ifako Ijaiye, Lagos
08066190685

REPORT DATE
Feb 28, 2026

CUSTOMER
Inspire Sports Academy

LOCATION
Oshodi, Lagos

CUSTOMER INFORMATION

FULL ADDRESS

No 1, Old Nitel Road, Oshodi, Lagos State, Nigeria

NATURE OF PROBLEM

Reported Issue: Genset failure investigated.
Findings: Control module failure detected.
Recommendation: Replace control module.

EQUIPMENT SPECIFICATIONS

TYPE	MAKE	MODEL	CAPACITY
Generator	Kirloskar	2R1040	20 KVA
SERIAL NUMBER / EQUIPMENT LOCATION			
2H.9275/2120092		No 1, Old Nitel Road, Oshodi	

OPERATIONAL READINGS

Voltage (V)	Frequency (Hz)	Battery (V)	Temp (°C)	Pressure (bar)	Running Hours

PARTS USED

Control Module

SERVICE TIMELINE

SERVICE START	SERVICE END
Feb 28, 2026	Feb 28, 2026

SERVICE RENDERED & STATUS

WORK PERFORMED

Replaced control module. Tested genset for proper operation and verified functionality across all load conditions.

ENGINEER'S REMARKS

SERVICE STATUS

- ☒ Complete
☐ Incomplete
☐ Pending Spares
☐ Under Observation
☐ Temp Solution

CUSTOMER ACKNOWLEDGMENT

CUSTOMER REMARKS

AUTHORIZED SIGNATURE

Sign here

PRINT NAME

