
Ejector

Material: 4140 steel, hardened.

Construction: Mill, or filed from stock, pins shown can be replaced by slotting the receiver and welding in place, although harder to position



The ejector is positioned central with the magazine apeture of the receiver tube as shown. Construction can vary, here an ejector supported by two pins through the receiver tube is welded in place.

